

## Defect Details

<b>NC No.</b>	7000936274
<b>NC Date</b>	10/08/2023
<b>NC Submission Date</b>	
<b>Part No.</b>	520AE00300
<b>Part Name</b>	CORE PLATE 3W 4S
<b>Supplier Name &amp; Code</b>	100959-AAR CEE ENGINEERING WORKS UNIT
<b>ETL Plant</b>	1132-ETL K-226/1 TRANSMISSION
<b>Defect Details</b>	FLATNESS NOT OK.-flatness obs 0.30 against 0.10 mm

## 1. Problem Description

<b>Defect Description</b>	3W4S Core Plate Not qualify to gap gauge (Flatness found oversize up to 0.3 mm against 0.1 mm)
<b>Detection Stage</b>	Receipt
<b>Problem Severity</b>	Function
<b>NG Quantity</b>	10000
<b>Is Defect Repeatative?</b>	Yes
<b>Defect Sketch / Photo</b>	

## Supplier Communication Details

<b>Quality Head Email ID</b>	qc@aarceeengg.com
<b>Plant Head/CEO Email ID</b>	planthead.diecasting@aarceeengg.com
<b>MD Email ID</b>	vaibhav.arora@aarceeengg.com

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	16000	0	0	7000	0	23000
<b>Check Qty</b>	16000	0	0	7000	0	23000
<b>NG Qty</b>	1200	0	0	55	0	1255

## Action taken on NG part

<b>Scrap</b>	0
<b>Rework</b>	1255
<b>Under Deviation</b>	0

## Containment Action

Material segregated at the customer end(ETL end) & our end (AAR CEE end)NG parts to be re-shot Blasting

## 3. Process Flow

**Process Flow Description**

10.Receipt of raw material 20.Storage of raw material 30.Holding cum melting 40. PDC stage 50.Trimming process 60.Shot Blasting 70. Barrelling process 80.Sound Testing 90.stress reliving 100.Final inspection 110.Storage & Dispatch

**4. Process Details**

<b>Process / Operation</b>	60.Shot blasting & 100. Final inspection
<b>Outsource</b>	No
<b>Machine / Cell</b>	Shot blasting machine
<b>Machine / Cell No.</b>	SBM-02

**5. Problem Analysis**

Type	Possible Cause	Fact Verification	Jud
Method	Improper shot size used at shot blasting	Obsed SS 0.30 mm shot	O
Man	skipped at final inspection	ok limit sample not displayed at final inspection table	X
Method	Improper stress reliving process	Checked and found fixture flatness found up to 0.35 mm	X
Method	Improper cycle time at shot blasting	Found ok ,6 minutes against 5~7 minutes	O

**6. Inspection Method Analysis (Current)**

<b>Inspection Method</b>	Instrument
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	Sampling
<b>Sampling</b>	No
<b>Sample Size</b>	5 pcs/lot

**7. Root Cause Analysis (Occurance)**

<b>Why 1</b>	FLATNESS NOT OK.-flatness obs 0.30 against 0.10
<b>Why 2</b>	shot blasting is not done as per defined frequency.
<b>Why 3</b>	process parameter monitoring not done.
<b>Why 4</b>	lack of awareness of operator
<b>Why 5</b>	
<b>Root Cause (Occurance)</b>	process parameter monitoring not done.

**Root Cause Analysis (Outflow)**

<b>Why 1</b>	FLATNESS NOT OK.-flatness obs 0.30 against 0.10
<b>Why 2</b>	NG pieces were skipped by final inspection.
<b>Why 3</b>	limit sample not displayed in final inspection area.
<b>Why 4</b>	
<b>Why 5</b>	
<b>Root Cause (Outflow)</b>	limit sample not displayed in final inspection area.

## 8. Countermeasure ( Occurrence , Outflow & System side Actions )

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Occurance	QC inspection given to the tanning	Mukesh	01/09/2023	01/09/2023	Completed
Outflow	OK LIMIT SAMPLE DISPLAY AT FINAL INSPECTION AREA	MUKESH	03/09/2023	01/09/2023	Completed
Occurance	Fixture corrected	Ajay Malik	20/10/2023	20/10/2023	Completed
Occurance	Heating Fixture validation plan made and adhere for	Ajay Malik	23/10/2023	23/10/2023	Completed
Outflow	Standard operating procedure made and adhere for gap gauge verification & handling	Ajay Malik	23/10/2023	23/10/2023	Completed
Outflow	Standard operating procedure made and adhere for gap gauge verification & handling	Ajay Malik	23/10/2023	23/10/2023	Completed

## 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	No
<b>Change Details</b>	no change
<b>Inspection Method</b>	Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	10 pcs 1 h

## 10. Evidence of Countermeasure

<b>Occurance (Before)</b>	FORMAT AVAILABLE BUT NOT UPDATED <a href="#">524_Occurance_Before.pdf</a>
<b>Occurance (After)</b>	GIVEN TANNING AND RECORDED STARTED <a href="#">524_Occurance_After.pdf</a>
<b>Outflow (Before)</b>	LIMIT SAMPLE NOT DISPLAYED <a href="#">524_Outflow_Before.jpg</a>
<b>Outflow (After)</b>	LIMIT SAMPLE DISPLAY <a href="#">524_Outflow_After.jpg</a>

## 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	No
<b>Applicable Machine / Model / Plant</b>	NO

## 12. Document Review

<b>Documents</b>	WISOP
<b>Specify Other Document</b>	NO

### 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	10000
<b>Reason for submission</b>	Repeated Occurrence at ETL end -Gap Inspection activity need to strengthen