

## Defect Details

<b>NC No.</b>	7000939452
<b>NC Date</b>	23/08/2023
<b>NC Submission Date</b>	
<b>Part No.</b>	C3CE00201B
<b>Part Name</b>	CLUTCH SHAFT ASSLY
<b>Supplier Name &amp; Code</b>	100264-SAI INDUSTRIES
<b>ETL Plant</b>	1132-ETL K-226/1 TRANSMISSION
<b>Defect Details</b>	CRACKS-flairing dia obs 4.26 & flange cracked

## 1. Problem Description

<b>Defect Description</b>	Crack observed at flaring dia -During Riveting
<b>Detection Stage</b>	Inprocess
<b>Problem Severity</b>	Function
<b>NG Quantity</b>	2
<b>Is Defect Repeatative?</b>	No
<b>Defect Sketch / Photo</b>	

## Supplier Communication Details

<b>Quality Head Email ID</b>	info@sai-industries.com
<b>Plant Head/CEO Email ID</b>	info@sai-industries.com
<b>MD Email ID</b>	umesh.honap@gmail.com

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	200	480	0	280	0	960
<b>Check Qty</b>	200	480	0	280	0	960
<b>NG Qty</b>	2	0	0	0	0	2

## Action taken on NG part

<b>Scrap</b>	2
<b>Rework</b>	0
<b>Under Deviation</b>	0

## Containment Action

In ETL stock verified 200 Nos. found 2 nos cracks in Assly line. In A`Bad Warehouse stock verified 480 Nos.found no any cracks . InSai Inhouse stock verified 288 Nos.found no anycracks . All riveting parameter checked found ok except rivet height. Clutch Flange Bend/Warpage above 0.30mm. CNC Facing operation all parameters found ok.

### 3. Process Flow

Process Flow Description
Rivetting

### 4. Process Details

<b>Process / Operation</b>	Rivetting
<b>Outsource</b>	No
<b>Machine / Cell</b>	Assly
<b>Machine / Cell No.</b>	Rivetting

### 5. Problem Analysis

Type	Possible Cause	Fact Verification	Jud
Material	Clutch Flange bend/warpage above 0.30mm or may be internal crack in casting.	Parallerity not ok observed.	O

### 6. Inspection Method Analysis (Current)

<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	Dial & Fixture
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100%

### 7. Root Cause Analysis (Occurance)

<b>Why 1</b>	Why 1:-CRACKS-flairing dia obs 4.26 & flange cracked
<b>Why 2</b>	Why 2:- Rivetting operation, Rivet height uneven or excess.
<b>Why 3</b>	Why 3:- Clutch Flange parallerity above 0.30mm.
<b>Why 4</b>	Why 4:- Clutch Flange bend/warpage above 0.30mm or may be internal crack in casting. Already informed to ETL time to time refer mail and rejection returned also.
<b>Why 5</b>	
<b>Root Cause (Occurance)</b>	Clutch Flange bend/warpage above 0.30mm or may be internal crack in casting. Already informed to ETL time to time refer mail and rejection returned also.

### Root Cause Analysis (Outflow)

<b>Why 1</b>	Why 1:-CRACKS-flairing dia obs 4.26 & flange cracked
<b>Why 2</b>	Why 2:- Not proper adreesed in 100% visual inspection.
<b>Why 3</b>	Why 3:- Not kept crack assly in rejection bin.
<b>Why 4</b>	why 4:- Cracks assly may be mix up in ok assly.
<b>Why 5</b>	
<b>Root Cause (Outflow)</b>	Cracks assly may be mix up in ok assly.

## 8. Countermeasure ( Occurrence , Outflow & System side Actions )

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Occurance	1) ETL will ensure defect free(without bend/warpage)clutch flange supplied to Sai. 2) Received all clutch flange segrrigate for parallerity and Only Ok flange used for assly. 3) For crack free parts rivet height to be increased by 0.20mm.i.e.within 0.70mm and ETL will give approval for increase the the same.	ETL and SAI	02/09/2023	02/10/2023	Completed
Outflow	2) After 100% visual inspection marked Blue dot as identification.	SAI	01/09/2023	01/09/2023	Completed
Outflow	1) Display Ok and Not ok photo in final/visual inspection stage.	SAI	01/09/2023		Completed

## 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	Yes
<b>Change Details</b>	Firewall inspection started.
<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	Visual
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100%

## 10. Evidance of Countermeasure

<b>Occurance (Before)</b>	No Parameter in SOP <a href="#">531_Occurance_Before.pdf</a>
<b>Occurance (After)</b>	Add parameter in SOP <a href="#">531_Occurance_After.pdf</a>
<b>Outflow (Before)</b>	Not Display Photo <a href="#">531_Outflow_Before.pdf</a>
<b>Outflow (After)</b>	Display Photo <a href="#">531_Outflow_After.pdf</a>

## 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	Yes
<b>Applicable Machine / Model / Plant</b>	Clutch Shaft Assly BS III and BS VI PVPL

## 12. Document Review

<b>Documents</b>	WISOP
<b>Specify Other Document</b>	No

## 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	1000
<b>Reason for submission</b>	OK