

Defect Details

| | |
|---------------------------------|---------------------------------------|
| NC No. | 7001005905 |
| NC Date | 15/04/2024 |
| NC Submission Date | |
| Part No. | 53BKZ00102 |
| Part Name | RUBBER BUSH |
| Supplier Name & Code | 101023-FORES ELASTOMECH INDIA PVT. LT |
| ETL Plant | 1136-ETL Suspension Sanand |
| Defect Details | DIMETER UNDERSIZE-Outer dia undersize |

1. Problem Description

| | |
|-------------------------------|---|
| Defect Description | OD found undersize 23.637 mm against specification 24.3+0.3/-0.3 mm |
| Detection Stage | Customer End |
| Problem Severity | Fitment |
| NG Quantity | 10000 |
| Is Defect Repeatative? | No |
| Defect Sketch / Photo | |

Supplier Communication Details

| | |
|--------------------------------|-------------------------------|
| Quality Head Email ID | malani.pritam@foresgroup.com |
| Plant Head/CEO Email ID | singh.barinder@foresgroup.com |
| MD Email ID | swamy.pj@foresgroup.com |

2. Stock Details & action taken for NG parts

| Location | ETL End | Warehouse | Transit | Supplier FG | Supplier WIP | Total |
|------------------|---------|-----------|---------|-------------|--------------|-------|
| Total Qty | 17500 | 0 | 7500 | 0 | 0 | 25000 |
| Check Qty | 17500 | 0 | 7500 | 0 | 0 | 25000 |
| NG Qty | 20 | 0 | 0 | 0 | 0 | 20 |

Action taken on NG part

| | |
|------------------------|----|
| Scrap | 20 |
| Rework | 0 |
| Under Deviation | 0 |

Containment Action

100 % inspection by ring gauge at final Inspection & dot marking provided on parts 100%

3. Process Flow

Process Flow Description

Inward material- Mixing - Moulding- Buffing process- Final Inspection

4. Process Details

| | |
|----------------------------|-----------------|
| Process / Operation | Buffing process |
| Outsource | No |
| Machine / Cell | Machine no-01 |
| Machine / Cell No. | 01 |

5. Problem Analysis

| Type | Possible Cause | Fact Verification | Jud |
|--------|------------------------------|--------------------------------|-----|
| Tool | Tool design not okay | OD maintained in Tool is 24.20 | X |
| Method | Inspection on sampling basis | Skipped from inspection | X |

6. Inspection Method Analysis (Current)

| | |
|--|-------|
| Inspection Method | Gauge |
| Other Inspection Method | |
| Check Point at Final Inspection | Yes |
| Checking Freq. | 100% |
| Sampling | No |
| Sample Size | 100 % |

7. Root Cause Analysis (Occurance)

| | |
|-------------------------------|---|
| Why 1 | OD undersize |
| Why 2 | OD undersize on parting line |
| Why 3 | OD undersize due to buffing process at parting line |
| Why 4 | OD dimension got undersize due to excess buffing process. |
| Why 5 | |
| Root Cause (Occurance) | OD dimension got undersize due to excess buffing process. |

Root Cause Analysis (Outflow)

| | |
|-----------------------------|----------------------------|
| Why 1 | OD undersize |
| Why 2 | Skipped from Inspection |
| Why 3 | Inspection as per sampling |
| Why 4 | |
| Why 5 | |
| Root Cause (Outflow) | Inspection as per sampling |

8. Countermeasure (Occurrence , Outflow & System side Actions)

| Type | Countermeasure Details | Responsibility | Target Date | Actual Date | Status |
|------|------------------------|----------------|-------------|-------------|--------|
|------|------------------------|----------------|-------------|-------------|--------|

| | | | | | |
|-----------|---|--------------------------|------------|------------|-----------|
| Occurance | 1)Training Given to buffing operator 2)OPL display at work station 3)Work Instruction updated 4)Frequency of inspection increases from 2 hourly to 1 hourly | Buffing process InCharge | 16/04/2024 | 16/04/2024 | Completed |
| Occurance | Dimension of OD in Mould will be maintained 24.5 mm | Fores | 26/04/2024 | 26/04/2024 | Completed |
| Outflow | 1)Training given to inspector 2)Q Alert displayed 3)Defective sample & limit sample to displayed 4)Dot marking started after inspection 5)OD inspection by Ring gauge 100 % | Final Inspection | 16/04/2024 | 16/04/2024 | Completed |

9. Inspection Method After Customer Complaint

| | |
|--|--------------------------|
| Change In Inspection System | Yes |
| Change Details | Inspection by ring gauge |
| Inspection Method | Gauge |
| Other Inspection Method | |
| Check Point at Final Inspection | Yes |
| Checking Freq. | 100% |
| Sampling | No |
| Sample Size | 100 % |

10. Evidence of Countermeasure

| | |
|---------------------------|--|
| Occurance (Before) | Excess buffing 749_Occurance_Before.jpg |
| Occurance (After) | Training record of buffing operator 749_Occurance_After.pdf |
| Outflow (Before) | Inspection on sampling 749_Outflow_Before.jpg |
| Outflow (After) | Training record of Final inspector 749_Outflow_After.pdf |

11. Horizontal Deployment

| | |
|---|----|
| Horizontal Deployment Required | No |
| Applicable Machine / Model / Plant | NA |

12. Document Review

| | |
|-------------------------------|--------------------|
| Documents | ControlPlan, PFMEA |
| Specify Other Document | Work instruction |

13. Effectiveness Of Action

| | |
|------------------------------|---|
| Reviewed Quantity | 5 |
| Reason for submission | Tool OD modified from 24.2 to higher tolerance side 24.5 mm in die . No Ng parts found in fresh upcoming lots . |

