

## Defect Details

<b>NC No.</b>	7001010243
<b>NC Date</b>	01/05/2024
<b>NC Submission Date</b>	
<b>Part No.</b>	520KT00102
<b>Part Name</b>	ROD BUSH
<b>Supplier Name &amp; Code</b>	100177-SPECIALITY SINTERED PRODUCTS P
<b>ETL Plant</b>	1136-ETL Suspension Sanand
<b>Defect Details</b>	PARALITY NOT OK.-Parallelism observed up to 0.150 against

## 1. Problem Description

<b>Defect Description</b>	Parallelism observed 0.150 against specification 0.100 mm.
<b>Detection Stage</b>	Inprocess
<b>Problem Severity</b>	Function
<b>NG Quantity</b>	15000
<b>Is Defect Repeatative?</b>	Yes
<b>Defect Sketch / Photo</b>	

## Supplier Communication Details

<b>Quality Head Email ID</b>	kalyan.babar@specialitysintered.com
<b>Plant Head/CEO Email ID</b>	Datta.gadhve@ssplpune.com
<b>MD Email ID</b>	lalit.chaudhari@ssplpune.com

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	51000	0	0	5000	0	56000
<b>Check Qty</b>	51000	0	0	5000	0	56000
<b>NG Qty</b>	51000	0	0	0	0	51000

## Action taken on NG part

<b>Scrap</b>	51000
<b>Rework</b>	0
<b>Under Deviation</b>	0

## Containment Action

100% inspection done for FG parts available at SSPL END

## 3. Process Flow

**Process Flow Description**

RM Inspection - Forming - Sintering - Debarring - Steam - Final inspection - Packaging

**4. Process Details**

<b>Process / Operation</b>	Forming
<b>Outsource</b>	Yes
<b>Machine / Cell</b>	15F3
<b>Machine / Cell No.</b>	15F3

**5. Problem Analysis**

Type	Possible Cause	Fact Verification	Jud
Man	unskilled operator	interviewing operator operator skill observed ok	X
Material	Wrong grade RM used	verified Raw Materil TC obsered grade is OK	X
Material	incorrect resting material	verified resting obseved less strength	O
Method	incorrect control plan	verified control plan flange taper not addressed in control plan	O
Tool	incorrect tool used	verified inccorect tool used detected in first off	X
Method	incorrect inspection method	verified inspection method observed ok with V block & dial gauge	X

**6. Inspection Method Analysis (Current)**

<b>Inspection Method</b>	Instrument
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	Sampling
<b>Sampling</b>	No
<b>Sample Size</b>	IS2500

**7. Root Cause Analysis (Occurance)**

<b>Why 1</b>	Parallelism NG observed up to 0.25 mm against spec 0.1 mm max
<b>Why 2</b>	Parallelism Getting out of spec In Forming Process.
<b>Why 3</b>	In Running Condition Length Taper Generated
<b>Why 4</b>	Punch resting Getting Cracked during running condition
<b>Why 5</b>	less strength of resting
<b>Root Cause (Occurance)</b>	less strength of resting

**Root Cause Analysis (Outflow)**

<b>Why 1</b>	Parallelism NG observed up to 0.25 mm against spec 0.1 mm max
<b>Why 2</b>	Part Not Detect in Process Inspection
<b>Why 3</b>	Inspector Not Checked Flange Taper.
<b>Why 4</b>	Flange Taper Checkpoint Not Address In Forming Control Plan. .
<b>Why 5</b>	
<b>Root Cause (Outflow)</b>	Flange Taper Checkpoint Not Address In Forming Control Plan. .

## 8. Countermeasure ( Occurrence , Outflow & System side Actions )

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Occurance	Countermeasure Details Responsibility Target Date Actual Date Status Occurance New Top Punch Resting Made With Sufficient Straight. (Total Width 50MM) Top Punch Resting Check Point Add In Tool History Card.	Mayur Patil	16/05/2024	17/05/2024	Completed

## 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	Yes
<b>Change Details</b>	length inspection method changed flange tapper point added in forming control plan
<b>Inspection Method</b>	Instrument
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	Sampling
<b>Sampling</b>	No
<b>Sample Size</b>	IS2500

## 10. Evidence of Countermeasure

<b>Occurance (Before)</b>	N-31 material grade used <a href="#">770_Occurance_Before.xlsx</a>
<b>Occurance (After)</b>	N-24 material grade used <a href="#">770_Occurance_After.xlsx</a>
<b>Outflow (Before)</b>	Their was no check point of flange tapper <a href="#">770_Outflow_Before.jpeg</a>
<b>Outflow (After)</b>	Flange tapper check point added in control plan <a href="#">770_Outflow_After.jpeg</a>

## 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	Yes
<b>Applicable Machine / Model / Plant</b>	S2KT model

## 12. Document Review

<b>Documents</b>	ControlPlan, PFMEA, WISOP
<b>Specify Other Document</b>	NA

## 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	5
<b>Reason for submission</b>	Parallelism found Ok in upcoming fresh Lots .

