

## Defect Details

<b>NC No.</b>	7001014528
<b>NC Date</b>	16/05/2024
<b>NC Submission Date</b>	
<b>Part No.</b>	F1GN01102B
<b>Part Name</b>	MAIN SPRING K86A
<b>Supplier Name &amp; Code</b>	100186-SAGAR SPRINGS PRIVATE LIMITED
<b>ETL Plant</b>	1136-ETL Suspension Sanand
<b>Defect Details</b>	DIMN.U/SIZE.-Tip thickness undersize.

## 1. Problem Description

<b>Defect Description</b>	Tip thickness specified 0.8 mm min observation 0.20 mm (NG)
<b>Detection Stage</b>	Receipt
<b>Problem Severity</b>	Function
<b>NG Quantity</b>	1020
<b>Is Defect Repeatative?</b>	No
<b>Defect Sketch / Photo</b>	

## Supplier Communication Details

<b>Quality Head Email ID</b>	quality@sagarsprings.com
<b>Plant Head/CEO Email ID</b>	ajai.singh@sagarsprings.com
<b>MD Email ID</b>	sagar@sagarsprings.com

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	4080	0	4500	0	0	8580
<b>Check Qty</b>	4080	0	4500	0	0	8580
<b>NG Qty</b>	1020	0	250	0	0	1270

## Action taken on NG part

<b>Scrap</b>	20
<b>Rework</b>	0
<b>Under Deviation</b>	0

## Containment Action

100%inspection at ETL HALOL PLANT

## 3. Process Flow

**Process Flow Description**

COILING, TEMPRING, GRINDING, SHOT PEENING, 2ND TEMPRING, WAVINESS

**4. Process Details**

<b>Process / Operation</b>	Grinding stage
<b>Outsource</b>	No
<b>Machine / Cell</b>	Grinding
<b>Machine / Cell No.</b>	Grinding

**5. Problem Analysis**

Type	Possible Cause	Fact Verification	Jud
Man	Unskilled operator not set machine properly and check it properly result in to generation of rejecti	Found operator deputed are well understood of grindng process and deffect it cause and counter meas	O
Material	Wrong grade wheel result on grinding performance	Check the grade of wheel used ie ceramic wheel	O
Method	Faulty program will result into more feed, full grinding, less grinding or taper grinding in some ca	Check the program used for grinding it was found OK	O
Method	Grinding angle more	Grinding angle found 300 to 350deg and tip thickness found less than 0.80 mm	X

**6. Inspection Method Analysis (Current)**

<b>Inspection Method</b>	Instrument
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	Sampling
<b>Sampling</b>	No
<b>Sample Size</b>	Sample pla

**7. Root Cause Analysis (Occurance)**

<b>Why 1</b>	Grinding angle more
<b>Why 2</b>	Grinding angle measures 300° to 350° against specification 320° minimum
<b>Why 3</b>	Grinding angle maintained at higher band causing thickness less
<b>Why 4</b>	
<b>Why 5</b>	
<b>Root Cause (Occurance)</b>	Grinding angle maintained at higher band (300° to 350°) causing thickness less

**Root Cause Analysis (Outflow)**

<b>Why 1</b>	Tip thickness less
<b>Why 2</b>	Inspection done on sampling basis
<b>Why 3</b>	
<b>Why 4</b>	
<b>Why 5</b>	
<b>Root Cause (Outflow)</b>	Inspection done on sampling basis

## 8. Countermeasure ( Occurrence , Outflow & System side Actions )

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Outflow	100% Visual inspection started for grinding angle at grinding stage	VDP	01/06/2024	01/06/2024	Completed
Occurance	At grinding stage grinding angle will be maintained 320 deg minimum	VDP	01/06/2024	01/06/2024	Completed

## 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	No
<b>Change Details</b>	No change
<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	100% Visual inspecti
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	Sampling
<b>Sampling</b>	No
<b>Sample Size</b>	10 no/1000

## 10. Evidence of Countermeasure

<b>Occurance (Before)</b>	At Grinding stage Grinding angle maintained 300° to 350° <a href="#">805_Occurance_Before.pdf</a>
<b>Occurance (After)</b>	At Grinding stage Grinding angle maintained 320° deg minimum to maintain tip thickness 0.80 mm. <a href="#">805_Occurance_After.pdf</a>
<b>Outflow (Before)</b>	Inspection on sampling basis. <a href="#">805_Outflow_Before.pdf</a>
<b>Outflow (After)</b>	100% Inspection for Grinding angle at Grinding stage. <a href="#">805_Outflow_After.pdf</a>

## 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	No
<b>Applicable Machine / Model / Plant</b>	Action applicable for this part only.

## 12. Document Review

<b>Documents</b>	ControlPlan, PFMEA
<b>Specify Other Document</b>	In-process Inspectio

## 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	5
<b>Reason for submission</b>	Tip thickness found less against specified 0.8 mm min.

