

## Defect Details

<b>NC No.</b>	7001024806
<b>NC Date</b>	18/06/2024
<b>NC Submission Date</b>	
<b>Part No.</b>	S2DP02902B
<b>Part Name</b>	EXTENSION K55G
<b>Supplier Name &amp; Code</b>	100106-SHARP ENGINEERS.
<b>ETL Plant</b>	1136-ETL Suspension Sanand
<b>Defect Details</b>	CRACK-crack lot (suspected material )

## 1. Problem Description

<b>Defect Description</b>	Crack
<b>Detection Stage</b>	Inprocess
<b>Problem Severity</b>	Safety
<b>NG Quantity</b>	2200
<b>Is Defect Repeatative?</b>	No
<b>Defect Sketch / Photo</b>	

## Supplier Communication Details

<b>Quality Head Email ID</b>	quality@apw3.co.in
<b>Plant Head/CEO Email ID</b>	kurund.ma@sharp-engineers.com
<b>MD Email ID</b>	urkhandelwal@sharp-engineers.com

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	5000	5000	2000	3000	500	15500
<b>Check Qty</b>	5000	5000	2000	3000	500	15500
<b>NG Qty</b>	2200	0	0	0	5	2205

## Action taken on NG part

<b>Scrap</b>	2205
<b>Rework</b>	0
<b>Under Deviation</b>	0

## Containment Action

Segregation done immediately for suspected material of pipeline .

## 3. Process Flow

**Process Flow Description**

10) RM Inward 20) RM Storage 30) Traub Operation ( Parting & Drilling) 40) Forming 50) Tapping 60) OD grinding 70) MPI 80) Visual Inspection 90) Oiling 100) Packing & forwarding

**4. Process Details**

<b>Process / Operation</b>	Traub Machining
<b>Outsource</b>	No
<b>Machine / Cell</b>	Traub Machine
<b>Machine / Cell No.</b>	SE/SSAL/06

**5. Problem Analysis**

Type	Possible Cause	Fact Verification	Jud
Method	NG storage open	Wrong storage method for NG part, no lock and key	X
Man	Unskilled Manpower	Skill matrix as per requirement	O
Machine	Machine Variation	JH/PM as per defined frequency	O
Material	Wrong material grade	Third part inspection as per RM testing plan	O
Tool	Tool/insert/drill worn out	Tool life monitoring as per defined frequency	O

**6. Inspection Method Analysis (Current)**

<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	Cross MPI
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	1:1

**7. Root Cause Analysis (Occurance)**

<b>Why 1</b>	Extension K55 Crack
<b>Why 2</b>	RM crack at draw stage
<b>Why 3</b>	Internal crack not detectable.
<b>Why 4</b>	Not feasible in MPI
<b>Why 5</b>	Need ultrasonic test at round bar stage not done.
<b>Root Cause (Occurance)</b>	Need ultrasonic test at round bar stage not done.

**Root Cause Analysis (Outflow)**

<b>Why 1</b>	Crack Part got mix up with ok part
<b>Why 2</b>	NG material kept openly in bin without lock and keys.
<b>Why 3</b>	lock and key not available at MPI testing supplier (Outsource)
<b>Why 4</b>	
<b>Why 5</b>	
<b>Root Cause (Outflow)</b>	lock and key not available at MPI testing supplier (Outsource)

## 8. Countermeasure ( Occurrence , Outflow & System side Actions )

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Occurance	Ultrasonic test is being done at round bar stage after draw process	Mr. Ganesh Chavan	25/06/2024	25/06/2024	Completed
Outflow	Lock and key provided for NG material at MPI testing supplier.	Mr. Shaikh L.N.	26/06/2024	26/06/2024	Completed

## 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	Yes
<b>Change Details</b>	Ultrasonic test is being don at draw stage at sub-supplier.( Vishwa Samrudhi Industries)
<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	ultrasonic test (UTI)
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	1:1

## 10. Evidence of Countermeasure

<b>Occurance (Before)</b>	Magnetic particle inspection after draw process <a href="#">874_Occurance_Before.pptx</a>
<b>Occurance (After)</b>	Additional Ultrasonic test is being done at round bar stage after draw process <a href="#">874_Occurance_After.pptx</a>
<b>Outflow (Before)</b>	lock and key not available at MPI testing supplier (Outsource) <a href="#">874_Outflow_Before.pptx</a>
<b>Outflow (After)</b>	Lock and key provided for NG material at MPI testing supplier. <a href="#">874_Outflow_After.pptx</a>

## 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	No
<b>Applicable Machine / Model / Plant</b>	NA

## 12. Document Review

<b>Documents</b>	ControlPlan, PFMEA, WISOP, ProcessFlowChart, InspCheckSheet
<b>Specify Other Document</b>	NA

## 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	5
<b>Reason for submission</b>	Crack

