

## Defect Details

<b>NC No.</b>	7001032025
<b>NC Date</b>	10/07/2024
<b>NC Submission Date</b>	
<b>Part No.</b>	B207082000
<b>Part Name</b>	END CON ASM ABS SIDE- ABS 2 FR MC K42CH
<b>Supplier Name &amp; Code</b>	101221-SUNREN AUTOMOTIVE PRIVATE LIMI
<b>ETL Plant</b>	1120-ETL K-226/2 Disc Brakes
<b>Defect Details</b>	RUSTY-rusty

## 1. Problem Description

<b>Defect Description</b>	RUSTY-rusty
<b>Detection Stage</b>	Receipt
<b>Problem Severity</b>	Aesthetic
<b>NG Quantity</b>	300
<b>Is Defect Repeatative?</b>	Yes
<b>Defect Sketch / Photo</b>	

## Supplier Communication Details

<b>Quality Head Email ID</b>	shivank@sunren.in
<b>Plant Head/CEO Email ID</b>	sanjayrana@sunren.in
<b>MD Email ID</b>	subhashsaini@sunren.in

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	2800	3800	800	500	1500	9400
<b>Check Qty</b>	2800	3800	800	500	1500	9400
<b>NG Qty</b>	300	0	0	0	0	300

## Action taken on NG part

<b>Scrap</b>	0
<b>Rework</b>	300
<b>Under Deviation</b>	0

## Containment Action

Re-Plating

## 3. Process Flow

Process Flow Description
Plating

#### 4. Process Details

<b>Process / Operation</b>	Plating
<b>Outsource</b>	Yes
<b>Machine / Cell</b>	01
<b>Machine / Cell No.</b>	01

#### 5. Problem Analysis

Type	Possible Cause	Fact Verification	Jud
Method	Wrong Method	Wrong Method Followed	O
Man	Lack of Knowledge	Skilled	X
Man	Lack Of Awareness	Training Required	O

#### 6. Inspection Method Analysis (Current)

<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	Visual
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	5

#### 7. Root Cause Analysis (Occurance)

<b>Why 1</b>	Due to presence of water.
<b>Why 2</b>	Due to no. of bends , in the part water gets accumulated at the bends.
<b>Why 3</b>	Pressurized air not passed through the bends of the part.
<b>Why 4</b>	Not Define in SOP.
<b>Why 5</b>	Lack of Awareness
<b>Root Cause (Occurance)</b>	Pressurized Air not passes through the bends of the parts after plating operation.

#### Root Cause Analysis (Outflow)

<b>Why 1</b>	Rust cannot be detected at the same time and takes time to occur.
<b>Why 2</b>	Depends on storage conditions also.
<b>Why 3</b>	
<b>Why 4</b>	
<b>Why 5</b>	
<b>Root Cause (Outflow)</b>	Rust takes time to occur and cannot be detected at the same time.

#### 8. Countermeasure ( Occurrence , Outflow & System side Actions )

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Outflow	Rust Oil will be passed through the bend of the part after plating operation.	Krishna Plating	30/07/2024	30/07/2024	Completed
Occurance	Pressurized Air will be passed through the bends of the parts after plating operation.	Krishna Plating	30/07/2024	30/07/2024	Completed

## 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	Yes
<b>Change Details</b>	Rust oil will be passed through the end bend of the part after plating operation and it's inspection.
<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	Visual
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	5

## 10. Evidence of Countermeasure

<b>Occurance (Before)</b>	No Air Passes Through Bend After Plating Operation <a href="#">932_Occurance_Before.jpg</a>
<b>Occurance (After)</b>	Air will be pass through bend after plating operation. <a href="#">932_Occurance_After.jpeg</a>
<b>Outflow (Before)</b>	Rust Oil was applied over the surface of the part. <a href="#">932_Outflow_Before.jpeg</a>
<b>Outflow (After)</b>	Rust oil will be pass through the bend of the part,. <a href="#">932_Outflow_After.jpeg</a>

## 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	Yes
<b>Applicable Machine / Model / Plant</b>	B207078000

## 12. Document Review

<b>Documents</b>	
<b>Specify Other Document</b>	OPL

## 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	100
<b>Reason for submission</b>	ok