

## Defect Details

NC No.	8000782061
NC Date	27/03/2022
NC Submission Date	
Part No.	520CJ00102
Part Name	COPPER WASHER
Supplier Name & Code	100152-GOLDY PRECISION STAMPINGS PVT.
ETL Plant	1136-ETL Suspension Sanand
Defect Details	EXCESS CUT/SANDERING-CUT FROM EDGE

## 1. Problem Description

Defect Description	Part Cut From OD
Detection Stage	Inprocess
Problem Severity	Function
NG Quantity	5
Is Defect Repeatative?	Yes
Defect Sketch / Photo	<a href="#">rfo2mvbruc002pra10ggh2kq.png</a>

## Supplier Communication Details

Quality Head Email ID	quality@goldy.in
Plant Head/CEO Email ID	mangesh.chaudhary@goldy.in
MD Email ID	sidhesh.raikar@goldy.in

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
Total Qty	10000	0	0	10000	0	20000
Check Qty	10000	0	0	10000	0	20000
NG Qty	5	0	0	0	0	5

## Action taken on NG part

Scrap	5
Rework	0
Under Deviation	0

## Containment Action

Finish good qty 10000 Nos verify at visual inspection found ok.

## 3. Process Flow

## Process Flow Description

## 4. Process Details

<b>Process / Operation</b>	BLANKING
<b>Outsource</b>	No
<b>Machine / Cell</b>	PRESS MACHINE
<b>Machine / Cell No.</b>	P-4

## 5. Problem Analysis

Type	Possible Cause	Fact Verification	Jud
Man	Operator skill	Verify opeartor skill as per Enducation & training, operator found trained	O
Method	Blanking method not ok	Checked method as per work instruction found ok	O
Tool	Tool not ok	Verify Tool condition, dowel pin found not ok	X
Machine	Machine not ok	Checked Parameter checked founf ok	O
Material	Material not ok	Material thickness width, hardness checked found ok	O

## 6. Inspection Method Analysis (Current)

<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	VISUAL
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100%

## 7. Root Cause Analysis (Occurance)

<b>Why 1</b>	Outer Diameter cut found parts no- 520CJ00102
<b>Why 2</b>	Outer diameter cut during blanking while strip feeding
<b>Why 3</b>	Strip Overlap feed because toll dowel not control to overlap operation
<b>Why 4</b>	Dowel pin not ok, dowel pin height in sufficient
<b>Why 5</b>	NOT APPLICABLE
<b>Root Cause (Occurance)</b>	Dowel pin not ok, dowel pin height in sufficient

## Root Cause Analysis (Outflow)

<b>Why 1</b>	Outer diameter cut parts skipped in visual inspection
<b>Why 2</b>	Operator could not detect to cut parts
<b>Why 3</b>	Operator take more parts on table for visual inspection
<b>Why 4</b>	NOT APPLICABLE
<b>Why 5</b>	NOT APPLICABLE
<b>Root Cause (Outflow)</b>	Operator take more parts on table for visual inspection

**8. Countermeasure ( Occurrence , Outflow & System side Actions )**

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Occurance	1) Dowel pin height increase more than 2 mm of thickness. (Height increase 3.5 against 1.5mm) 2) Operator verify pin height condition before start blanking.	Vikas Divate / Rahul kandale	28/03/2022	28/03/2022	Completed
Outflow	10-12 no`s parts checking started on visual inspection on table	Rahul Pawar	29/03/2022	29/03/2022	Completed
Outflow	Training given to visual inspector for part inspection	Rahul Pawar / Vikas Divate	29/03/2022	29/03/2022	Completed

**9. Inspection Method After Customer Complaint**

<b>Change In Inspection System</b>	Yes
<b>Change Details</b>	10-12 no`s parts checking started on visual inspection on table
<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	Visual
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100%

**10. Evidence of Countermeasure**

<b>Occurance (Before)</b>	Dowel pin not ok, dowel pin height in sufficient <a href="#">27_Occurance_Before.pdf</a>
<b>Occurance (After)</b>	1) Dowel pin height increase more than 2 mm of thickness. (Height increase 3.5 against 1.5mm) 2)Operator verify pin condition before start blanking. <a href="#">27_Occurance_After.pdf</a>
<b>Outflow (Before)</b>	Operator take more parts on table for visual inspection <a href="#">27_Outflow_Before.pdf</a>
<b>Outflow (After)</b>	10-12 no`s parts checking started on visual inspection on table <a href="#">27_Outflow_After.pdf</a>

**11. Horizontal Deployment**

<b>Horizontal Deployment Required</b>	Yes
<b>Applicable Machine / Model / Plant</b>	Cooper parts - 520CJ00502 & 520CJ00702

**12. Document Review**

<b>Documents</b>	ControlPlan, PFMEA
<b>Specify Other Document</b>	Before after

**13. Effectiveness Of Action**

--	--

<b>Reviewed Quantity</b>	1000
<b>Reason for submission</b>	Accepted