#### **Defect Details**

NC No.	8000786469
NC Date	06/05/2022
NC Submission Date	
Part No.	C2FY00233M
Part Name	HUB CL. WITH INSERT MACHINED-D1
Supplier Name & Code	100874-ANUSHRUSHTI AUTO PARTS
ETL Plant	1132-ETL K-226/1 TRANSMISSION
<b>Defect Details</b>	RUN OUT MORE-TEETH R/O O/S UP TO 0.40 MM

# 1. Problem Description

<b>Defect Description</b>	Teeth OD Run out observed upto 0.4 mm as against 0.25 mm
<b>Detection Stage</b>	Receipt
Problem Severity	Function
NG Quantity	25
Is Defect Repeatative?	Yes
Defect Sketch / Photo	

# Supplier Communication Details

Quality Head Email ID quality@anushrushtiautoparts.com	
Plant Head/CEO Email ID	anushrushti 2011 @rediffmail.com
MD Email ID	rrwable@redffmail.com

## 2. Stock Details & action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
Total Qty	300	0	0	0	0	300
Check Qty	300	0	0	0	0	300
NG Qty	25	0	0	0	0	25

#### Action taken on NG part

Scrap		25
Rework		0
Under Dev	iation	0

#### **Containment Action**

100% inspection done for D1 HUB CL WITH INSERT with marking on TEETH.

#### 3. Process Flow

#### Process Flow Description

1.)RM INWARD 2) CNC 1ST SETUP 3) CNC 2ND SETUP 4) DRILLING 5)FINAL INSPECTION 6) PACKING & DISPATCH

#### 4. Process Details

Process / Operation	CASTING
Outsource	Yes
Machine / Cell	CNC 2
Machine / Cell No.	CNC 2

## 5. Problem Analysis

Туре	Possible Cause	Fact Verification	Jud
Man	Inspector not aware of defect	Inspector skill matrix checked found ok	0
Man	Operator not aware of defect	Operator training was not effective	Х
Method	Separate bins not used for storage	Operator is storing Parts in special partision bin	0
Method	Part clamping & decampling not proper	uneven part clamping in jaw	Х

# 6. Inspection Method Analysis (Current)

Inspection Method	Other
Other Inspection Method	MANDRELL& DIAL GAUGE
Check Point at Final Inspection	Yes
Checking Freq.	Sampling
Sampling	No
Sample Size	5NO'S /LOT

# 7. Root Cause Analysis (Occurance)

Why 1	uneven part clamping in jaw
Why 2	heavy burr deposited at part clamping location (jaw)
Why 3	part clamping location not clean properly
Why 4	part clamping location cleaning frequency not define properly.
Why 5	
Root Cause (Occurance)	part clamping location cleaning frequency not define properly.

## Root Cause Analysis (Outflow)

Why 1	Part inspection frequency not evident
Why 2	Lot wise 5 no`s inspection fequency was define in control plan
Why 3	
Why 4	Part inspection frequency not evident
Why 5	
Root Cause (Outflow)	Part inspection frequency not evident

# 8. Countermeasure ( Occurrence , Outflow & System side Actions )

Туре	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Outflow	Partwise On job training are provided of all operator	Mr.Malhari pawar	18/05/2022	18/05/2022	Completed
Outflow	Part inspection frequency not evident	Deepak singh	27/05/2022	27/05/2022	Completed
Occurance	part clamping location cleaning frequency not define properly	malhari pawar	16/06/2022	16/06/2022	Completed

# 9. Inspection Method After Customer Complaint

Change In Inspection System	Yes
Change Details	1)Before - 5no's per lot inspection done 2) After customer complaints -per bins 1 nos inspection started in final inspection
Inspection Method	Other
Other Inspection Method	dial+centerbetween
Check Point at Final Inspection	Yes
Checking Freq.	Sampling
Sampling	No
Sample Size	PER BINS 1

### 10. Evidance of Countermeasure

Occurance (Before)	Jaw Burr cleaning frequency not define in control plan 95_Occurance_Before.xlsx
Occurance (After)	Jaw Burr cleaning define & updated in controlplan 95_Occurance_After.xlsx
Outflow (Before)	Face runout insp frequency was 5 no`s per lot 95_Outflow_Before.xlsx
Outflow (After)	Face runout insp frequency revied from 5 no's per lot to 1 no's per Bins 95_Outflow_After.xlsx

# 11. Horizontal Deployment

Horizontal Deployment Required	Yes
Applicable Machine / Model / Plant	Tranmission Division

#### 12. Document Review

Documents	ControlPlan
Specify Other Document	On job training shee

### 13. Effectiveness Of Action

Reviewed Quantity	2000
Reason for submission	OK

