

## Defect Details

NC No.	8000788016
NC Date	19/05/2022
NC Submission Date	
Part No.	F2FA19033M
Part Name	K0PG FORK PIPE MACHINED
Supplier Name & Code	101109-TUBE INVESTMENTS OF INDIA LIMI
ETL Plant	1136-ETL Suspension Sanand
Defect Details	NOT AS PER SPECIFICATION-MACHINING OPERATION(46.1+01MM DEPTH MISS

## 1. Problem Description

Defect Description	Caulking Side (46.1 +0.1 mm Depth) Machining Operation Miss.
Detection Stage	Inprocess
Problem Severity	Fitment
NG Quantity	1
Is Defect Repeatative?	No
Defect Sketch / Photo	

## Supplier Communication Details

Quality Head Email ID	anandms@tii.murugappa.com
Plant Head/CEO Email ID	vijayakumarv@tii.murugappa.com
MD Email ID	mukeshahuja@tii.murugappa.com

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
Total Qty	2010	0	0	1500	700	4210
Check Qty	2010	0	0	1500	700	4210
NG Qty	1	0	0	0	0	1

## Action taken on NG part

Scrap	1
Rework	0
Under Deviation	0

## Containment Action

1.100% Inspection Done at ETL end for all available Qty. 2.100% visual Inspection done for all available Qty of Machined Tubes KOPG & K86 - A Model with Blue Marking at Tube ID Chamfer at TI Sanand WH.

## 3. Process Flow

**Process Flow Description**

Incoming Material - Inward Inspection - Storage - CNC Machining Clip Side - CNC Machining Caulking Side - Drilling - Deburring - Final Inspection - Packing in Bins - Dispatch to ETL.

**4. Process Details**

<b>Process / Operation</b>	CNC Machining Caulking Side
<b>Outsource</b>	No
<b>Machine / Cell</b>	CNC Machining Cell
<b>Machine / Cell No.</b>	ACE CNC -02

**5. Problem Analysis**

Type	Possible Cause	Fact Verification	Jud
Method	Wrong Setup	Verified through Gemba observation and found M/c Setup Repot OK.	O
Machine	Machining Parameter	Verified through Gemba observation and found all Machine Parameter as per Control Plan	O
Method	Incomplete M/C Cycle	Verified through Gemba observation and found that if Sudden power Failure / Sudden Emergency Button	X
Machine	Sudden Machine Breakdown	Verified through Gemba & facts found ACE CNC -02 M/c Stop frequently with error cabinet temp too high	X
Man	Inspection SOP not Followed	in Deburring Fixture Pokayoke , fully Inserted & rest at bottom Plate is not easily to visualize.	X

**6. Inspection Method Analysis (Current)**

<b>Inspection Method</b>	Pokayoke
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	Sampling
<b>Sampling</b>	No
<b>Sample Size</b>	20 Nos/lot

**7. Root Cause Analysis (Occurance)**

<b>Why 1</b>	Caulking Depth of Dim. 46.10 +.10 mm Miss part found at Customer end.
<b>Why 2</b>	Incomplete Machining cycle
<b>Why 3</b>	ACE CNC -02 Machine Stopping in Running operation
<b>Why 4</b>	ACE CNC -02 m/c stopping with error cabinet temp too high.
<b>Why 5</b>	In ACE CNC -02 Machine Setting ( Handy ) value of Parameter write is wrong ( set by Manufacturer )
<b>Root Cause (Occurance)</b>	In ACE CNC -02 Machine Setting ( Handy ) value of Parameter write is wrong ( set by Manufacturer )

**Root Cause Analysis (Outflow)**

<b>Why 1</b>	Caulking Depth of Dim. 46.10 +.10 mm Miss part found at Customer end.
<b>Why 2</b>	Part not Capture in De- Burring Fixture Poka-yoke ( at Bottom Side Bush Provided with OD 26 mm & Height 45 mm.)
<b>Why 3</b>	Operator not judged Part is fully Inserted & rest at bottom of Deburring Poka-yoke Fixture.
<b>Why 4</b>	Deburring Fixture poka-yoke Table Height is Less (380 mm ) & Burr Collecting box height ( 285 mm ) is More.

<b>Why 5</b>	
<b>Root Cause (Outflow)</b>	Deburring Fixture poka-yoke Table Height is Less (380 mm ) & Burr Collecting box height ( 285 mm ) is More.

**8. Countermeasure ( Occurrence , Outflow & System side Actions )**

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Occurrence	After Discussion with ACE CNC M/C representative in Machine Setting ( Handy ) value of Parameter write changed from 1 to 0	Mr. Bhupender Paji	23/05/2022	22/05/2022	Completed
Outflow	Training given to operator to check for Power Failure / Sudden stop of machine during operation part 100% for all Dimension and if part is not as per specification then the reject part.	Mr. Bhupendra.	20/09/2022	20/09/2022	Completed
Outflow	Deburring Poka-yoke Fixture table Height will Increase to 4 feet & Burr Collecting box height reduced to 50 mm	Mr. Palak Shah	27/05/2022	26/05/2022	Completed
Outflow	Deburring Work Instruction Updated for tube should be rested fully to bottom.	Mr.Piyush Parmar	24/09/2022	23/09/2022	Completed
Outflow	One Point Lesson Displayed at Deburring Station	Mr. Piyush Parmar	24/09/2022	23/09/2022	Completed

**9. Inspection Method After Customer Complaint**

<b>Change In Inspection System</b>	Yes
<b>Change Details</b>	Added Visual Check for Operation Miss with Identification marking in Caulking ID.
<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	Visual Insp.
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100%

**10. Evidance of Countermeasure**

<b>Occurance (Before)</b>	In ACE CNC -02 Machine Setting ( Handy ) value of Parameter write is 1 due to this Machine stop in running with showing error of cabinet temp too high. <a href="#">135_Occurance_Before.pdf</a>
<b>Occurance (After)</b>	To overcome the issue of cabinet temp too high resulting in machine Stoppage in Running in Machine Setting ( Handy ) value of Parameter write changed from 1 to 0 <a href="#">135_Occurance_After.pptx</a>
<b>Outflow (Before)</b>	Operator not able detected that Part is fully Inserted & rest at bottom of Deburring Poka- Yoke Fixture Cause of Deburring Fixture Table Height is Less (380 mm ) & Burr Collecting box height ( 285 mm ) is More. <a href="#">135_Outflow_Before.pptx</a>
<b>Outflow (After)</b>	Deburring Poka-yoke Fixture table Height will Increase to 4 feet & Burr Collecting box height reduced to 50 mm . So Operator will easily detect that Part is fully Inserted & rest at bottom of Deburring Poka-yoke Fixture. <a href="#">135_Outflow_After.pptx</a>

**11. Horizontal Deployment**

<b>Horizontal Deployment Required</b>	Yes
<b>Applicable Machine / Model / Plant</b>	ACE CNC -01 Machine TFF Tube Model - K86 -A

12. Document Review

<b>Documents</b>	WISOP
<b>Specify Other Document</b>	one Point Lesson

13. Effectiveness Of Action

<b>Reviewed Quantity</b>	14000
<b>Reason for submission</b>	Operation miss part not reported again in review qty.