QFR No - 8000790667

Defect Details

NC No.	8000790667
NC Date	13/06/2022
NC Submission Date	
Part No.	550MB07702
Part Name	SPACER TUBE - VE (115.5)
Supplier Name & Code	100756-BLUE STAR ENGINEERS
ETL Plant	1116-ETL K-120 Suspension
Defect Details	EXCESS MATERIAL-GATE MARK ON FACE

1. Problem Description

Defect Description	In Spacer tube (550MB07702) observed with excess high point at gate position & face parallisum observed up to 0.3 mm against requirement of 0.1mm.
Detection Stage	Inprocess
Problem Severity	Function
NG Quantity	1000
Is Defect Repeatative?	No
Defect Sketch / Photo	qixcy22tqjkdv3zlpjwjrlqg.pdf

Supplier Communication Details

Quality Head Email ID	kakade.dnyaneshwar@sanghavigroup.co	
Plant Head/CEO Email ID	prabhune.girish@sanghavigroup.co.in	
MD Email ID	sanghavi.rajesh@sanghavigroup.co.in	

2. Stock Details & action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
Total Qty	20000	0	0	5000	0	25000
Check Qty	20000	0	0	5000	0	25000
NG Qty	1000	0	0	0	0	1000

Action taken on NG part

Scrap	0
Rework	1000
Under Deviation	0

Containment Action	
Gate cutting.	

1)Raw Material Receiving & Storing - 2)Predrying/Pre Heating - 3)Injection moulding - 4)Deflashing & degating - 5)Final Inspection - 6)Packing & Storing - 7)Logistics and transport.

4. Process Details

Process / Operation	Injection Moulding Process
Outsource	No
Machine / Cell	Injection Moulding Machine
Machine / Cell No.	IMMH1017

5. Problem Analysis

Туре	Possible Cause	Fact Verification	Jud
Man	Ineffective training	Gate point issue present in defect list	Х
Tool	Gate point provided at improper place.	Functional issues observed due to gate point.	Х

6. Inspection Method Analysis (Current)

Inspection Method	Other
Other Inspection Method	Visual
Check Point at Final Inspection	Yes
Checking Freq.	100%
Sampling	No
Sample Size	100

7. Root Cause Analysis (Occurance)

Why 1	Gate point issue observed resulting in funtional issue.
Why 2	Gate point mark observed at face due tool wear out.
Why 3	Tool wear out due to maintenance delay.
Why 4	Tool wear out faster than expected
Why 5	Gate point provided at sensitive point as compaired to function of part.
Root Cause (Occurance)	Gate point provided at sensitive point as compaired to function of part.

Root Cause Analysis (Outflow)

Why 1	Gate point issue observed resulting in funtional issue.
Why 2	Degating Issue was not detected.
Why 3	Ineffective Training.
Why 4	
Why 5	
Root Cause (Outflow)	Ineffective Training

8. Countermeasure (Occurrence , Outflow & System side Actions)

Туре	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Occurance	Change in gate point position	Sarang Chandak	04/07/2022	30/06/2022	Completed

9. Inspection Method After Customer Complaint

Change In Inspection System	Yes
Change Details	100% visual inspection with Marking(Blue marker)
Inspection Method	Other
Other Inspection Method	visual
Check Point at Final Inspection	Yes
Checking Freq.	100%
Sampling	No
Sample Size	1000

10. Evidance of Countermeasure

Occurance (Before)	Three plate mould(Point Gate) 173_Occurance_Before.jpg
Occurance (After)	Two plate Mould(Tab gate) 173_Occurance_After.jpg
Outflow (Before)	Defect list 173_Outflow_Before.xlsx
Outflow (After)	Defect list change 173_Outflow_After.xlsx

11. Horizontal Deployment

Horizontal Deployment Required	No
Applicable Machine / Model / Plant	n

12. Document Review

Documents	PMCheckSheet
Specify Other Document	n

13. Effectiveness Of Action

Reviewed Quantity	1000
Reason for submission	Completed.