

## Defect Details

<b>NC No.</b>	8000797760
<b>NC Date</b>	29/07/2022
<b>NC Submission Date</b>	
<b>Part No.</b>	550HL00602
<b>Part Name</b>	OIL LOCK COLLAR
<b>Supplier Name &amp; Code</b>	100503-DIVYA INDUSTRIES
<b>ETL Plant</b>	1117-ETL K-228/9 Suspension
<b>Defect Details</b>	NOT AS PER SPECIFICATION-LENGTH U/S, OD O/S, EXTRA HOLE

## 1. Problem Description

<b>Defect Description</b>	TOTAL LENGTH UNDERSIZED, O/D OVERSIZED & EXTRA HOLE PUNCHING
<b>Detection Stage</b>	Inprocess
<b>Problem Severity</b>	Fitment
<b>NG Quantity</b>	4
<b>Is Defect Repeatative?</b>	Yes
<b>Defect Sketch / Photo</b>	

## Supplier Communication Details

<b>Quality Head Email ID</b>	quality@mahavirind.co.in
<b>Plant Head/CEO Email ID</b>	production@mahavirind.co.in
<b>MD Email ID</b>	rajesh@mahavirind.co.in

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	600	0	0	0	0	600
<b>Check Qty</b>	600	0	0	0	0	600
<b>NG Qty</b>	4	0	0	0	0	4

## Action taken on NG part

<b>Scrap</b>	4
<b>Rework</b>	0
<b>Under Deviation</b>	0

## Containment Action

All Suspected material Segregation at customer End

## 3. Process Flow

## Process Flow Description

RM Inward- Store- Traub Parting - Semi finish Inward CNC-1st- CNC-2nd- Cross Hole Both sides- Deburring - OD Grinding - Plating -Final Inspection- Packing - Transport-

## 4. Process Details

<b>Process / Operation</b>	Cross Hole Both sides
<b>Outsource</b>	Yes
<b>Machine / Cell</b>	Cross Hole Drilling Machine
<b>Machine / Cell No.</b>	Drill M/C No.1

## 5. Problem Analysis

Type	Possible Cause	Fact Verification	Jud
Man	During Cross hole Setting Piece Mix	During Cross Hole Drill CD distance Setiing 2pieces By mistake mix with ok material .	X

## 6. Inspection Method Analysis (Current)

<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	Visual
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100

## 7. Root Cause Analysis (Occurance)

<b>Why 1</b>	Double Cross hole
<b>Why 2</b>	Setting defective pcs mix with OK Material
<b>Why 3</b>	During the Change over CD Adjustment setting pcs mix
<b>Why 4</b>	Cross drill operator Semiskilled
<b>Why 5</b>	
<b>Root Cause (Occurance)</b>	Setting defective pcs mix with OK Material

## Root Cause Analysis (Outflow)

<b>Why 1</b>	Double Cross hole
<b>Why 2</b>	Visual Inspection Not checking carefully
<b>Why 3</b>	Depend On Cross Drill Operator
<b>Why 4</b>	Without Identified Material Dispatch To Customer
<b>Why 5</b>	
<b>Root Cause (Outflow)</b>	Without Identified Material Dispatch To Customer

## 8. Countermeasure ( Occurrence , Outflow & System side Actions )

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
------	------------------------	----------------	-------------	-------------	--------

Outflow	1)Location Decided for Cross Hole Setting Piece and Defective Material. 2) Training To Operator. 3)Both Hole Identification Start By block marker	Mr.Suresh Kapgate/Mr.Pralhad Bhawar	12/08/2022	12/08/2022	Completed
---------	---	-------------------------------------	------------	------------	-----------

## 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	Yes
<b>Change Details</b>	After 360° Visual Inspection Identification Start to both cross hole to final Inspection Stage.
<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	VISUAL
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100

## 10. Evidence of Countermeasure

<b>Occurance (Before)</b>	By Mistekly Setting Piece Mix With ok cross Hole Process Material. <a href="#">215_Occurance_Before.jpg</a>
<b>Occurance (After)</b>	1) Quality Alert Display .2)Training To Operator .3)Lock & key Red Box Provide on Cross hole Drill Machine. Not Need More Change In Fixture. <a href="#">215_Occurance_After.jpg</a>
<b>Outflow (Before)</b>	Without Identification Dispatch To Customer <a href="#">215_Outflow_Before.jpeg</a>
<b>Outflow (After)</b>	1)100% Identification to both holes at the Final inspection Stage.2)Defected Sample Display On final Inspection Table. 3)Training To Inspector. <a href="#">215_Outflow_After.jpeg</a>

## 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	Yes
<b>Applicable Machine / Model / Plant</b>	All OLC Cross Hole Identification at the final Inspection stage Before Dispatch to the Customer

## 12. Document Review

<b>Documents</b>	ControlPlan
<b>Specify Other Document</b>	No Need

## 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	300
<b>Reason for submission</b>	Verified next 3 lot and found ok