

## Defect Details

<b>NC No.</b>	8000807947
<b>NC Date</b>	17/10/2022
<b>NC Submission Date</b>	
<b>Part No.</b>	S2BG02502B
<b>Part Name</b>	BRACKET UN P/C KTEP
<b>Supplier Name &amp; Code</b>	100973-TESMO MOTORCAST PRIVATE LIMITE
<b>ETL Plant</b>	1116-ETL K-120 Suspension
<b>Defect Details</b>	THREADING NOT OK-THREADING NOT OK

## 1. Problem Description

<b>Defect Description</b>	Bracket KTEP observed with threading not ok concern. In every month major qty. rejected for same.
<b>Detection Stage</b>	Receipt
<b>Problem Severity</b>	Fitment
<b>NG Quantity</b>	967
<b>Is Defect Repeatative?</b>	Yes
<b>Defect Sketch / Photo</b>	

## Supplier Communication Details

<b>Quality Head Email ID</b>	rkhare@tesmomotorcast.com
<b>Plant Head/CEO Email ID</b>	harish.bala@tesmomotorcast.com
<b>MD Email ID</b>	svkallani@tesmomotorcast.com

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	767	0	0	0	0	767
<b>Check Qty</b>	767	0	0	0	0	767
<b>NG Qty</b>	767	0	0	0	0	767

## Action taken on NG part

<b>Scrap</b>	500
<b>Rework</b>	100
<b>Under Deviation</b>	67

## Containment Action

core pin bend issue

## 3. Process Flow

**Process Flow Description**

pdc , debering ,remer , vibro ,chamfer ,taping , air claning ,pack

**4. Process Details**

<b>Process / Operation</b>	pdc,debering ,remer ,vibro ,chamfer ,taping
<b>Outsource</b>	No
<b>Machine / Cell</b>	pdc
<b>Machine / Cell No.</b>	pdc 250 1

**5. Problem Analysis**

Type	Possible Cause	Fact Verification	Jud
Tool	core pin bend	Gauge	O
Material	core pin hardness not ok	hardness testing report check	O

**6. Inspection Method Analysis (Current)**

<b>Inspection Method</b>	Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	Sampling
<b>Sampling</b>	No
<b>Sample Size</b>	every hrs

**7. Root Cause Analysis (Occurance)**

<b>Why 1</b>	Tap not gone up to required depth
<b>Why 2</b>	Tap jam while completing its cycle
<b>Why 3</b>	Hole pin perpendicularity not ok
<b>Why 4</b>	Die core pin bend
<b>Why 5</b>	Pin hardness not as per requirement
<b>Root Cause (Occurance)</b>	Core pin hardness not freeze.

**Root Cause Analysis (Outflow)**

<b>Why 1</b>	Tap not gone up to required depth
<b>Why 2</b>	Tap jam while completing its cycle
<b>Why 3</b>	Hole pin perpendicularity not ok
<b>Why 4</b>	Die core pin perpendicularity not ok
<b>Why 5</b>	Perpendicularity not check
<b>Root Cause (Outflow)</b>	Core pin Perpendicularity checking frequency not defined.

**8. Countermeasure ( Occurrence , Outflow & System side Actions )**

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
------	------------------------	----------------	-------------	-------------	--------

Outflow	hourly pin hole perpendicularity checking	Rahul	06/07/2023	25/06/2023	Completed
Occurance	Pin hardness freeze	Ravi	10/07/2023	26/06/2023	Completed

## 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	Yes
<b>Change Details</b>	Perpendicularity checking started on hourly check on PDC
<b>Inspection Method</b>	Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	Sampling
<b>Sampling</b>	No
<b>Sample Size</b>	1000

## 10. Evidance of Countermeasure

<b>Occurance (Before)</b>	Core pin bend <a href="#">290_Occurance_Before.jpg</a>
<b>Occurance (After)</b>	Due to the pin bend, taping was not done untill the end. <a href="#">290_Occurance_After.jpg</a>
<b>Outflow (Before)</b>	Guaege install <a href="#">290_Outflow_Before.jpg</a>
<b>Outflow (After)</b>	Guaege checking strat <a href="#">290_Outflow_After.jpg</a>

## 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	Yes
<b>Applicable Machine / Model / Plant</b>	Pdc 250 t 1 KTEP Bracket

## 12. Document Review

<b>Documents</b>	JHCheckSheet, InspCheckSheet
<b>Specify Other Document</b>	Pm check sheet, Ins

## 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	
<b>Reason for submission</b>	