

## Defect Details

<b>NC No.</b>	8000808079
<b>NC Date</b>	17/10/2022
<b>NC Submission Date</b>	
<b>Part No.</b>	S2HT68607B
<b>Part Name</b>	OUTER SPRING K23L
<b>Supplier Name &amp; Code</b>	101069-SAGAR SPRINGS PVT LTD
<b>ETL Plant</b>	1116-ETL K-120 Suspension
<b>Defect Details</b>	HOOK MARK-TOUCHUP NOT OK

## 1. Problem Description

<b>Defect Description</b>	Powder coating observed not OK in almost all model & on daily basis. In K23L Outer spring supplied for expert, due to hook mark concern, end customer raising complaint on frequently.
<b>Detection Stage</b>	Inprocess
<b>Problem Severity</b>	Aesthetic
<b>NG Quantity</b>	28
<b>Is Defect Repeatative?</b>	Yes
<b>Defect Sketch / Photo</b>	

## Supplier Communication Details

<b>Quality Head Email ID</b>	quality@sagarsprings.com
<b>Plant Head/CEO Email ID</b>	ajai.singh@sagarsprings.com
<b>MD Email ID</b>	sagar@sagarsprings.com

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	1500	5000	0	1600	0	8100
<b>Check Qty</b>	1500	5000	0	1600	0	8100
<b>NG Qty</b>	28	450	0	100	0	578

## Action taken on NG part

<b>Scrap</b>	0
<b>Rework</b>	578
<b>Under Deviation</b>	0

## Containment Action

Segregation carried out at warehouse as well as FG and spring hook mark reworked

## 3. Process Flow

## Process Flow Description

Coiling – Tempering – Grinding - Shot Pinning – Tempering – Scragging – Sq correction/ht checking –Pre treatment-Powder coating- Inspection-Dispatch

## 4. Process Details

<b>Process / Operation</b>	Inspection
<b>Outsource</b>	No
<b>Machine / Cell</b>	Inspection and touch up table
<b>Machine / Cell No.</b>	130

## 5. Problem Analysis

Type	Possible Cause	Fact Verification	Jud
Material	Improper hook	Found hook used are of appropriate design	O
Method	Spring not hanged properly	Spring are hanged properly on hanger and locked properly	O
Material	Hook get deformed while locking of spring	In case of using used hook, some time hook shape get deformed	X
Method	Used hook with powder used	Found hook used are bared not powder coated	O
Man	Loading person negligence	Found some loading operators not properly loading spring	X

## 6. Inspection Method Analysis (Current)

<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	Visual Inspection
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100%

## 7. Root Cause Analysis (Occurance)

<b>Why 1</b>	Hook get deformed while locking of spring
<b>Why 2</b>	Hook strength of some hooks get weakens because of excessive reuse
<b>Why 3</b>	Used hook with more than 4 cycle get mixed
<b>Why 4</b>	
<b>Why 5</b>	
<b>Root Cause (Occurance)</b>	Used hook with more than 4 cycle get mixed with other hook

## Root Cause Analysis (Outflow)

<b>Why 1</b>	Spring is not hanged properly and locked properly
<b>Why 2</b>	Loading operator negilgence
<b>Why 3</b>	Absence of awareness in loading person
<b>Why 4</b>	
<b>Why 5</b>	
<b>Root Cause (Outflow)</b>	Absence of awareness in loading person result in improper loading

## 8. Countermeasure ( Occurrence , Outflow & System side Actions )

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Occurance	Proper arrangement of hook made to identify it burning frequency and it status	PC-Supervisor	22/10/2022	22/10/2022	Completed
Outflow	Refresher training will be given to loading operator for checking loading pattern and proper locking	PC-Supervisor	19/10/2022	19/10/2022	Completed

## 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	Yes
<b>Change Details</b>	Proper visual inspection at loading stage
<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	Visual inspection
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100%

## 10. Evidence of Countermeasure

<b>Occurance (Before)</b>	Hook of more than 3 burnt get mix and deformed hook get used on line <a href="#">287_Occurance_Before.pdf</a>
<b>Occurance (After)</b>	Hook are properly tracked and it freq could be identified it remain well arranged <a href="#">287_Occurance_After.pdf</a>
<b>Outflow (Before)</b>	Lack of awareness to Loading person and Inspector <a href="#">287_Outflow_Before.pdf</a>
<b>Outflow (After)</b>	Operators and inspectors are well understood and loading spring properly and identify hook mark defective spring <a href="#">287_Outflow_After.pdf</a>

## 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	Yes
<b>Applicable Machine / Model / Plant</b>	Applicable to all the powder coated springs

## 12. Document Review

<b>Documents</b>	ControlPlan, PFMEA, WISOP
<b>Specify Other Document</b>	OPL

## 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	1000
<b>Reason for submission</b>	Completed

