Defect Details

NC No.	8000808405
NC Date	19/10/2022
NC Submission Date	
Part No.	F2BF26773B
Part Name	KONA CBS OUTER TUBE CAST RH
Supplier Name & Code	101262-SUNBEAM LIGHTWEIGHTING SOLUTIO
ETL Plant	1116-ETL K-120 Suspension
Defect Details	CENTRE DIST. NOT OKAXEL HOLE SHIFT

1. Problem Description

Defect Description	Wall thickness variation concern reported with major rejection qty.
Detection Stage	Inprocess
Problem Severity	Fitment
NG Quantity	269
Is Defect Repeatative?	Yes
Defect Sketch / Photo	

Supplier Communication Details

Quality Head Email ID	deepak.rana@sunbeamauto.com
Plant Head/CEO Email ID	anoop.gupta@sunbeamauto.com
MD Email ID	

2. Stock Details & action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
Total Qty	715	478	0	876	521	2590
Check Qty	715	478	0	870	521	2584
NG Qty	0	0	0	6	0	6

Action taken on NG part

Scrap	6
Rework	0
Under Deviation	0

Containment Action

casting should be catch on FI stage (oil seal coller wall 100% checked by vernier)

3. Process Flow

Process Flow Description

"1.Alloy Preparation 2.Degassing & Defluxing 3.Casting 4.Riser Cutting 5.Fettling & Filing 6.Leak Testing 7.Final Inspection " "1.Alloy Preparation 2.Degassing & Defluxing 3.Casting 4.Riser Cutting 5.Fettling & Filing 6.Leak Testing 7.Final Inspection " 1.alloy preparation 2.degassing and defuxing 3.casting 4.riser cutting 5.fettling and filling 6.leak testing 7.final inspection

4. Process Details

Process / Operation	casting
Outsource	No
Machine / Cell	gdc/domestic
Machine / Cell No.	6 and 8

5. Problem Analysis

Туре	Possible Cause	Fact Verification	Jud
Machine	hydraulic pressure low	found pressure low	Х

6. Inspection Method Analysis (Current)

Inspection Method	Sp. Gauge
Other Inspection Method	
Check Point at Final Inspection	Yes
Checking Freq.	100%
Sampling	No
Sample Size	100%

7. Root Cause Analysis (Occurance)

Why 1	Flash observed at parting line area
Why 2	Die was not closing
Why 3	Hydrulic pressure low
Why 4	Cylinder leakage due to core holder was shaking .
Why 5	Core holder change frequency was not deciding in pm plan cheek sheet .
Root Cause (Occurance)	Core holder change frequency was not deciding in pm plan cheek sheet .

Root Cause Analysis (Outflow)

Why 1	Oil Seal area wall thickness ng
Why 2	Process and final inspector in this problem not captured.
Why 3	No check point avaiable in set up sheet and final work instruction sheet .
Why 4	
Why 5	
Root Cause (Outflow)	No check point available in set up sheet and final work instruction sheet .

8. Countermeasure (Occurrence, Outflow & System side Actions)

Туре	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
------	------------------------	----------------	-------------	-------------	--------

Occurance	Holder change frequency decided as per PM check sheet	kishore/mukesh	05/11/2022	Completed	
Outflow	check point add in process quality & final inspection	kishore/mukesh	21/10/2022	Completed	

9. Inspection Method After Customer Complaint

Change In Inspection System	Yes
Change Details	100% part inspection before dispatch
Inspection Method	Instrument
Other Inspection Method	
Check Point at Final Inspection	Yes
Checking Freq.	100%
Sampling	No
Sample Size	100%

10. Evidance of Countermeasure

Occurance (Before)	Earlier core holder frequency not defined 292_Occurance_Before.pdf
Occurance (After)	Holder change frequency decided as per PM check sheet 292_Occurance_After.pdf
Outflow (Before)	No check point avaiable in set up sheet and final work instruction sheet . 292_Outflow_Before.pdf
Outflow (After)	check point add in process quality & final inspection 292_Outflow_After.pdf

11. Horizontal Deployment

Horizontal Deployment Required	Yes
Applicable Machine / Model / Plant	08/kona/101262

12. Document Review

Documents	ControlPlan, PMCheckSheet, WISOP, InspCheckSheet
Specify Other Document	na

13. Effectiveness Of Action

Reviewed Quantity	100
Reason for submission	No any re-occurance.