

## Defect Details

<b>NC No.</b>	8000811623
<b>NC Date</b>	22/11/2022
<b>NC Submission Date</b>	
<b>Part No.</b>	F2DZ09002B
<b>Part Name</b>	FORK BOLT -K17E
<b>Supplier Name &amp; Code</b>	100189-SANGKAJ STEEL PVT LTD.
<b>ETL Plant</b>	1117-ETL K-228/9 Suspension
<b>Defect Details</b>	NOT AS PER SPECIFICATION-M6 NO-GO PASS

## 1. Problem Description

<b>Defect Description</b>	M6 No-Go Pass in fork bolt
<b>Detection Stage</b>	Receipt
<b>Problem Severity</b>	Fitment
<b>NG Quantity</b>	310
<b>Is Defect Repeative?</b>	Yes
<b>Defect Sketch / Photo</b>	<a href="#">zm1kgsmtm0a3zv0hsp4bmvd.pptx</a>

## Supplier Communication Details

<b>Quality Head Email ID</b>	qualityassurance@sangkaj.com
<b>Plant Head/CEO Email ID</b>	steel@sangkaj.com
<b>MD Email ID</b>	anirudh.2007@hotmail.com

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	310	0	0	500	1000	1810
<b>Check Qty</b>	310	0	0	500	1000	1810
<b>NG Qty</b>	5	0	0	0	0	5

## Action taken on NG part

<b>Scrap</b>	5
<b>Rework</b>	0
<b>Under Deviation</b>	0

## Containment Action

Lot booked after found 5 nos NG at inward end, also re-verified the in-house stock.

## 3. Process Flow

**Process Flow Description**

Inward Inspection &gt; Forging blank &gt; CNC 1ST &gt; CNC 2nd &gt; Drilling &gt; Tapping &gt; Rolling &gt; Plating &gt; Final Inspection

**4. Process Details**

<b>Process / Operation</b>	Drilling
<b>Outsource</b>	No
<b>Machine / Cell</b>	Tapping
<b>Machine / Cell No.</b>	1

**5. Problem Analysis**

Type	Possible Cause	Fact Verification	Jud
Machine	Collet Wear out	Drill fitment issue	X

**6. Inspection Method Analysis (Current)**

<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	Sampling basis (DV)
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	Sampling
<b>Sampling</b>	No
<b>Sample Size</b>	5 OUT 100

**7. Root Cause Analysis (Occurance)**

<b>Why 1</b>	Drill ID O/S
<b>Why 2</b>	Drill Overhanging
<b>Why 3</b>	Play in collet
<b>Why 4</b>	Collet wear out
<b>Why 5</b>	
<b>Root Cause (Occurance)</b>	Collet wear out found

**Root Cause Analysis (Outflow)**

<b>Why 1</b>	NG Piece not traced in sampling basis
<b>Why 2</b>	sampling frequency found less
<b>Why 3</b>	
<b>Why 4</b>	
<b>Why 5</b>	
<b>Root Cause (Outflow)</b>	sampling frequency at FID found less

**8. Countermeasure ( Occurrence , Outflow & System side Actions )**

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
	Collet replaced with new one having close clamping				

Occurance	having facility of clamp more area of drill bit. so that overhanging possibility get eliminate	Mr. Raut Sir	24/11/2022	23/11/2022	Completed
-----------	--	--------------	------------	------------	-----------

## 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	Yes
<b>Change Details</b>	Sampling frequency increased to 10 %
<b>Inspection Method</b>	Sp. Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	Sampling
<b>Sampling</b>	No
<b>Sample Size</b>	10

## 10. Evidence of Countermeasure

<b>Occurance (Before)</b>	Collet Wear Out drill bit overhanging due to clamping area less. <a href="#">312_Occurance_Before.pptx</a>
<b>Occurance (After)</b>	Collet replaced with new one having close clamping having facility of clamp more area of drill bit. so that overhanging possibility get eliminate. <a href="#">312_Occurance_After.pptx</a>
<b>Outflow (Before)</b>	5 % Inspection from lot <a href="#">312_Outflow_Before.jpeg</a>
<b>Outflow (After)</b>	10 % Inspection from lot <a href="#">312_Outflow_After.jpeg</a>

## 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	No
<b>Applicable Machine / Model / Plant</b>	Drilling M/c

## 12. Document Review

<b>Documents</b>	InspCheckSheet
<b>Specify Other Document</b>	FID Checksheet

## 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	300
<b>Reason for submission</b>	Kindly maintain the same in further production.