

Defect Details

NC No.	8000813285
NC Date	07/12/2022
NC Submission Date	
Part No.	550LG00602
Part Name	SEAT PIPE JB
Supplier Name & Code	100648-JOTIBA TECHNOLOGIES PVT.LTD.
ETL Plant	1117-ETL K-228/9 Suspension
Defect Details	NOT AS PER SPECIFICATION-HEX ID FOUND UNDERSIZE

1. Problem Description

Defect Description	Hex ID found undersize
Detection Stage	Receipt
Problem Severity	Fitment
NG Quantity	16
Is Defect Repeatative?	No
Defect Sketch / Photo	

Supplier Communication Details

Quality Head Email ID	accjotiba@gmail.com
Plant Head/CEO Email ID	sanghavi.rajesh@sanghavigroup.co.in
MD Email ID	jotibatech@gmail.com

2. Stock Details & action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
Total Qty	6000	0	0	1500	1000	8500
Check Qty	6000	0	0	1500	1000	8500
NG Qty	16	0	0	0	0	16

Action taken on NG part

Scrap	0
Rework	16
Under Deviation	0

Containment Action

ID inspection with hex plug gauge as per sampling plan

3. Process Flow

Process Flow Description

10. RM Inspection,20.Parting off,30.Chmafering,40.Weighing,50.Draw forging,60.Hex Forging,70.Rough Grinding, 80.Collar Machining,90.Total length facing and boring, 100 Piercing, 110.DF hole Chamfer, 120.Compression hole Chamfer, 130.ID Reaming, 140.Tapping, 150.Finish Grinding, 160.Final Inspection, 170.ID brush Cleaning, 180.Ultrasonic Cleaning, 190.Apply antirust oil, 200.Packing and dispatch.

4. Process Details

Process / Operation	60.Hex forging
Outsource	No
Machine / Cell	Header
Machine / Cell No.	H-001

5. Problem Analysis

Type	Possible Cause	Fact Verification	Jud
Tool	Tool and die center not align	ok	O

6. Inspection Method Analysis (Current)

Inspection Method	Other
Other Inspection Method	Visual
Check Point at Final Inspection	Yes
Checking Freq.	Sampling
Sampling	No
Sample Size	sample pla

7. Root Cause Analysis (Occurance)

Why 1	Id undersize produces
Why 2	due to id burr
Why 3	punch damage
Why 4	center not align.
Why 5	
Root Cause (Occurance)	Due to die and punch center not align, punch got damaged and Id undersize produced.

Root Cause Analysis (Outflow)

Why 1	ID undersize not detected at outflow
Why 2	No inspection in outflow.
Why 3	
Why 4	
Why 5	
Root Cause (Outflow)	due to no inspection at outflow this issue not detected.

8. Countermeasure (Occurrence , Outflow & System side Actions)

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
------	------------------------	----------------	-------------	-------------	--------

Occurance	Center alignment checking while setup.	Mr.gore	31/12/2022	31/12/2022	Completed
Outflow	Id inspection with plug gauge as per sampling plan.	Mr.Gore	18/01/2023	17/01/2023	Completed

9. Inspection Method After Customer Complaint

Change In Inspection System	Yes
Change Details	By using plug gauge
Inspection Method	Gauge
Other Inspection Method	
Check Point at Final Inspection	Yes
Checking Freq.	Sampling
Sampling	No
Sample Size	chart

10. Evidence of Countermeasure

Occurance (Before)	No setup verification of alignment 319_Occurance_Before.jpg
Occurance (After)	alignment verification in setup approval. 319_Occurance_After.jpg
Outflow (Before)	ID dent damage only sampling 319_Outflow_Before.jpg
Outflow (After)	ID dent and damage visual inspection 100%. 319_Outflow_After.jpg

11. Horizontal Deployment

Horizontal Deployment Required	No
Applicable Machine / Model / Plant	NA

12. Document Review

Documents	
Specify Other Document	Punch drawing

13. Effectiveness Of Action

Reviewed Quantity	100
Reason for submission	Ok. Next 3 lot inspected and no defect found