

## Defect Details

<b>NC No.</b>	8000820736
<b>NC Date</b>	16/02/2023
<b>NC Submission Date</b>	
<b>Part No.</b>	16JPP00117
<b>Part Name</b>	WHEEL CLUTCH REML 6 PLATE / 7 PLATE
<b>Supplier Name &amp; Code</b>	101100-CAST 4 ALUMINIUM PVT LTD
<b>ETL Plant</b>	1132-ETL K-226/1 TRANSMISSION
<b>Defect Details</b>	TAPPING O/SIZE.-TAPPING OVER SIZE

## 1. Problem Description

<b>Defect Description</b>	Threading Oversize *Minor Dia found oversize up to 6.02 mm against 5.13 mm)
<b>Detection Stage</b>	Inprocess
<b>Problem Severity</b>	Fitment
<b>NG Quantity</b>	3
<b>Is Defect Repeatative?</b>	Yes
<b>Defect Sketch / Photo</b>	<a href="#">oalbh4q0u5jzjx4ubsgt2ova.jpg</a>

## Supplier Communication Details

<b>Quality Head Email ID</b>	info@cast4aluminium.com
<b>Plant Head/CEO Email ID</b>	info@cast4aluminium.com
<b>MD Email ID</b>	kiran@cast4aluminium.com

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	900	990	1050	5322	2250	10512
<b>Check Qty</b>	900	990	1050	5322	2250	10512
<b>NG Qty</b>	18	6	5	14	2	45

## Action taken on NG part

<b>Scrap</b>	45
<b>Rework</b>	0
<b>Under Deviation</b>	0

## Containment Action

1.Spindle head height increase by 12mm. 2. Inspection frequency increases to 100%. 3) Plug gauge provided for checking minor dia.

## 3. Process Flow

## 4. Process Details

<b>Process / Operation</b>	Drilling & Tapping
<b>Outsource</b>	No
<b>Machine / Cell</b>	Machine No-05
<b>Machine / Cell No.</b>	Machine No-05

## 5. Problem Analysis

Type	Possible Cause	Fact Verification	Jud
Method	During the drilling operation drilling loose burr was stuck on drill, due to this burr hole get cut.	Observed burr on drill.	O
Method	Coolant flow observed improper, due to improper coolant flow material get stuck on drill.	Coolant not flow to all drill.	O
Method	Coolant flow observed in lower side (3% to 4%) due that drill get heat during drilling operation.	Coolant concentration observed 3.5%.	O
Method	100 % inspection observed with minor dia plug gauge without identification marking.	Marking not available on parts.	O

## 6. Inspection Method Analysis (Current)

<b>Inspection Method</b>	Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100%

## 7. Root Cause Analysis (Occurance)

<b>Why 1</b>	Minor diameter of REML Wheel was observed 6.04 mm against 4.92 mm.
<b>Why 2</b>	During the drilling operation loose burr was stuck on drill, due to this burr hole get cut excess in drilling.
<b>Why 3</b>	Coolant flow observed improper, due to improper coolant flow material get stuck on drill.
<b>Why 4</b>	Coolant concentration observed in lower side ( 3% to 4%), due to the coolant concentration drill get heat.
<b>Why 5</b>	
<b>Root Cause (Occurance)</b>	Coolant flow observed improper, due to improper coolant flow material get stuck on drill.

## Root Cause Analysis (Outflow)

<b>Why 1</b>	Part knowledge not found evident to final inspector.
<b>Why 2</b>	Inspection frequency observed on sample basis.
<b>Why 3</b>	100% inspection observed by using minor diameter plug gauge without identification marking
<b>Why 4</b>	
<b>Why 5</b>	

**Root Cause (Outflow)**

100% inspection observed by using minor diameter plug gauge without identification marking, so we found the owner ship missing.

## 8. Countermeasure ( Occurrence , Outflow & System side Actions )

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Occurance	We have increase the coolant pipe & coolant flow.	Mr. Datta Moin.	22/02/2023	21/02/2023	Completed
Occurance	We started to maintained the coolant concentration in higher side 5% to 6 %.	Mr. Datta Moin.	22/02/2023	21/02/2023	Completed
Outflow	Training & awareness provided to final inspector & operator.	Mr. Mahesh ghadmode.	22/02/2023	21/02/2023	Completed
Outflow	We started 100% inspection for minor diameter checking with plug gauge with 100% identification marking.	Mr. Mahesh ghadmode.	21/02/2023	20/02/2023	Completed

## 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	Yes
<b>Change Details</b>	We started 100% inspection for minor diameter checking with plug gauge.
<b>Inspection Method</b>	Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100%

## 10. Evidance of Countermeasure

<b>Occurance (Before)</b>	Coolant flow is improper or not sufficient for drilling operation. <a href="#">371_Occurance_Before.xlsx</a>
<b>Occurance (After)</b>	Provided the proper coolant flow with maintained coolant concentration 5% to 6% & we started the coolant concentration monitoring on production report. <a href="#">371_Occurance_After.jpg</a>
<b>Outflow (Before)</b>	Sample basis inspection 10 nos per hours. <a href="#">371_Outflow_Before.xlsx</a>
<b>Outflow (After)</b>	Started 100% inspection by using plug gauge. <a href="#">371_Outflow_After.jpg</a>

## 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	Yes
<b>Applicable Machine / Model / Plant</b>	3W4S Wheel & K70 Wheel SPM Machine.

## 12. Document Review

<b>Documents</b>	ControlPlan, InspCheckSheet
<b>Specify Other Document</b>	no

### 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	2000
<b>Reason for submission</b>	OK