

## Defect Details

<b>NC No.</b>	8000822306
<b>NC Date</b>	01/03/2023
<b>NC Submission Date</b>	
<b>Part No.</b>	B2TD00626O
<b>Part Name</b>	ANCHOR PIN 9 MM DIA - REML
<b>Supplier Name &amp; Code</b>	100846-SANGKAJ ENGINEERING PVT.LTD.
<b>ETL Plant</b>	1156-ETL Disc Brake P'Nagar
<b>Defect Details</b>	DIMN.U/SIZE.-OPERATION MISS

## 1. Problem Description

<b>Defect Description</b>	operation miss & wrong thread pieces received
<b>Detection Stage</b>	Receipt
<b>Problem Severity</b>	Fitment
<b>NG Quantity</b>	22
<b>Is Defect Repeatative?</b>	Yes
<b>Defect Sketch / Photo</b>	

## Supplier Communication Details

<b>Quality Head Email ID</b>	aslam@sangkaj.com
<b>Plant Head/CEO Email ID</b>	pardeshinr@sangkaj.com
<b>MD Email ID</b>	anirudh.2007@hotmail.com

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	5480	0	0	0	0	5480
<b>Check Qty</b>	4000	0	0	0	0	4000
<b>NG Qty</b>	22	0	0	0	0	22

## Action taken on NG part

<b>Scrap</b>	22
<b>Rework</b>	0
<b>Under Deviation</b>	0

## Containment Action

Segregation done at ETL-Pantnagar End

## 3. Process Flow

**Process Flow Description**

Raw material inward-wire draw-cold forging-CNC machining-Rolling-Heat treatment-plating-final inspection-PDI-dispatch

**4. Process Details**

<b>Process / Operation</b>	Cold forging
<b>Outsource</b>	No
<b>Machine / Cell</b>	Cold forging
<b>Machine / Cell No.</b>	19B4S

**5. Problem Analysis**

Type	Possible Cause	Fact Verification	Jud
Machine	Semi finished part fallen down in chute and got mix with OK parts at cold forging stage.	Cause verified.	O

**6. Inspection Method Analysis (Current)**

<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	Visual
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100%

**7. Root Cause Analysis (Occurance)**

<b>Why 1</b>	Anchor pin 9mm, dimn U/S and operation missing found at ETL
<b>Why 2</b>	Incomplete operation part found with ok parts
<b>Why 3</b>	Part fallen down through 3rd station ,where 4th station is final station.
<b>Why 4</b>	Part skipped through part shifting fingers.
<b>Why 5</b>	Fingers worn out.
<b>Root Cause (Occurance)</b>	Part shifting fingers worn out.

**Root Cause Analysis (Outflow)**

<b>Why 1</b>	Anchor pin 9mm, dimn U/S and operation missing found at ETL
<b>Why 2</b>	NG parts got mixed with Ok parts at final inspection.
<b>Why 3</b>	Final inspection is carried out visually.
<b>Why 4</b>	At visual inspection more than one part holding in hand by inspector.
<b>Why 5</b>	Part holding method while doing visual inspection is wrong.
<b>Root Cause (Outflow)</b>	Part holding method while doing visual inspection is wrong.

**8. Countermeasure ( Occurrence , Outflow & System side Actions )**

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
------	------------------------	----------------	-------------	-------------	--------

Occurance	Work instruction reviewed and updated to ensure condition of fingers.	Mr. Shrikant Magar	20/03/2023	16/03/2023	Completed
Outflow	OPL displayed to ensure one part at a time should be hold.	Aslam Shaikh	15/03/2023	15/03/2023	Completed

## 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	Yes
<b>Change Details</b>	Part holding method has been changed , now only one part at a time is being hold while doing visual inspection.
<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	visual
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100%

## 10. Evidence of Countermeasure

<b>Occurance (Before)</b>	Assuring of condition of fingers of cold forging was not in process as not mentioned in WI for setup. <a href="#">383_Occurance_Before.pdf</a>
<b>Occurance (After)</b>	WI updated and training also provided to assure condition of fingers of cold forging machine <a href="#">383_Occurance_After.pdf</a>
<b>Outflow (Before)</b>	No instruction for visual inspection of individual part. <a href="#">383_Outflow_Before.pdf</a>
<b>Outflow (After)</b>	OPL provided for visual inspection to educate for proper material inspection. <a href="#">383_Outflow_After.pdf</a>

## 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	Yes
<b>Applicable Machine / Model / Plant</b>	Anchor pin 8mm

## 12. Document Review

<b>Documents</b>	ControlPlan, PFMEA, WISOP
<b>Specify Other Document</b>	no

## 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	50
<b>Reason for submission</b>	done