

## Defect Details

<b>NC No.</b>	8000827592
<b>NC Date</b>	26/04/2023
<b>NC Submission Date</b>	
<b>Part No.</b>	F1LG00902B
<b>Part Name</b>	SEAT PIPE -K86A
<b>Supplier Name &amp; Code</b>	100538-NARINDER PARKASH AND CO
<b>ETL Plant</b>	1146-ETL Suspension Narasapura
<b>Defect Details</b>	LENGTH UNDERSIZE-TOTAL LENGHT LESS

## 1. Problem Description

<b>Defect Description</b>	Seat pipe total length less issue
<b>Detection Stage</b>	Inprocess
<b>Problem Severity</b>	Fitment
<b>NG Quantity</b>	2
<b>Is Defect Repeatative?</b>	Yes
<b>Defect Sketch / Photo</b>	<a href="#">myxhb1uoyxroq2e4tssk4rhv.jpg</a>

## Supplier Communication Details

<b>Quality Head Email ID</b>	quality@npcindustries.in
<b>Plant Head/CEO Email ID</b>	anand@npcindustries.in
<b>MD Email ID</b>	ajay@npcindustries.in

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	4000	0	0	2000	0	6000
<b>Check Qty</b>	4000	0	0	4	0	4004
<b>NG Qty</b>	2	0	0	4	0	6

## Action taken on NG part

<b>Scrap</b>	6
<b>Rework</b>	0
<b>Under Deviation</b>	0

## Containment Action

Segregated all parts at ETL, at Warehouse & at NPC Nabha.

## 3. Process Flow

### Process Flow Description

1.Raw Material 2.Cutting & Chamfering 3. Multistation Draw 4.Head Formation 5.Rough Grinding 6.Punching 7.CNC Head Turning 8.CNC Boring & Facing 9.Tapping 10. Chamfering 1&2 11.Finish Grinding 12.Final Inspection 13.Cleaning 14.Oiling 15.Packing & Dispatch

## 4. Process Details

<b>Process / Operation</b>	CNC Boring
<b>Outsource</b>	No
<b>Machine / Cell</b>	CNC
<b>Machine / Cell No.</b>	CNC-04

## 5. Problem Analysis

Type	Possible Cause	Fact Verification	Jud
Material	Material hardness less/more	After verification we found material Hardness as per spec.	O
Method	Other model mixed during processing	after verification We found material was ok.	O
Machine	Cnc Program was tampered	After verification we found CNC program was ok as per drawing.	O
Method	vernier not calibrated	after Verification vernier was Calibrated	O
Method	Material clamping method inadequate	After verification we found material clamping method inadequate.	X

## 6. Inspection Method Analysis (Current)

<b>Inspection Method</b>	Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	No
<b>Checking Freq.</b>	Sampling
<b>Sampling</b>	No
<b>Sample Size</b>	as per CP

## 7. Root Cause Analysis (Occurance)

<b>Why 1</b>	seatpipe total length Less
<b>Why 2</b>	seat pipe did not proper fit in collet.
<b>Why 3</b>	Part did not clamp as per requirement.
<b>Why 4</b>	Chips stucked with stopper pin
<b>Why 5</b>	no proper cleaning during operation
<b>Root Cause (Occurance)</b>	no proper cleaning during operation

## Root Cause Analysis (Outflow)

<b>Why 1</b>	seatpipe total length Less
<b>Why 2</b>	Could not be detected at final inspection
<b>Why 3</b>	Skipped in Sampling at Final Inspection
<b>Why 4</b>	Sampling quantity was less
<b>Why 5</b>	
<b>Root Cause (Outflow)</b>	Sampling quantity was less

## 8. Countermeasure ( Occurrence , Outflow & System side Actions )

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Outflow	100% inspection during final inspection	Mr. Ankush	29/04/2023	28/04/2023	Completed
Occurance	freezed cleaning frequency by Air gun during operation.	Mr. Gurpreet Singh	29/04/2023	28/04/2023	Completed

## 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	Yes
<b>Change Details</b>	100% Inspection During final inspection.
<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	Use Flat plate
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100%

## 10. Evidance of Countermeasure

<b>Occurance (Before)</b>	Chips stucked with stopper <a href="#">433_Occurance_Before.jpeg</a>
<b>Occurance (After)</b>	freezed cleaning frequency by Air gun during operation. <a href="#">433_Occurance_After.jpeg</a>
<b>Outflow (Before)</b>	We checked with sampling inspection By Digital vernier <a href="#">433_Outflow_Before.jpeg</a>
<b>Outflow (After)</b>	Increase sampling quantity at work station & use of surface flat for length checking at final inspection <a href="#">433_Outflow_After.png</a>

## 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	No
<b>Applicable Machine / Model / Plant</b>	CNC Machine

## 12. Document Review

<b>Documents</b>	ControlPlan, PFMEA, WISOP, InspCheckSheet
<b>Specify Other Document</b>	No

## 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	2000
<b>Reason for submission</b>	Reviewed 2000 no's found ok

