Defect Details

NC No.	8000827791
NC Date	28/04/2023
NC Submission Date	
Part No.	F2PH00902B
Part Name	VALVE RETAINER (C101B)
Supplier Name & Code	101255-MAHAVIR INDUSTRIES
ETL Plant	1146-ETL Suspension Narasapura
Defect Details	RUSTY-RUST ISSUE

1. Problem Description

Defect Description	valve retainer rust issue
Detection Stage	Receipt
Problem Severity	Aesthetic
NG Quantity	1000
Is Defect Repeatative?	No
Defect Sketch / Photo	hu2g3xnwwdoxzi2mq5cqmlnm.jpg

Supplier Communication Details

Quality Head Email ID	quality@mahavirind.co.in
Plant Head/CEO Email ID	production@mahavirind.co.in
MD Email ID	

2. Stock Details & action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
Total Qty	6000	6000	0	0	0	12000
Check Qty	6000	6000	0	0	0	12000
NG Qty	1000	0	0	0	0	1000

Action taken on NG part

Scrap	1000
Rework	0
Under Deviation	0

Containment Action

All Material Check at the Customer End and Warehouse End.

3. Process Flow

Process Flow Description

RM inward - store - Parting - Semi finish Inward - CNC (Counter ID Machining) - OD Grinding- Plating - Final Inspection - Packing - Dispatch - Transportwarehouse- Customer Received

4. Process Details

Process / Operation	Varehouse Loading - Unloading Handling Problem	
Outsource	No	
Machine / Cell	Narsapura Warehouse	
Machine / Cell No.	Narsapura Warehouse	

5. Problem Analysis

Туре	Possible Cause	Fact Verification	Jud
------	----------------	-------------------	-----

6. Inspection Method Analysis (Current)

Inspection Method	Other
Other Inspection Method	Visual
Check Point at Final Inspection	Yes
Checking Freq.	100%
Sampling	No
Sample Size	100%

7. Root Cause Analysis (Occurance)

Why 1	Rusty
Why 2	Finish Good Material Wet at warehouse
Why 3	Finish Good Lying On Shop floor
Why 4	Packing Bag Torn of finish good
Why 5	Improper Material Handling
Root Cause (Occurance)	Packing Bag Torn of finish good

Root Cause Analysis (Outflow)

Why 1	Rusty	
Why 2	nish Good Material More No. of days lying at transport Godown	
Why 3	Inform To godown person	
Why 4		
Why 5		
Root Cause (Outflow)	Finish Good Material More No. of days lying at transport Godown	

8. Countermeasure (Occurrence, Outflow & System side Actions)

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status

Occurance	1)Improper Material Handling .2)Finish Good Material	Mahavir QA	10/05/2023	10/05/2023	Completed
	More No. of days lying at transport Godown				

9. Inspection Method After Customer Complaint

Change In Inspection System	Yes
Change Details	1)Packing as per Customer Standards. 2) HDPE white, Heavy thickness and clean Gunny bags use for outer coating packing.
Inspection Method	Other
Other Inspection Method	Packing Visual Obs
Check Point at Final Inspection	Yes
Checking Freq.	100%
Sampling	No
Sample Size	100

10. Evidance of Countermeasure

Occurance (Before)	1)Finish Good Packing Bag Torn at warehouse during Material Handling . 2)Low Thickness Poly Bag. 443_Occurance_Before.xlsx
Occurance (After)	1)Inner poly bag thickness increases up to 400 gauge Instead of 300 Gauge for Tearing problems avoid Suitable to Material Handling. 2)HDPE white , Heavy thickness and clean Gunny bags use for outer coating packing. 443_Occurance_After.xlsx
Outflow (Before)	Finish Good Material More No. of days lying at transport godown 443_Outflow_Before.jpg
Outflow (After)	As per the attached packing standard 443_Outflow_After.xlsx

11. Horizontal Deployment

Horizontal Deployment Required	Yes
Applicable Machine / Model / Plant	Applicable all Narsapur-supplied Parts

12. Document Review

Documents	PackingStd
Specify Other Document	No

13. Effectiveness Of Action

Reviewed Quantity	1000
Reason for submission	Reviewed 1000 no`s found ok