

## Defect Details

<b>NC No.</b>	8000827813
<b>NC Date</b>	28/04/2023
<b>NC Submission Date</b>	
<b>Part No.</b>	F2LG01302B
<b>Part Name</b>	SEAT PIPE -KTEM/KTEL
<b>Supplier Name &amp; Code</b>	100539-N P ENTERPRISES
<b>ETL Plant</b>	1116-ETL K-120 Suspension
<b>Defect Details</b>	MIX UP OTHER MODEL-MIXUP OTHER MODEL

## 1. Problem Description

<b>Defect Description</b>	Total length oversize by 2mm & runout oversize up to 1mm.
<b>Detection Stage</b>	Receipt
<b>Problem Severity</b>	Function
<b>NG Quantity</b>	1230
<b>Is Defect Repeatative?</b>	Yes
<b>Defect Sketch / Photo</b>	

## Supplier Communication Details

<b>Quality Head Email ID</b>	quality@npcindustries.in
<b>Plant Head/CEO Email ID</b>	anand@npcindustries.in
<b>MD Email ID</b>	ajay@npcindustries.in

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	2000	2000	0	0	0	4000
<b>Check Qty</b>	2000	2000	0	0	0	4000
<b>NG Qty</b>	1230	270	0	0	0	1500

## Action taken on NG part

<b>Scrap</b>	1500
<b>Rework</b>	0
<b>Under Deviation</b>	0

## Containment Action

Segregated all parts at ETL, at Warehouse & at NPC Nabha.

## 3. Process Flow

## Process Flow Description

1.Raw Material 2.Cutting & Chamfering 3. Multistation Draw 4.Head Formation 5.Rough Grinding 6.Punching 7.CNC Head Turning 8.CNC Boring & Facing 9.Tapping 10. Chamfering 1&2 11.Finish Grinding 12.Final Inspection 13.Cleaning 14.Oiling 15.Packing & Dispatch

## 4. Process Details

<b>Process / Operation</b>	CNC Boring
<b>Outsource</b>	No
<b>Machine / Cell</b>	CNC
<b>Machine / Cell No.</b>	CNC-06

## 5. Problem Analysis

Type	Possible Cause	Fact Verification	Jud
Method	vernier not calibrated	after Verification vernier was Calibrated	O
Material	Material hardness less/more	After verification we found material Hardness as per spec.	O
Machine	Cnc Program was tampered	After verification we found CNC program was ok as per drawing.	O
Machine	Pin stoper should't loose	after verification We found Pinstoper was loose	X
Method	Material clamping method inadequate	After verification we found material clamping method was correct	O

## 6. Inspection Method Analysis (Current)

<b>Inspection Method</b>	Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	No
<b>Checking Freq.</b>	Sampling
<b>Sampling</b>	No
<b>Sample Size</b>	as per CP

## 7. Root Cause Analysis (Occurance)

<b>Why 1</b>	Seat Pipe Length more
<b>Why 2</b>	seatpipe facing margin was less
<b>Why 3</b>	seat pipe could't be located properly
<b>Why 4</b>	seat pipe head could not touch stoper
<b>Why 5</b>	stoper was loose & shift and backward.
<b>Root Cause (Occurance)</b>	stoper was loose & shift and backward.

## Root Cause Analysis (Outflow)

<b>Why 1</b>	seatpipe total length Less
<b>Why 2</b>	Could not be detected at final inspection
<b>Why 3</b>	Skipped in Sampling at Final Inspection
<b>Why 4</b>	Sampling quantity was less
<b>Why 5</b>	
<b>Root Cause (Outflow)</b>	Sampling quantity was less

## 8. Countermeasure ( Occurrence , Outflow & System side Actions )

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Outflow	Give instructions for 100% length checking by surface plate.	Mr. Ankush	01/05/2023	29/04/2023	Completed
Occurance	Check the stopper condition in starting of every shift	Mr. Gurjant	01/05/2023	29/04/2023	Completed

## 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	Yes
<b>Change Details</b>	Inccress sampling quantity at work station & use of surface flate for length chacking at final inspection
<b>Inspection Method</b>	Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100%

## 10. Evidence of Countermeasure

<b>Occurance (Before)</b>	stopper was loose & shift and backward. <a href="#">440_Occurance_Before.jpeg</a>
<b>Occurance (After)</b>	Check the stopper condition in starting of every shift & display OPL At work station. <a href="#">440_Occurance_After.png</a>
<b>Outflow (Before)</b>	We chacked with sampling inspection By Digital vernier <a href="#">440_Outflow_Before.jpeg</a>
<b>Outflow (After)</b>	Inccress sampling quantity at work station & use of surface flate for length chacking at final inspection <a href="#">440_Outflow_After.png</a>

## 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	Yes
<b>Applicable Machine / Model / Plant</b>	CNC

## 12. Document Review

<b>Documents</b>	ControlPlan, PFMEA, WISOP, InspCheckSheet
<b>Specify Other Document</b>	No

## 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	10
<b>Reason for submission</b>	Corrective action parts submission.

