Defect Details

NC No.	8000839662
NC Date	07/08/2023
NC Submission Date	
Part No.	S1HT05507B
Part Name	OUTER SPRING - K1JF
Supplier Name & Code	101225-HELICAL SPRINGS
ETL Plant	1146-ETL Suspension Narasapura
Defect Details	DIMETER UNDERSIZE-ID LESS ISSUE

1. Problem Description

Defect Description	K1JF Outer spring ID less issue
Detection Stage	Inprocess
Problem Severity	Fitment
NG Quantity	2
Is Defect Repeatative?	No
Defect Sketch / Photo	vegwl3chpj0cbxq1xrhmexwa.jpg

Supplier Communication Details

Quality Head Email ID	shaikhmoin@helicalsprings.in
Plant Head/CEO Email ID	shaikhmoin@helicalsprings.in
MD Email ID	ataneja@helicalsprings.in

2. Stock Details & action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
Total Qty	2000	0	0	1200	1000	4200
Check Qty	2000	0	0	1200	1000	4200
NG Qty	2	0	0	0	0	2

Action taken on NG part

Scrap	2
Rework	0
Under Deviation	0

Containment Action

We Have Checked All At M/s Helical End Material Found OK.

3. Process Flow

Process Flow Description

Coiling>Stress-relieving-1>End Grinding>Shot-peening>Scragging>100% E1, E2 & Length Checking>ID Checking>Stress-Relieving-2>Powder Coating>Final Inspection>Packing>Dispatch.

4. Process Details

Process / Operation	100% ID Checking
Outsource	No
Machine / Cell	Plain Plug Gauge
Machine / Cell No.	-

5. Problem Analysis

Туре	Possible Cause	Fact Verification	Jud
Method	Setup spring not specific location.	Location to be defined for setup spring.	Х
Man	Unskilled Operator	Skill matrix checked found ok	0
Machine	Machine check Sheet not followed	CLIT verified found ok	0
Material	Material Grade	RMTC verified found ok	0

6. Inspection Method Analysis (Current)

Inspection Method	Gauge
Other Inspection Method	
Check Point at Final Inspection	Yes
Checking Freq.	100%
Sampling	No
Sample Size	100%

7. Root Cause Analysis (Occurance)

Why 1	Inner Diameter Under Size
Why 2	RM Coil Change Initial Parts Mix-up
Why 3	No Location Defined for Coil Change Initial Parts
Why 4	
Why 5	
Root Cause (Occurance)	RM Coil Change Initial Parts Mix-up

Root Cause Analysis (Outflow)

Why 1	Inner Diameter Undersize (mix Up)
Why 2	ID Checked in Sampling Basis
Why 3	Due to less qty. not able to detect.
Why 4	
Why 5	
Root Cause (Outflow)	RM Coil Change Initial Parts Mix-up

8. Countermeasure (Occurrence , Outflow & System side Actions)

Туре	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Outflow	1.100% Inspection Started. 2. Training Provided to the Operators, Final Inspectors & Recorded	QA	20/08/2023		Completed
Occurance	Procedure is Defined for Coil Change Parts Handling	QA & Production	20/11/2023		Completed

9. Inspection Method After Customer Complaint

Change In Inspection System	Yes
Change Details	100% ID Check Point Added.
Inspection Method	Gauge
Other Inspection Method	
Check Point at Final Inspection	Yes
Checking Freq.	100%
Sampling	No
Sample Size	100%

10. Evidance of Countermeasure

Occurance (Before)	WI And SOP Not Displayed for Coil Change Initial Parts Handling 516_Occurance_Before.pdf
Occurance (After)	WI And SOP Displayed for Coil Change Initial Parts Handling 516_Occurance_After.pdf
Outflow (Before)	Operator not aware. 516_Outflow_Before.pdf
Outflow (After)	Training Given. 516_Outflow_After.pdf

11. Horizontal Deployment

Horizontal Deployment Required	Yes
Applicable Machine / Model / Plant	Horizontal Deployment Done For KOPG.

12. Document Review

Documents	WISOP, InspCheckSheet
Specify Other Document	Training Record

13. Effectiveness Of Action

Reviewed Quantity	1000
Reason for submission	Reviewed 1000 found ok