

## Defect Details

<b>NC No.</b>	8000845684
<b>NC Date</b>	20/09/2023
<b>NC Submission Date</b>	
<b>Part No.</b>	S2MX00112B
<b>Part Name</b>	STEEL BUSH
<b>Supplier Name &amp; Code</b>	101255-MAHAVIR INDUSTRIES
<b>ETL Plant</b>	1143-ETL Suspension Halol, Vadodara
<b>Defect Details</b>	LENGTH OVERSIZE-LENGTH OVERSIZE

## 1. Problem Description

<b>Defect Description</b>	STEEL BUSH (S2MX00112O) TOTAL LENGTH OVERSIZE FOUND UPTO 24.06 MM AGAINST 24 -0.2 MM
<b>Detection Stage</b>	Receipt
<b>Problem Severity</b>	Fitment
<b>NG Quantity</b>	8
<b>Is Defect Repeatative?</b>	No
<b>Defect Sketch / Photo</b>	<a href="#">4nndp3kisfc1ecbi3e5kchrz.jpg</a>

## Supplier Communication Details

<b>Quality Head Email ID</b>	quality@mahavirind.co.in
<b>Plant Head/CEO Email ID</b>	planthead@mahavirind.co.in
<b>MD Email ID</b>	

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	5600	0	0	0	6000	11600
<b>Check Qty</b>	5600	0	0	0	6000	11600
<b>NG Qty</b>	1906	0	0	0	0	1906

## Action taken on NG part

<b>Scrap</b>	0
<b>Rework</b>	0
<b>Under Deviation</b>	1906

## Containment Action

All Suspected Material segregation At Customer End .

## 3. Process Flow

## Process Flow Description

RM Inward - Store - Traub Parting- Inward -Plating- Plating Mate.Inward- Final Inspection - packing - Dispatch

## 4. Process Details

<b>Process / Operation</b>	Traub Parting
<b>Outsource</b>	Yes
<b>Machine / Cell</b>	Traub Machine
<b>Machine / Cell No.</b>	Traub Section

## 5. Problem Analysis

Type	Possible Cause	Fact Verification	Jud
Machine	Stopper Lightly move During parting Pipe Rest.	Physically Check-Stopper Lightly Lose	O

## 6. Inspection Method Analysis (Current)

<b>Inspection Method</b>	Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100%

## 7. Root Cause Analysis (Occurance)

<b>Why 1</b>	TOTAL LENGTH OVERSIZE FOUND UPTO 24.06 MM AGINST 24 -0.2 MM
<b>Why 2</b>	Pipe Rest Stopper Not Proper Working
<b>Why 3</b>	Pipe Rest Stopper Lightly loose.
<b>Why 4</b>	
<b>Why 5</b>	
<b>Root Cause (Occurance)</b>	Pipe Rest Stopper Lightly loose.

## Root Cause Analysis (Outflow)

<b>Why 1</b>	TOTAL LENGTH OVERSIZE FOUND UPTO 24.06 MM AGINST 24 -0.2 MM
<b>Why 2</b>	During Final Inspection part Not proper Checking
<b>Why 3</b>	During Final Inspection Part tight Part Inserting In Checking Height Gauge.
<b>Why 4</b>	
<b>Why 5</b>	
<b>Root Cause (Outflow)</b>	During Final Inspection Part tight Part Inserting In Checking Height Gauge.

## 8. Countermeasure ( Occurrence , Outflow & System side Actions )

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Occurance	Stopper Adjust as specification	Mahadev Bhawar	22/09/2023	22/09/2023	Completed

## 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	Yes
<b>Change Details</b>	Height Reduce By 0.02 mm of Height Gauge.
<b>Inspection Method</b>	Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	Sampling
<b>Sampling</b>	No
<b>Sample Size</b>	100%

## 10. Evidence of Countermeasure

<b>Occurance (Before)</b>	On Traub Machine Pipe Resting stopper Lightly Loose <a href="#">553_Occurance_Before.pptx</a>
<b>Occurance (After)</b>	On Traub Machine Pipe Resting stopper Adjust As per Required Specification <a href="#">553_Occurance_After.pptx</a>
<b>Outflow (Before)</b>	Part forcely insert in height gauge at Final Stage <a href="#">553_Outflow_Before.pptx</a>
<b>Outflow (After)</b>	Height gauge Size Reduce By 0.02mm Than Required Size 24.0( Now 23.98mm) <a href="#">553_Outflow_After.pptx</a>

## 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	Yes
<b>Applicable Machine / Model / Plant</b>	All Steel Bush

## 12. Document Review

<b>Documents</b>	ControlPlan, PFMEA
<b>Specify Other Document</b>	no

## 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	50
<b>Reason for submission</b>	ok