

## Defect Details

<b>NC No.</b>	8000851178
<b>NC Date</b>	06/11/2023
<b>NC Submission Date</b>	
<b>Part No.</b>	550LG06702
<b>Part Name</b>	SEAT PIPE-(HMS-30 & HMP-30)
<b>Supplier Name &amp; Code</b>	100538-NARINDER PARKASH AND CO
<b>ETL Plant</b>	1143-ETL Suspension Halol, Vadodara
<b>Defect Details</b>	NOT AS PER SPECIFICATION-HALF THREAD

## 1. Problem Description

<b>Defect Description</b>	Seat Pipe M8 X 1.25 -6G half thread and Thread Length Short
<b>Detection Stage</b>	Inprocess
<b>Problem Severity</b>	Function
<b>NG Quantity</b>	1
<b>Is Defect Repeatative?</b>	No
<b>Defect Sketch / Photo</b>	<a href="#">f3flbtnxltmrvjxhuriho0h.jpg</a>

## Supplier Communication Details

<b>Quality Head Email ID</b>	quality@npcindustries.in
<b>Plant Head/CEO Email ID</b>	anand@npcindustries.in
<b>MD Email ID</b>	ajay@npcindustries.in

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	3800	8200	0	0	0	12000
<b>Check Qty</b>	3800	8200	0	0	0	12000
<b>NG Qty</b>	2	0	0	0	0	2

## Action taken on NG part

<b>Scrap</b>	2
<b>Rework</b>	0
<b>Under Deviation</b>	0

## Containment Action

Thread length checking with thread plug gauge.

## 3. Process Flow

## Process Flow Description

Raw material Inspection - Cutting - Draw - Forging - Rough Grinding - Punching - CNC Head turning - CNC Tail facing - Tapping & Chamfering - Final Inspection - Cleaning - Oiling - Packing & Dispatch

## 4. Process Details

<b>Process / Operation</b>	Tapping
<b>Outsource</b>	No
<b>Machine / Cell</b>	Tapping machine
<b>Machine / Cell No.</b>	TM-03

## 5. Problem Analysis

Type	Possible Cause	Fact Verification	Jud
Method	Incorrect location of part during Tapping	After verification we found part was located at Incorrect location.	X
Man	Operator negligence	After verification we found operator was aware about process	O
Material	Material Hard	After verification we found material was used as per std.	O
Tool	Wrong tapping tool use	After verification we found tapping tool was used as per std.	O
Machine	Tap tightening not ok	After verification we found tap tightening was ok	O

## 6. Inspection Method Analysis (Current)

<b>Inspection Method</b>	Sp. Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	No
<b>Checking Freq.</b>	Sampling
<b>Sampling</b>	No
<b>Sample Size</b>	As per std

## 7. Root Cause Analysis (Occurance)

<b>Why 1</b>	Half thread seatpipe found
<b>Why 2</b>	part was located at Incorrect location.
<b>Why 3</b>	The part was setted below the specified location
<b>Why 4</b>	No reference available on Fixture
<b>Why 5</b>	there was not available any stopper.
<b>Root Cause (Occurance)</b>	there is not available any stopper.

## Root Cause Analysis (Outflow)

<b>Why 1</b>	Half thread seatpipe found
<b>Why 2</b>	Could not be detected at Final Inspection
<b>Why 3</b>	Skipped in sampling at Final Inspection
<b>Why 4</b>	Sampling quantity was less.
<b>Why 5</b>	
<b>Root Cause (Outflow)</b>	Sampling quantity was less.

## 8. Countermeasure ( Occurrence , Outflow & System side Actions )

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Occurance	New clamp fixture to be modified with stopper.	Mr Ravinder Singh	10/11/2023	09/11/2023	Completed
Outflow	Sampling quantity to be increased.	Mr. Ankush	08/11/2023	07/11/2023	Completed
Occurance	Quality Alert to be displayed at working station	Mr. Princ	07/11/2023	06/11/2023	Completed
Outflow	Quality alert to be displayed at final Q- inspection station	Mr. Princ	07/11/2023	06/11/2023	Completed

## 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	Yes
<b>Change Details</b>	sampling quantity to be doubled at final inspection station.
<b>Inspection Method</b>	Sp. Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	No
<b>Checking Freq.</b>	Sampling
<b>Sampling</b>	No
<b>Sample Size</b>	double

## 10. Evidence of Countermeasure

<b>Occurance (Before)</b>	No stopper was available in clamp fixture <a href="#">588_Occurance_Before.png</a>
<b>Occurance (After)</b>	New clamp fixture to be modified with stopper. <a href="#">588_Occurance_After.png</a>
<b>Outflow (Before)</b>	Quality alert not available at final inspection. Sampling qty was less. <a href="#">588_Outflow_Before.jpg</a>
<b>Outflow (After)</b>	Display quality alert at work station & final Q-gate. Samling qty to be double. <a href="#">588_Outflow_After.png</a>

## 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	Yes
<b>Applicable Machine / Model / Plant</b>	Tapping machine

## 12. Document Review

<b>Documents</b>	ControlPlan, PFMEA, WISOP, InspCheckSheet
<b>Specify Other Document</b>	Not required

## 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	50
--------------------------	----

