

## Defect Details

<b>NC No.</b>	8000855363
<b>NC Date</b>	18/12/2023
<b>NC Submission Date</b>	
<b>Part No.</b>	520JT00302
<b>Part Name</b>	PLATE CLUTCH 3W-4S UPGRADE
<b>Supplier Name &amp; Code</b>	100150-DHANANJAY ENTERPRISES
<b>ETL Plant</b>	1132-ETL K-226/1 TRANSMISSION
<b>Defect Details</b>	THICKNESS UNDERSIZE-THICKNESS U/S UP TO 1.63 AGAINST 2.0

## 1. Problem Description

<b>Defect Description</b>	Wrong Thickness observed in 3W4S Plate clutch (1.6 mm observed in 2 mm)
<b>Detection Stage</b>	Inprocess
<b>Problem Severity</b>	Function
<b>NG Quantity</b>	17
<b>Is Defect Repeatative?</b>	Yes
<b>Defect Sketch / Photo</b>	

## Supplier Communication Details

<b>Quality Head Email ID</b>	qade@dhananjaygroup.com
<b>Plant Head/CEO Email ID</b>	de@dhananjaygroup.com
<b>MD Email ID</b>	kandakuretn@dhananjaygroup.com

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	19480	0	0	20160	0	39640
<b>Check Qty</b>	19480	0	0	20160	0	39640
<b>NG Qty</b>	22	0	0	52	0	74

## Action taken on NG part

<b>Scrap</b>	74
<b>Rework</b>	0
<b>Under Deviation</b>	0

## Containment Action

Segregated whole lot at the M/s ETL end & our DE-I plant end.

## 3. Process Flow

**Process Flow Description**

Receiving inspection of RM?Blanking &amp; Piercing?Deburring?Cleaning?Planishing?Straightening?Final Inspection?Oiling &amp; Packing?Logistics/Dispatch

**4. Process Details**

<b>Process / Operation</b>	Blanking & Piercing
<b>Outsource</b>	No
<b>Machine / Cell</b>	Press Machine-Pnumatic 100T
<b>Machine / Cell No.</b>	Machine no.-10000063

**5. Problem Analysis**

Type	Possible Cause	Fact Verification	Jud
Method	Set-up approval	Set-up approval not followed after RM coil change	X
Man	Man- Unskilled Operator	Unskilled operator for loading of coil	X
Man	Man- Wrong coil loading	Wrong thickness coil loading on D-coiler	X
Material	Material- RM Storage	No separate storage location for same width different thickness coils	X
Material	Material- Wrong thk.	Wrong material thickness coil loaded on D-coiler	X
Machine	Machine- Excess deburring	No excess deburring done on part	O

**6. Inspection Method Analysis (Current)**

<b>Inspection Method</b>	Instrument
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	Sampling
<b>Sampling</b>	No
<b>Sample Size</b>	05nos/lot

**7. Root Cause Analysis (Occurance)**

<b>Why 1</b>	Wrong thickness in Plate Clutch 3W4S
<b>Why 2</b>	Required thickness 2 observed 1.6mm
<b>Why 3</b>	Two packed form RM coils have same width but different thickness.
<b>Why 4</b>	No separate storage location available.
<b>Why 5</b>	
<b>Root Cause (Occurance)</b>	No separate storage location available.

**Root Cause Analysis (Outflow)**

<b>Why 1</b>	Wrong thickness in Plate Clutch 3W4S
<b>Why 2</b>	Required thickness 2 observed 1.6mm
<b>Why 3</b>	Set up approval not done after RM Coil change.
<b>Why 4</b>	Set-up approval done during changeover of part/die only.
<b>Why 5</b>	RM coil loading approval report not considered in setting of new RM coil on D-Coiler in PFMEA
<b>Root Cause (Outflow)</b>	RM coil loading approval report not considered in setting of new RM coil on D-Coiler in PFMEA

## 8. Countermeasure ( Occurrence , Outflow & System side Actions )

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Occurance	Separate location provided for same width-different thickness raw material coil	Mr. Nikhil Attarde	30/12/2023	30/12/2023	Completed
Occurance	Colour coding with blue & yellow paint colour according to thickness of same width different thickness RM coils to be ensured by incoming inspection person.Meantime the same to be informed to supplier for this colour codification.	Mr. Nikhil Attarde	30/12/2023	30/12/2023	Completed
Outflow	100% inspection of material for thickness with Gap gauge started for next 1 month.	Mr. Nikhil Attarde	30/12/2023	18/12/2023	Completed
Outflow	Raw material coil loading approval report provided for every new coil loading on D-coiler.	Mr. Nikhil Attarde	30/12/2023	30/12/2023	Completed
Occurance	Training given to operator	Mr. Nikhil Attarde	30/12/2023	20/12/2023	Completed

## 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	Yes
<b>Change Details</b>	Gap-Gauge inspection started 100% for thickness mix-up detection for next one month
<b>Inspection Method</b>	Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	Sampling
<b>Sampling</b>	No
<b>Sample Size</b>	05nos/lot

## 10. Evidance of Countermeasure

<b>Occurance (Before)</b>	RM coils of same width and different thickness have no separate location available for storage. <a href="#">618_Occurance_Before.jpg</a>
<b>Occurance (After)</b>	RM coils of same width and different thickness have allocated separate location for storage. <a href="#">618_Occurance_After.jpg</a>
<b>Outflow (Before)</b>	Set-up approval report take for die-change & start of the shift only. <a href="#">618_Outflow_Before.pdf</a>
<b>Outflow (After)</b>	RM coil loading approval report for every new coil loading on machine D-coiler. <a href="#">618_Outflow_After.pdf</a>

## 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	No
<b>Applicable Machine / Model / Plant</b>	N.A

## 12. Document Review

<b>Documents</b>	ControlPlan, PFMEA, InspCheckSheet
------------------	------------------------------------

<b>Specify Other Document</b>	N.A
-------------------------------	-----

### 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	1000
<b>Reason for submission</b>	OK