

## Defect Details

<b>NC No.</b>	8000862175
<b>NC Date</b>	07/02/2024
<b>NC Submission Date</b>	
<b>Part No.</b>	520PC03307
<b>Part Name</b>	UNDER BKT SUB-ASSY. K3
<b>Supplier Name &amp; Code</b>	100061-BAJAJSONS LIMITED
<b>ETL Plant</b>	1117-ETL K-228/9 Suspension
<b>Defect Details</b>	OPERATION MISSING-M16 OPERAION MISSING

## 1. Problem Description

<b>Defect Description</b>	OPERATION MISSING-M16 OPERAION MISSING
<b>Detection Stage</b>	Customer End
<b>Problem Severity</b>	Fitment
<b>NG Quantity</b>	1
<b>Is Defect Repeatative?</b>	No
<b>Defect Sketch / Photo</b>	

## Supplier Communication Details

<b>Quality Head Email ID</b>	pushpendra.singh@bajajsons.com
<b>Plant Head/CEO Email ID</b>	crbansal@bajajsons.com
<b>MD Email ID</b>	sanjay.bajaji@bajajsons.com

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	50	800	100	100	200	1250
<b>Check Qty</b>	50	300	0	100	200	650
<b>NG Qty</b>	1	0	0	0	0	1

## Action taken on NG part

<b>Scrap</b>	0
<b>Rework</b>	1
<b>Under Deviation</b>	0

## Containment Action

No material at customer end .Inspection started in warehouse & checked 300 pcs. Out of 800 pcs. and found all material ok ,Rest 500+100pcs(Transit) will be checked before Dispatch to ETL as per their requirement. At our end we checked our F.G Stock and WIP material (Qty. 100+200) and found ok.

## 3. Process Flow

## Process Flow Description

PRESS FITTING, MIG WELDING ,COUNTER SIDE BORES(TOP) , COUNTER SIDE BORES(BOTTOM SIDE) ,SLITTING(LEFT SIDE) , SLITTING(RIGHT SIDE) BROACHING(CHAMFER AT SLITTING )(LEFT AND RIGHT SIDE) , COUNTERING AT HOLE DIA.10.50(LEFT & RIGHT) , COUNTERING AT HOLE DIA. 8.60(LEFT & RIGHT) , DEBURRING AT MACHINE AREA , CARBON CLEANING-BORE OPENING , 2-TAPPING M6X1-6H , TAPPING M10 X 1.5 -6H(LEFT SIDE) , TAPPING M10 X 1.5 -6H(RIGHT SIDE) , 2-TAPPING 2-M6 X 1-6H , BUSH TAPPING M16 X 1.5-6H , STRAIGHTENING (PARALLISM INSPECTION) , DIE PASS OUT TO REMOVE THE DENT AND PHASPHATING SLIDGE (M30X1P-6H) , FINAL INSPECTION , PRE- DISPATCH INSPECTION PACKING &DISPATCH.

## 4. Process Details

<b>Process / Operation</b>	BUSH TAPPING M16X 1.5-6H
<b>Outsource</b>	No
<b>Machine / Cell</b>	TMS
<b>Machine / Cell No.</b>	03

## 5. Problem Analysis

Type	Possible Cause	Fact Verification	Jud
Machine	Machine not working during tapping process	During verification found that machine is ok (No breakdown)	O
Method	Multiple part taking from trolley for tapping & kept at machine table	During verification found that operator is taking more then one part during tapping at table	X
Man	Unskilled manpower	Skilled manpower deployed at inspection	O
Tool	Worn out tap used & due to tapping not performed	Tap was ok because tap life monitoring	O
Method	Part skipped from tapping machine(Moved from previous operation to next operation)	During verification found that complete trolley moved to next stage	O
Method	Improper handling of NG part during final inspection	During verification found that checker was did not mark on NG part during inspection	X
Material	Hardness more in part	During verification found bush material was ok	O

## 6. Inspection Method Analysis (Current)

<b>Inspection Method</b>	Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	5

## 7. Root Cause Analysis (Occurance)

<b>Why 1</b>	Tapping miss of M16x1.5 part skipped
<b>Why 2</b>	Tapping not performed due to part not loaded at machine
<b>Why 3</b>	Due to mix-up of tapping done & without tapping parts
<b>Why 4</b>	Mix-up due to multi parts taken from trolley & kept of machine table
<b>Why 5</b>	Neglegency of machine operator
<b>Root Cause (Occurance)</b>	Mix-up due to multi parts taken from trolley & kept of machine table, resulting NG part mix up & reached at next stage

## Root Cause Analysis (Outflow)

<b>Why 1</b>	NG part skipped from final inspection & reached at customer end
<b>Why 2</b>	NG part mix-up in ok material
<b>Why 3</b>	Mix-up in ok material due to no marking on NG part
<b>Why 4</b>	No marking on NG part due to negligency of checker
<b>Why 5</b>	
<b>Root Cause (Outflow)</b>	No marking on NG part due to negligency of checker

## 8. Countermeasure ( Occurrence , Outflow & System side Actions )

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Outflow	Awareness given to checkers for NG part handling	Irfan Ahmed	16/02/2024	15/02/2024	Completed
Occurance	OPL made & awareness given to machine operators for single part movement from trolley to avoid mix-up	Jasbir Singh	15/02/2024	15/02/2024	Completed

## 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	No
<b>Change Details</b>	N/A
<b>Inspection Method</b>	Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	5

## 10. Evidence of Countermeasure

<b>Occurance (Before)</b>	Mix-up due to multi parts taken from trolley & kept of machine table <a href="#">671_Occurance_Before.jpg</a>
<b>Occurance (After)</b>	Single part pick up from trolley for Bush Tapping M16X1.5. <a href="#">671_Occurance_After.jpg</a>
<b>Outflow (Before)</b>	No marking on NG part due to negligency of checker <a href="#">671_Outflow_Before.jpg</a>
<b>Outflow (After)</b>	Rework part move after marking as a decided place. <a href="#">671_Outflow_After.jpg</a>

## 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	Yes
<b>Applicable Machine / Model / Plant</b>	TMS -03/AVENGER & K-17 B/D/BSL U-III.

## 12. Document Review

<b>Documents</b>	PFMEA, WISOP
<b>Specify Other Document</b>	NO

### 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	255
<b>Reason for submission</b>	Checked and found ok