

## Defect Details

<b>NC No.</b>	8000863411
<b>NC Date</b>	17/02/2024
<b>NC Submission Date</b>	
<b>Part No.</b>	520FG07802
<b>Part Name</b>	GEAR PRIMARY DRIVEN (JZ)
<b>Supplier Name &amp; Code</b>	200172-AURANGABAD AUTO ENGG PVT LTD
<b>ETL Plant</b>	1132-ETL K-226/1 TRANSMISSION
<b>Defect Details</b>	PATCH MARK ON FACE.-DFC OBS 0.12 AGAINST 0.07

## 1. Problem Description

<b>Defect Description</b>	Flicker observed excess up to 0.030 mm against 0.010 mm -DFCE observed 0.12 mm against 0.040 mm
<b>Detection Stage</b>	Receipt
<b>Problem Severity</b>	Function
<b>NG Quantity</b>	1
<b>Is Defect Repeatative?</b>	Yes
<b>Defect Sketch / Photo</b>	

## Supplier Communication Details

<b>Quality Head Email ID</b>	verma.aaepl@gmail.com
<b>Plant Head/CEO Email ID</b>	aaepl.pantnagar@sangkaj.com
<b>MD Email ID</b>	steel@sangkaj.com

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	1565	0	0	1008	1890	4463
<b>Check Qty</b>	1565	0	0	1008	1890	4463
<b>NG Qty</b>	25	0	0	12	7	44

## Action taken on NG part

<b>Scrap</b>	0
<b>Rework</b>	44
<b>Under Deviation</b>	0

## Containment Action

All WIP 100% Rechecked

## 3. Process Flow

**Process Flow Description**

CNC Blank Inward---Hobbing ---HT--- ID Honing---Teeth Honing -----Final Inspection ----Oiling Packing ---Dispatch

**4. Process Details**

<b>Process / Operation</b>	Teeth Honing
<b>Outsource</b>	Yes
<b>Machine / Cell</b>	Teeth Honing Machine
<b>Machine / Cell No.</b>	HMX 260

**5. Problem Analysis**

Type	Possible Cause	Fact Verification	Jud
Material	Less Allowance for teeth Honing	Less allowance for teeth honing	O

**6. Inspection Method Analysis (Current)**

<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	visual inspection
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100%

**7. Root Cause Analysis (Occurance)**

<b>Why 1</b>	Patch mark on teeth
<b>Why 2</b>	less material removal on teeth honing operation
<b>Why 3</b>	As per process requirement no sufficient stock for teeth honing
<b>Why 4</b>	Teeth honing input material face runout excess due to part excess bend in HT process
<b>Why 5</b>	HT charge making fixture bend & Crack
<b>Root Cause (Occurance)</b>	HT charge making fixture bend & Crack

**Root Cause Analysis (Outflow)**

<b>Why 1</b>	Patch mark on teeth
<b>Why 2</b>	Part detected in final inspection
<b>Why 3</b>	less awareness of final inspector
<b>Why 4</b>	N/A
<b>Why 5</b>	N/A
<b>Root Cause (Outflow)</b>	Less awareness of final inspector

**8. Countermeasure ( Occurrence , Outflow & System side Actions )**

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Occurance	New HT charge making plate ordered	Mr.Raut	20/03/2024		Pending

## 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	Yes
<b>Change Details</b>	1) Training provided to all final inspector 2) Ok Not Ok part OPL displayed at final inspection 3) Before teeth honing 100% face runout inspection started .
<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	Visual Inspection
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100%

## 10. Evidence of Countermeasure

<b>Occurance (Before)</b>	Evidence attached <a href="#">684_Occurance_Before.xlsx</a>
<b>Occurance (After)</b>	Evidence attached <a href="#">684_Occurance_After.xlsx</a>
<b>Outflow (Before)</b>	Evidence attached <a href="#">684_Outflow_Before.xlsx</a>
<b>Outflow (After)</b>	Evidence attached <a href="#">684_Outflow_After.xlsx</a>

## 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	No
<b>Applicable Machine / Model / Plant</b>	N/A

## 12. Document Review

<b>Documents</b>	ControlPlan, WISOP, AuditCheckSheet, InspCheckSheet
<b>Specify Other Document</b>	No

## 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	
<b>Reason for submission</b>	