

Defect Details

NC No.	8000868441
NC Date	22/03/2024
NC Submission Date	
Part No.	F20502107B
Part Name	UNDER BKT.ASSY. - B104D FF
Supplier Name & Code	100061-BAJAJSONS LIMITED
ETL Plant	1117-ETL K-228/9 Suspension
Defect Details	NOT AS PER SPECIFICATION-DIA. 28.02 28.053 FOUND UNDERSIZE

1. Problem Description

Defect Description	28.02/ 28.053 FOUND UNDERSIZE
Detection Stage	Inprocess
Problem Severity	Fitment
NG Quantity	1
Is Defect Repeatative?	No
Defect Sketch / Photo	

Supplier Communication Details

Quality Head Email ID	kasingh@bajajsons.com
Plant Head/CEO Email ID	crbansal@bajajsons.com
MD Email ID	sanjay.bajaji@bajajsons.com

2. Stock Details & action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
Total Qty	600	1652	148	80	104	2584
Check Qty	600	1652	0	80	104	2436
NG Qty	1	0	0	0	0	1

Action taken on NG part

Scrap	1
Rework	0
Under Deviation	0

Containment Action

Remaining material to be verify on date 28.03.2024 & marking started on fitting dia after inspection.

3. Process Flow

Process Flow Description

RAW MATL. INSPECTION - PIPE CUTTING - I.D. DEBURRING-FLARING - STEP TURNING - I.D.COUNTERING - THREAD ROLLING M25X1.0-6g - GRINDING (PIPE FITTING SIDE) - GRINDING (PIPE THREAD SIDE) - TO ASSY. - PRESS FITTING OF U/BKT. & STEM STEERING - MIG WELDING - SLITTING(L/R) - CHAMFERING AT SLITTING(L/R) - COUNTER AT HOLE DIA 6.80-COUNTER AT HOLE DIA 8.50 - DEBURRING AT MACHINING AREA - CARBON CLEANING - PHASPHATING & POWDER COATING -BORE OPENING-2 TAPPING M6 X1 -6H -TAPPING M8X1.25 -6H(L&R) -STRAIGHTENING//LISM INSPECTION)-DIE PASSOUT M25- FINAL INSPECTION -PRE DISPATCH INSPECTION -PACKING AND DISPATCH

4. Process Details

Process / Operation	Shaft Grinding
Outsource	No
Machine / Cell	CGM
Machine / Cell No.	01

5. Problem Analysis

Type	Possible Cause	Fact Verification	Jud
Man	Unskilled manpower	Skilled manpower deployed at inspection	O
Material	Hardness more in part	During verification found material hardness is ok	O
Method	Setting Part Mixup during Machine setting	During verification found that operator is putting setting part at wrong place	X

6. Inspection Method Analysis (Current)

Inspection Method	Gauge
Other Inspection Method	
Check Point at Final Inspection	Yes
Checking Freq.	100%
Sampling	No
Sample Size	NO

7. Root Cause Analysis (Occurance)

Why 1	Fitting dia 28.0 under size part skipped
Why 2	NG part mix-up in ok material
Why 3	Due to rejected part not kept separately as per decided place
Why 4	Negligence of machine operator
Why 5	
Root Cause (Occurance)	Operator Negligence

Root Cause Analysis (Outflow)

Why 1	NG part skipped from final inspection & reached at customer end
Why 2	NG part mix-up in ok material
Why 3	Mix-up in ok material due to no marking on NG part
Why 4	No marking on NG part due to negligence of checker
Why 5	
Root Cause (Outflow)	No marking on NG part due to negligence of checker

8. Countermeasure (Occurrence , Outflow & System side Actions)

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Occurance	OPL made & awareness given to machine operators to avoid setting part mix-up	Vijay Singh	28/03/2024		Completed
Outflow	Awareness given to checkers for NG part handling	IRFAN	28/03/2024		Completed
Outflow	Awareness given to checkers for NG part handling	Irfan Ahmed	26/03/2024		Completed

9. Inspection Method After Customer Complaint

Change In Inspection System	Yes
Change Details	After dia inspection White paint marking started on dia 28.0 at final inspection stage
Inspection Method	Gauge
Other Inspection Method	
Check Point at Final Inspection	Yes
Checking Freq.	100%
Sampling	No
Sample Size	NO

10. Evidence of Countermeasure

Occurance (Before)	SETTING PART MIXUP IN OK MATERIAL DUE TO PART KEPT AT WRONG PLACE 726_Occurance_Before.png
Occurance (After)	SETTING REJECTED PART AT OK PLACE AND ALSO LOCK AND PROVISION ADDED AT WORK STATION 726_Occurance_After.png
Outflow (Before)	REJECTED PART WITHOUT IDENTIFICATION AT WRONG PLACE 726_Outflow_Before.png
Outflow (After)	REJECTED PART KAPT AT OK PLACE AND OPL DISPLAYED AT FINAL INSPECTION STAGE FOR CHECKER AWARENESS 726_Outflow_After.png

11. Horizontal Deployment

Horizontal Deployment Required	Yes
Applicable Machine / Model / Plant	CGM-01 K-19 ,K-1 UPGRADE,CAL-115 BSL U-III

12. Document Review

Documents	PFMEA
Specify Other Document	NO

13. Effectiveness Of Action

Reviewed Quantity	175
Reason for submission	OK

