

## Defect Details

<b>NC No.</b>	8000873487
<b>NC Date</b>	06/05/2024
<b>NC Submission Date</b>	
<b>Part No.</b>	F2LG05302B
<b>Part Name</b>	SEAT PIPE - ABWB ENDURO
<b>Supplier Name &amp; Code</b>	100539-N P ENTERPRISES
<b>ETL Plant</b>	1117-ETL K-228/9 Suspension
<b>Defect Details</b>	NOT AS PER SPECIFICATION-OD OVERSIZE

## 1. Problem Description

<b>Defect Description</b>	OD OVERSIZE
<b>Detection Stage</b>	Inprocess
<b>Problem Severity</b>	Fitment
<b>NG Quantity</b>	5
<b>Is Defect Repeatative?</b>	Yes
<b>Defect Sketch / Photo</b>	

## Supplier Communication Details

<b>Quality Head Email ID</b>	quality@npcindustries.in
<b>Plant Head/CEO Email ID</b>	anand@npcindustries.in
<b>MD Email ID</b>	ajay@npcindustries.in

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	640	2200	0	0	0	2840
<b>Check Qty</b>	640	2200	0	0	0	2840
<b>NG Qty</b>	5	0	0	0	0	5

## Action taken on NG part

<b>Scrap</b>	0
<b>Rework</b>	5
<b>Under Deviation</b>	0

## Containment Action

segregation done at ETL and NP End

## 3. Process Flow

## Process Flow Description

Process Flow Description 1.0 Raw Material 2.0 Cutting 3.0 Drawing 4.0 Head Formation 5.0 Rough Grinding 6.0 Punching 7.0 CNC Head Turning 8.0 CNC Boring & Facing 9.0 Tapping 10.0 Chamfering 11.0 ID Deburring 12.0 Finish Grinding 13.0 Final Inspection 14.0 Cleaning 15.0 Oiling 16.0 Packing & Dispatch.

## 4. Process Details

<b>Process / Operation</b>	Final Grinding
<b>Outsource</b>	Yes
<b>Machine / Cell</b>	Centerless grinding
<b>Machine / Cell No.</b>	CG-05

## 5. Problem Analysis

Type	Possible Cause	Fact Verification	Jud
Method	skipped during inspection	After verification we observed part was skipped	X
Man	Inprocess quality inspector negligent	After verification found OK	O
Material	Dressing not done as per define freq.	After verification we found dressing done as per define freq.	O
Man	Inprocess operator negligent	after verification found ok	O
Method	Setting Part Mixed	After verification found no chance of mixing of setting part	O
Method	Operation skipped	After verification we found operation was skipped	X

## 6. Inspection Method Analysis (Current)

<b>Inspection Method</b>	Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	Sampling
<b>Sampling</b>	No
<b>Sample Size</b>	as per std

## 7. Root Cause Analysis (Occurance)

<b>Why 1</b>	The outer diameter is larger than the specified tolerance.
<b>Why 2</b>	Grinding operation is uneven
<b>Why 3</b>	Part could not be fully ground
<b>Why 4</b>	Operator skipped Grinding from Tail side
<b>Why 5</b>	Due to length being more operator performed 2operations simultaneously on one part (One from head side and then from tail side)
<b>Root Cause (Occurance)</b>	Due to length being more operator performed 2operations simultaneously on one part (One from head side and then from tail side)

## Root Cause Analysis (Outflow)

<b>Why 1</b>	Outer Diameter over size
<b>Why 2</b>	Part could not detected at final inspection
<b>Why 3</b>	skipped in Sampling at Final Inspection
<b>Why 4</b>	Sampling qty was less

<b>Why 5</b>	
<b>Root Cause (Outflow)</b>	Sampling qty was less

### 8. Countermeasure ( Occurrence , Outflow & System side Actions )

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Outflow	Sampling qty doubled during final inspection.	Mr. Vinay	08/05/2024	07/05/2024	Completed
Occurance	Final grinding work instruction to be updated	Mr. Princ	09/05/2024	09/05/2024	Completed
Occurance	only one side operation is performed at a time, and the next operation begins once the first operation is completed during final grinding	Mr. Ankush	09/05/2024	09/05/2024	Completed

### 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	Yes
<b>Change Details</b>	Sampling qty doubled
<b>Inspection Method</b>	Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	Sampling
<b>Sampling</b>	No
<b>Sample Size</b>	updated

### 10. Evidence of Countermeasure

<b>Occurance (Before)</b>	Grind Both (tail & Head) Sides of a part simultaneously <a href="#">780_Occurance_Before.jpg</a>
<b>Occurance (After)</b>	only one side operation (Head side) is performed at a time, and the next operation (tail side) begins once the first operation is completed during final grinding. <a href="#">780_Occurance_After.jpg</a>
<b>Outflow (Before)</b>	Follow the sampling inspection method as per plan so sampling quantity was less <a href="#">780_Outflow_Before.png</a>
<b>Outflow (After)</b>	Sampling Qty to be doubled. <a href="#">780_Outflow_After.png</a>

### 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	Yes
<b>Applicable Machine / Model / Plant</b>	All similar model

### 12. Document Review

<b>Documents</b>	ControlPlan, PFMEA, WISOP, JHCheckSheet, InspCheckSheet
<b>Specify Other Document</b>	No

### 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	100
<b>Reason for submission</b>	OK