

## Defect Details

<b>NC No.</b>	8000873532
<b>NC Date</b>	06/05/2024
<b>NC Submission Date</b>	
<b>Part No.</b>	F2DZ04603B
<b>Part Name</b>	FORK BOLT J1A & J1D
<b>Supplier Name &amp; Code</b>	100189-SANGKAJ STEEL PVT LTD.
<b>ETL Plant</b>	1117-ETL K-228/9 Suspension
<b>Defect Details</b>	NOT AS PER SPECIFICATION-THREAD OD U/S, FACE DAMAGE

## 1. Problem Description

<b>Defect Description</b>	THREAD OD U/S
<b>Detection Stage</b>	Inprocess
<b>Problem Severity</b>	Fitment
<b>NG Quantity</b>	2
<b>Is Defect Repeatative?</b>	Yes
<b>Defect Sketch / Photo</b>	

## Supplier Communication Details

<b>Quality Head Email ID</b>	qualityassurance@sangkaj.com
<b>Plant Head/CEO Email ID</b>	steel@sangkaj.com
<b>MD Email ID</b>	anirudh.2007@hotmail.com

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	500	0	0	350	833	1683
<b>Check Qty</b>	500	0	0	350	833	1683
<b>NG Qty</b>	2	0	0	1	1	4

## Action taken on NG part

<b>Scrap</b>	4
<b>Rework</b>	0
<b>Under Deviation</b>	0

## Containment Action

All Material at sangkaj Steel End & ETL End Segregated for the above Defect & NG Qty Quantity is Scrapped.

## 3. Process Flow

**Process Flow Description**

RM Inward-RM Inward Inspection-Traub Blank Cutting-CNC Machining 1st-CNC Machining 2nd-Milling-Deburring-Tapping-Plating -Final Inspection-Dispatch

**4. Process Details**

<b>Process / Operation</b>	CNC Machining 2nd
<b>Outsource</b>	Yes
<b>Machine / Cell</b>	CNC Machining
<b>Machine / Cell No.</b>	02

**5. Problem Analysis**

Type	Possible Cause	Fact Verification	Jud
Material	Input Material Not OK	Semi-finish Blanks are made from Uniform Diameter Bar, Cut blanks Found OK	O
Method	Inadequate inspection method	Only Visual Inspection is done for threading	X
Man	Wrong Offset given by operator	defective parts all dimensions found undersize, this happens only due to Wrong Offset	X
Tool	Tool Worn out	Insert Worn out doesn't lead to Dimensions undersize	O
Machine	Variation due to Machine	Machine Condition is OK, Not Contributing for Dimension Variation.	O

**6. Inspection Method Analysis (Current)**

<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	Visual Inspection
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100%

**7. Root Cause Analysis (Occurance)**

<b>Why 1</b>	Thread Major Dia. Undersize parts found at Customer End
<b>Why 2</b>	During CNC turning, major Diameter became undersize
<b>Why 3</b>	Wrong Offset given by operator
<b>Why 4</b>	Operator was not trained to give offset
<b>Why 5</b>	Training needs to operator not identified and followed.
<b>Root Cause (Occurance)</b>	Training needs to operator not identified and followed.

**Root Cause Analysis (Outflow)**

<b>Why 1</b>	Thread Major Dia. Undersize parts found at Customer End
<b>Why 2</b>	Defective parts didn't get arrested during Final inspection
<b>Why 3</b>	Only Visual Inspection is done for threading
<b>Why 4</b>	Inadequate inspection method is Followed
<b>Why 5</b>	

**Root Cause (Outflow)**

Inadequate inspection method is Followed

**8. Countermeasure ( Occurrence , Outflow & System side Actions )**

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Occurance	1.Training given to Operator about giving Offset. 2.Offset Interlocking is done with in 0.1mm. if by mistake operator gives more offset, it will not get executed.	Mr. Santosh Raut	10/05/2024	10/05/2024	Completed
Outflow	Inspection Method Changed, Snap Gauge implemented for 100% Inspection of major Diameter	Mr. Anil Chaudhari	12/05/2024	10/05/2024	Completed

**9. Inspection Method After Customer Complaint**

<b>Change In Inspection System</b>	Yes
<b>Change Details</b>	100 % Inspection of Major Diameter with Snap gauge of 37.68-37.75mm
<b>Inspection Method</b>	Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100%

**10. Evidance of Countermeasure**

<b>Occurance (Before)</b>	No Offset interlock Provided for the Dimensions, Operator by Mistake can give to much Offset. <a href="#">785_Occurance_Before.pptx</a>
<b>Occurance (After)</b>	Offset Interlocking is done within 0.1mm, if operator gave offset more than0.1mm, it will not be accepted. <a href="#">785_Occurance_After.pptx</a>
<b>Outflow (Before)</b>	Only Visual Inspection is done for threading. <a href="#">785_Outflow_Before.pptx</a>
<b>Outflow (After)</b>	Inspection Method changed, Snap Gauge implemented for Measurement of Major dia. <a href="#">785_Outflow_After.pptx</a>

**11. Horizontal Deployment**

<b>Horizontal Deployment Required</b>	Yes
<b>Applicable Machine / Model / Plant</b>	Fork Bolt AABM

**12. Document Review**

<b>Documents</b>	ControlPlan, WISOP, InspCheckSheet
<b>Specify Other Document</b>	None

**13. Effectiveness Of Action**

<b>Reviewed Quantity</b>	100
<b>Reason for submission</b>	OK