Defect Details

| NC No. | 8000873536 |
|----------------------|--|
| NC Date | 06/05/2024 |
| NC Submission Date | |
| Part No. | F2DZ07203B |
| Part Name | FORK BOLT (K-9207) Ni+Cr Plated |
| Supplier Name & Code | 100539-N P ENTERPRISES |
| ETL Plant | 1117-ETL K-228/9 Suspension |
| Defect Details | NOT AS PER SPECIFICATION-PLATING MISSING |

1. Problem Description

| Defect Description | PLATING MISSING |
|---------------------------|-----------------|
| Detection Stage | Inprocess |
| Problem Severity | Aesthetic |
| NG Quantity | 2 |
| Is Defect Repeatative? | Yes |
| Defect Sketch / Photo | |

Supplier Communication Details

| Quality Head Email ID | quality@npcindustries.in |
|-------------------------|--------------------------|
| Plant Head/CEO Email ID | anand@npcindustries.in |
| MD Email ID | ajay@npcindustries.in |

2. Stock Details & action taken for NG parts

| Location | ETL End | Warehouse | Transit | Supplier FG | Supplier WIP | Total |
|-----------|---------|-----------|---------|-------------|--------------|-------|
| Total Qty | 1500 | 50000 | 0 | 0 | 0 | 51500 |
| Check Qty | 1500 | 50000 | 0 | 0 | 0 | 51500 |
| NG Qty | 2 | 0 | 0 | 0 | 0 | 2 |

Action taken on NG part

| Scrap | 2 |
|-----------------|---|
| Rework | 0 |
| Under Deviation | 0 |

Containment Action

1.Raw Material 2. Blanking 3. Hex Punching 4. Flattening 5. CNC Turning, Chamfering & threading 6. Buffing 7. Plating 8.Final Inspection.

3. Process Flow

Process Flow Description

10 - Raw Material 20 - Cutting and Forging(1st) 30-Forging(2nd) 40-Annealing 50-Phosphating 60 - Forging(3rd) I.D 70-Forging(4th) Hex 80 - CNC(1st) 90 - CNC(2nd) 100 - CNC(3rd) 110 - CNC drilling and Chamfering 120 - Final inspection 130 - Packing & Dispatch 140 - Buffing-1st 150 - Buffing 2nd 160 - Plating

4. Process Details

| Process / Operation | Plating |
|---------------------|---------------|
| Outsource | Yes |
| Machine / Cell | Plating plant |
| Machine / Cell No. | NA |

5. Problem Analysis

| Туре | Possible Cause | Fact Verification | Jud |
|----------|--|---|-----|
| Material | Plating chemicals composition was not as per spec. | After verification we found OK | 0 |
| Man | Untrained Operator | After verification we found operator was aware about process and responsibilities | 0 |
| Method | Plating time duration less | After verification we observed plating time duration as per std. | 0 |
| Method | PC position holding method NG | During verification we found Jig holder was damage | Х |
| Method | Skipped during final inspection | after verification we found part was skipped at final inspection. | Х |

6. Inspection Method Analysis (Current)

| Inspection Method | Other |
|---------------------------------|--------|
| Other Inspection Method | visual |
| Check Point at Final Inspection | Yes |
| Checking Freq. | 100% |
| Sampling | No |
| Sample Size | 100% |

7. Root Cause Analysis (Occurance)

| Why 1 | The bolt was not correctly positioned during the plating process. |
|------------------------|--|
| Why 2 | The jig point, which is supposed to hold the bolt securely, was not clean. |
| Why 3 | The jig cleaning process was either inadequate or not performed regularly. |
| Why 4 | There was no clear protocol or schedule for cleaning the jig points. |
| Why 5 | WI did not include guidelines for the regular cleaning of jig points. |
| Root Cause (Occurance) | WI did not include guidelines for the regular cleaning of jig points. |

Root Cause Analysis (Outflow)

| Why 1 | Plating NG in fork bolt. |
|----------------------|--|
| Why 2 | Defected part could not detect |
| Why 3 | The part was skipped at final Q-gate. |
| Why 4 | NG and OK pc was put at the same color of bin. |
| Why 5 | |
| Root Cause (Outflow) | NG and OK pc was put at the same color of bin. |

8. Countermeasure (Occurrence , Outflow & System side Actions)

| Туре | Countermeasure Details | Responsibility | Target Date | Actual Date | Status |
|-----------|---|----------------|-------------|-------------|-----------|
| Outflow | Locked red bin implement at the Final Q gate | Nikhil Jain | 11/05/2024 | 11/05/2024 | Completed |
| Outflow | Q-alert to be displayed at final Q gate | Mr. Deepak | 08/05/2024 | 07/05/2024 | Completed |
| Occurance | Regular cleaning of jig points to be added in WI | Nikhil Jain | 10/05/2024 | 09/05/2024 | Completed |
| Outflow | Blue bin used for without checked material and Green bin used for Checked material. | Nikhil Jain | 15/05/2024 | 11/05/2024 | Completed |

9. Inspection Method After Customer Complaint

| Change In Inspection System | Yes |
|------------------------------------|--|
| Change Details | Same color of bin to be replaced with different color for different purpose. |
| Inspection Method | Other |
| Other Inspection Method | Visual |
| Check Point at Final Inspection | Yes |
| Checking Freq. | 100% |
| Sampling | No |
| Sample Size | 100% |

10. Evidance of Countermeasure

| Occurance (Before) | WI did not include guidelines for the regular cleaning of jig points. 788_Occurance_Before.jpg |
|--------------------|--|
| Occurance (After) | updated wi to be updated 788_Occurance_After.jpg |
| Outflow (Before) | NG and OK pc was put at the same color of bin. 788_Outflow_Before.jpeg |
| Outflow (After) | NG pcs put in orange bin and OK pc was put in Blue bin and red bin implement 788_Outflow_After.pdf |

11. Horizontal Deployment

| Horizontal Deployment Required | Yes |
|---------------------------------------|-------------------|
| Applicable Machine / Model / Plant | All Similar parts |

12. Document Review

| Documents | PMCheckSheet, PFMEA, WISOP |
|------------------------|----------------------------|
| Specify Other Document | Na |

13. Effectiveness Of Action

ok