

## Defect Details

<b>NC No.</b>	8000874017
<b>NC Date</b>	11/05/2024
<b>NC Submission Date</b>	
<b>Part No.</b>	F800500507
<b>Part Name</b>	UNDER BRACKET ASSEMBLY
<b>Supplier Name &amp; Code</b>	100061-BAJAJSONS LIMITED
<b>ETL Plant</b>	1126-ETL Pantnagar
<b>Defect Details</b>	THREADING MISSING-M10 THRAED MISS

## 1. Problem Description

<b>Defect Description</b>	M10 Thread Miss in Steering Shaft Bush
<b>Detection Stage</b>	Customer End
<b>Problem Severity</b>	Fitment
<b>NG Quantity</b>	1
<b>Is Defect Repeatative?</b>	Yes
<b>Defect Sketch / Photo</b>	

## Supplier Communication Details

<b>Quality Head Email ID</b>	kasingh@bajajsons.com
<b>Plant Head/CEO Email ID</b>	crbansal@bajajsons.com
<b>MD Email ID</b>	sanjay.bajaji@bajajsons.com

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	440	200	0	0	100	740
<b>Check Qty</b>	200	0	0	0	100	300
<b>NG Qty</b>	1	0	0	0	0	1

## Action taken on NG part

<b>Scrap</b>	1
<b>Rework</b>	0
<b>Under Deviation</b>	0

## Containment Action

All customer end material 440 pcs. hold for re-inspection & checked 180 pcs. and found all material ok. Warehouse Qty. 200 pcs. will re-check before dispatch to ETL. No material in our End & transit

## 3. Process Flow

## Process Flow Description

Press fitting-Mig Welding-Carbon cleaning-Fine boring-Counter at side bore-Slitting-Broaching or deburring-Counter at hole dia 10.5 & 8.8mm-Manual deburring- Phosphating & powder coating-Bore Opening-M6 tapping-M10x1.25 tapping-M6 Tapping-M10x1.25 bush tapping-Parallelism inspection- Die passout-Final inspection-PDI-Packing & dispatch

## 4. Process Details

<b>Process / Operation</b>	Bush Tapping M10x1.25
<b>Outsource</b>	No
<b>Machine / Cell</b>	Tapping machine (BDM)
<b>Machine / Cell No.</b>	BDM-11

## 5. Problem Analysis

Type	Possible Cause	Fact Verification	Jud
Machine	Machine spindle jam	Machine condition is ok	O
Material	Bush Material grade NG	Material is being used as defined grade	O
Method	Improper handling NC parts during inspection	During verification found that NC area was defined & followed	O
Man	Unskilled manpower	Skilled manpower deployed for tapping & inspection	O
Method	Part did not load on fixture for tapping	During verification found that single trolley used at tapping process, chances of part skipped	X
Method	PFD not followed during machining process	During verification found that material run as per sequence	O
Man	Not Follow up the SOP	During verification found that inspection is being done as per defined SOP	O
Method	More then one activities by one checker	During verification & found that more then one activity done during short manpower in Apr,24	X
Tool	Tap wear out	Tool monitoring done as defined	O

## 6. Inspection Method Analysis (Current)

<b>Inspection Method</b>	Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	5Pcs./Lot

## 7. Root Cause Analysis (Occurance)

<b>Why 1</b>	Without tapping part reached at next stage
<b>Why 2</b>	Tapping done & without tapping part mix up
<b>Why 3</b>	Mix up due to single trolley used
<b>Why 4</b>	Single trolley used due to less space for input & output trolley at tapping machine
<b>Why 5</b>	Machine lay-out constrain
<b>Root Cause (Occurance)</b>	Machine lay-out constrain

## Root Cause Analysis (Outflow)

<b>Why 1</b>	Without tapping part skipped from tapping inspection stage of F.I.
<b>Why 2</b>	Checked & without checked parameters part mix-up
<b>Why 3</b>	No marking done after each parameter inspection
<b>Why 4</b>	Marking after inspection was not defined
<b>Why 5</b>	Earlier no such type activities was defined for more then one activities for one checker
<b>Root Cause (Outflow)</b>	No marking done after each parameter inspection , resulting without tapping inspection part skipped & reached at customer end

## 8. Countermeasure ( Occurrence , Outflow & System side Actions )

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Outflow	OPL made & awareness given to final inspection checker that he will do marking with green paint marker after ensure tapping presence if he will more then one parameters	Mr Irfan	13/05/2024	13/05/2024	Completed
Occurance	Shooter provision to be add at tapping machine for material movement to cover up the space constrain	Mr. Jasbir Singh	25/05/2024	29/05/2024	Completed
Occurance	OJT made & awareness given to all concern for 100% inspection before material move to next stage by machine operator	Mr. Jasbir	13/05/2024	13/05/2024	Completed
Occurance	Poke-yoke provision feasibility to be check after review the sequence change if any	Mr. Harpal Singh	25/05/2024	29/05/2024	Completed

## 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	Yes
<b>Change Details</b>	Green dot marking started after ensure the tapping presence
<b>Inspection Method</b>	Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	05Pcs/Lot

## 10. Evidance of Countermeasure

<b>Occurance (Before)</b>	Single trolley is being used for bush tapping process, chances of tapping miss during part taking & loading at trolley from one trolley <a href="#">801_Occurance_Before.jpg</a>
<b>Occurance (After)</b>	Tray type provision will implemented at tapping machines for material material to next stage, At 1st tapping Input will take from trolley & after that material will move at tray as proposed. Secondly tapping sequence will review again for poke-yoke provision to detect tapping miss issue <a href="#">801_Occurance_After.jpg</a>
<b>Outflow (Before)</b>	There was no marking after inspection , In this case more then one parameters checked by checker , resulting part move to next stage because no marking was there after inspected parameters <a href="#">801_Outflow_Before.jpg</a>
<b>Outflow (After)</b>	Green dot marking started after inspection, if single parameter inspection or more then one parameters inspection.(Only one bush hole tapping is checked by checker and other checker checking two tapping left and right side as in bracket. thats why there is no load on bush tapping checker for green marking ) <a href="#">801_Outflow_After.pdf</a>

## 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	Yes
<b>Applicable Machine / Model / Plant</b>	K-19,K3,K17AB,K17E ,E101B , U101 & Avenger

## 12. Document Review

<b>Documents</b>	PFMEA, WISOP, InspCheckSheet
<b>Specify Other Document</b>	N/A

## 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	1
<b>Reason for submission</b>	1. In Occurrence side in Before and After photographs, No change seen. 2. In Occurrence side the Root cause is Machine Layout Constraint, So what Action you have taken for same. 3. In Outflow side the cause seen is that the Final Inspector was overloaded, who is doing multiple activities, earlier multiple activities not carried by one person, then you have added further marking activity, which increase his load also. Then How you assure that only addition of marking will resolve the problem. 4. As this is the Customer complaint for us, But you have shared only Manual controls, Have you initiated any activity for the automated controls for generation and Inspection of these type of Defects.