#### **Defect Details**

NC No.	8000877852
NC Date	11/06/2024
NC Submission Date	
Part No.	F20508502B
Part Name	UNDER BKT ASSY MACHINED - XF1C1
Supplier Name & Code	100060-A.G.TRANSMISSIONS
ETL Plant	1117-ETL K-228/9 Suspension
<b>Defect Details</b>	NOT AS PER SPECIFICATION-THREAD M22 MAJOR DIA UNDERSIZE

# 1. Problem Description

<b>Defect Description</b>	THREAD M22 MAJOR DIA UNDERSIZE
<b>Detection Stage</b>	Receipt
Problem Severity	Safety
NG Quantity	8
Is Defect Repeatative?	Yes
Defect Sketch / Photo	

# Supplier Communication Details

Quality Head Email ID	agtransmissions@rediffmail.com
Plant Head/CEO Email ID	planthead@agtransmissionsindia.com
MD Email ID	agtransmissions@rediffmail.com

### 2. Stock Details & action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	150	0	0	1200	0	1350
Check Qty	150	0	0	1200	0	1350
NG Qty	8	0	0	2	0	10

#### Action taken on NG part

Scrap	10	
Rework	0	
<b>Under Deviation</b>	0	

#### **Containment Action**

100% Inspection done & special identification white dot on Shaft done.

#### 3. Process Flow

#### Process Flow Description

Forging & pipe Inward, Drilling, Semi Boring, M8 Drilling, Slitting, Bracket Visual Inspection, Pipe Cutting, Flaring, Center Facing, CNC Turning, Visual Inspection, Pressing, Welding, M8 Tapping, Fine Boring, M6 Tapping, Deburring, Back Chamfer, Air Cleaning, Parallelity Inspection, Final Inspection, Packing & Dispatch

#### 4. Process Details

Process / Operation	CNC Turning
Outsource	No
Machine / Cell	CNC
Machine / Cell No.	CNC

#### 5. Problem Analysis

Туре	Possible Cause	Fact Verification	Jud
Machine	Wrong Offset given	Program lock not provided	X
Method	Sampling inspection done	100 Nos checked	Х
Man	Unskilled oprator	As per skill matrix Operator in skilled	0
Tool	Tool Change frequency not Followed.	Tool change frequency followed. OK	0

#### 6. Inspection Method Analysis (Current)

Inspection Method	Gauge
Other Inspection Method	
Check Point at Final Inspection	Yes
Checking Freq.	100%
Sampling	No
Sample Size	100%

#### 7. Root Cause Analysis (Occurance)

Why 1	M22 Thread undersize
Why 2	Wrong offset given for M22 Thread Dia.
Why 3	Program lock was not present
Why 4	
Why 5	
Root Cause (Occurance)	Program lock was not provided

#### Root Cause Analysis (Outflow)

Why 1	M22 Thread undersize
Why 2	Not detected at Final Inspection
Why 3	Sampling Inspection done. 10 Per Lot
Why 4	As per control Plan frequency
Why 5	
Root Cause (Outflow)	Lack of 100% inspection

# 8. Countermeasure ( Occurrence , Outflow & System side Actions )

Туре	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Occurance	Program lock provided	Supervisor	27/06/2024	27/06/2024	Completed

# 9. Inspection Method After Customer Complaint

Change In Inspection System	Yes
Change Details	Instead of sampling inspection. 100% Inspection by Thread Ring Gauge M22-6g is started.
Inspection Method	Gauge
Other Inspection Method	
Check Point at Final Inspection	Yes
Checking Freq.	100%
Sampling	No
Sample Size	100%

### 10. Evidance of Countermeasure

Occurance (Before)	Program lock was not present 852_Occurance_Before.jpeg
Occurance (After)	Program lock provided 852_Occurance_After.jpeg
Outflow (Before)	Sampling Inspection 852_Outflow_Before.xls
Outflow (After)	100% Inspection started 852_Outflow_After.xls

# 11. Horizontal Deployment

Horizontal Deployment Required	Yes
Applicable Machine / Model / Plant	Caliber Under Bracket

### 12. Document Review

Documents	ControlPlan, InspCheckSheet
Specify Other Document	PDIR

### 13. Effectiveness Of Action

Reviewed Quantity	150
Reason for submission	ОК