

Defect Details

NC No.	8000877871
NC Date	11/06/2024
NC Submission Date	
Part No.	520HL00202
Part Name	OIL LOCK COLLAR
Supplier Name & Code	100176-GKN SINTER METALS PRIVATE LIM
ETL Plant	1117-ETL K-228/9 Suspension
Defect Details	NOT AS PER SPECIFICATION-CRACK - MATERIAL DEFECT

1. Problem Description

Defect Description	CUT MAK
Detection Stage	Inprocess
Problem Severity	Fitment
NG Quantity	5
Is Defect Repeatative?	Yes
Defect Sketch / Photo	

Supplier Communication Details

Quality Head Email ID	nitin.palve@gknp.com
Plant Head/CEO Email ID	Deepak.jadhav@gknp.com
MD Email ID	Rajesh.Mirani@gknp.com

2. Stock Details & action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
Total Qty	14000	28000	0	0	0	42000
Check Qty	14000	28000	0	0	0	42000
NG Qty	7000	12	0	0	0	7012

Action taken on NG part

Scrap	7000
Rework	0
Under Deviation	0

Containment Action

Quality Alert raised at In process area. Awareness training given to all concern stakeholders. All stock is under

3. Process Flow

Process Flow Description

Mixing-Forming-Sintering- Barreling- Steam treatment PDI

4. Process Details

Process / Operation	Forming
Outsource	No
Machine / Cell	Smal segment
Machine / Cell No.	Plant 1

5. Problem Analysis

Type	Possible Cause	Fact Verification	Jud
Man	New Operator	Operator Skill Matrix verified	O
Method	Parts fallen in rotary table due to conveyer height mismatch	Past history of concerned batch verified & Observed Excess gap creating impact on OD	X
Material	Wrong Mix	MTR	O

6. Inspection Method Analysis (Current)

Inspection Method	Other
Other Inspection Method	Sampling Inspection
Check Point at Final Inspection	No
Checking Freq.	Sampling
Sampling	No
Sample Size	5

7. Root Cause Analysis (Occurance)

Why 1	Crack Generated on OD During Forming Process
Why 2	Impact generated on part OD on Rotary table during transferring from conveyer
Why 3	Excess gap between Rotary table & Conveyer Chute end
Why 4	No Checkpoint to verify gap
Why 5	
Root Cause (Occurance)	Excess gap between Rotary table & Conveyer Chute end resulted into excess impact on part OD

Root Cause Analysis (Outflow)

Why 1	Crack Parts outflow to ETL
Why 2	Crack parts not detected during Inspection
Why 3	Inspection Frequency not adequate
Why 4	Inspection done on sampling basis
Why 5	
Root Cause (Outflow)	Inspection done on sampling basis

8. Countermeasure (Occurrence , Outflow & System side Actions)

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Outflow	Inspection Frequency Revised from 5 Parts / 4 Hours to 5 Parts/1 Hour	Rohan G	04/07/2024	22/07/2024	Completed
Occurance	Glide Path Provided between Rotary table & Conveyer Clearance to avoid Impact	Rohan Gunwant	04/07/2024	22/07/2024	Completed

9. Inspection Method After Customer Complaint

Change In Inspection System	Yes
Change Details	Inspection frequency Revised from 5/8 Hour to 5 Parts/1 hour
Inspection Method	Other
Other Inspection Method	Visual Inspection
Check Point at Final Inspection	Yes
Checking Freq.	Sampling
Sampling	No
Sample Size	10 Nos

10. Evidance of Countermeasure

Occurance (Before)	Excess Gap on Rotary Table 857_Occurance_Before.pptx
Occurance (After)	Gap Eliminated to avoid stuck up issue 857_Occurance_After.pptx
Outflow (Before)	Before Inspection Frequency 5 Parts/8 Hour 857_Outflow_Before.pdf
Outflow (After)	After Inspection Frequency 5 Parts/ 1 Hour 857_Outflow_After.pdf

11. Horizontal Deployment

Horizontal Deployment Required	No
Applicable Machine / Model / Plant	NA

12. Document Review

Documents	ControlPlan, PFMEA
Specify Other Document	NA

13. Effectiveness Of Action

Reviewed Quantity	100
Reason for submission	OK

