

## Defect Details

<b>NC No.</b>	8000880725
<b>NC Date</b>	02/07/2024
<b>NC Submission Date</b>	
<b>Part No.</b>	F2FA10933M
<b>Part Name</b>	FORK PIPE MACHINED - J1A
<b>Supplier Name &amp; Code</b>	101030-TUBE INVESTMENTS OF INDIA LTD
<b>ETL Plant</b>	1117-ETL K-228/9 Suspension
<b>Defect Details</b>	NOT AS PER SPECIFICATION-SHORT LENGTH

## 1. Problem Description

<b>Defect Description</b>	SHORT LENGTH
<b>Detection Stage</b>	Inprocess
<b>Problem Severity</b>	Fitment
<b>NG Quantity</b>	12
<b>Is Defect Repeatative?</b>	Yes
<b>Defect Sketch / Photo</b>	

## Supplier Communication Details

<b>Quality Head Email ID</b>	AmitVD@tii.murugappa.com
<b>Plant Head/CEO Email ID</b>	guptaajay@tii.murugappa.com
<b>MD Email ID</b>	mukeshahuja@tii.murugappa.com

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	2000	0	0	0	1500	3500
<b>Check Qty</b>	2000	0	0	0	1500	3500
<b>NG Qty</b>	12	0	0	0	12	24

## Action taken on NG part

<b>Scrap</b>	12
<b>Rework</b>	0
<b>Under Deviation</b>	0

## Containment Action

All Stock available at ETL end & Inhouse checked for the Threading Parameter

## 3. Process Flow

**Process Flow Description**

Raw Material Inspection- Machining (Cualking &amp; Threading)-Drilling-Oiling-Final Inspection-Dispatch

**4. Process Details**

<b>Process / Operation</b>	Machining
<b>Outsource</b>	No
<b>Machine / Cell</b>	CNC Machine Cell
<b>Machine / Cell No.</b>	Machine No.22/23 &14

**5. Problem Analysis**

Type	Possible Cause	Fact Verification	Jud
Method	No Inspection for Length Parameter	Inspection on the Sampling Basis	X
Machine	Stopper Condtion Not OK	The uneven resting surface of the stopper	X

**6. Inspection Method Analysis (Current)**

<b>Inspection Method</b>	Instrument
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	Sampling
<b>Sampling</b>	No
<b>Sample Size</b>	Sampling

**7. Root Cause Analysis (Occurance)**

<b>Why 1</b>	Total Length Observed Undersize
<b>Why 2</b>	Tube end face not resting properly on Stopper Surface
<b>Why 3</b>	The uneven resting surface of the stopper
<b>Why 4</b>	During Mass production resting surface of the stopper wears out
<b>Why 5</b>	The current Stopper, material used was MS & Not enough which caused the stopper wear out
<b>Root Cause (Occurance)</b>	The current Stopper, material used was MS & Not enough which caused the stopper wear out

**Root Cause Analysis (Outflow)**

<b>Why 1</b>	Not Detected during the Final Inspection & PDIR Why 2
<b>Why 2</b>	Inspection on the Sampling Basis
<b>Why 3</b>	No Length Inspection gauge is available for the 100 % Inspection
<b>Why 4</b>	
<b>Why 5</b>	
<b>Root Cause (Outflow)</b>	No Length Inspection gauge is available for the 100 % Inspection

**8. Countermeasure ( Occurrence , Outflow & System side Actions )**

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
------	------------------------	----------------	-------------	-------------	--------

Occurance	The Carbide material was used for the new stopper & made Properly hard ?50 to 65 HB ? & to prevent loose burr from sticking to the stopper, Also Provision was made for the coolant to come out from the stopper.	Mr. Rathod KS	03/07/2024	03/07/2024	Completed
Outflow	Length Gauge added for the 100% Inspection	Mr. Dethe SS	03/07/2024	03/07/2024	Completed

## 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	Yes
<b>Change Details</b>	Length Inspection Gauge Added for the 100 % Inspection
<b>Inspection Method</b>	Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100 %

## 10. Evidence of Countermeasure

<b>Occurance (Before)</b>	The current Stopper, material used was MS & Not enough which caused the stopper to wear out <a href="#">901_Occurance_Before.pdf</a>
<b>Occurance (After)</b>	The Carbide material was used for the new stopper & made Properly hard ?50 to 65 HB ? & to prevent loose burr from sticking to the stopper, Also Provision was made for the coolant to come out from the stopper. <a href="#">901_Occurance_After.pdf</a>
<b>Outflow (Before)</b>	Before: No 100 % Inspection on Length Gauge <a href="#">901_Outflow_Before.pdf</a>
<b>Outflow (After)</b>	After: 100 % Inspection Started by Using Length Inspection Gauge <a href="#">901_Outflow_After.pdf</a>

## 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	Yes
<b>Applicable Machine / Model / Plant</b>	All Model

## 12. Document Review

<b>Documents</b>	WISOP, InspCheckSheet
<b>Specify Other Document</b>	WI

## 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	120
<b>Reason for submission</b>	Ok