

## Defect Details

<b>NC No.</b>	8000881730
<b>NC Date</b>	08/07/2024
<b>NC Submission Date</b>	
<b>Part No.</b>	F20519007B
<b>Part Name</b>	UNDER BRACKET ASSEMBLY H107B PHASE 1
<b>Supplier Name &amp; Code</b>	100073-SINGLA FORGING (P) LTD
<b>ETL Plant</b>	1117-ETL K-228/9 Suspension
<b>Defect Details</b>	THREADING NOT OK-Step observed

## 1. Problem Description

<b>Defect Description</b>	THREADING NOT OK-Step observed
<b>Detection Stage</b>	Customer End
<b>Problem Severity</b>	Fitment
<b>NG Quantity</b>	5
<b>Is Defect Repeatative?</b>	No
<b>Defect Sketch / Photo</b>	

## Supplier Communication Details

<b>Quality Head Email ID</b>	quality@singlaforging.in
<b>Plant Head/CEO Email ID</b>	quality@singlaforging.in
<b>MD Email ID</b>	jain@singlaforging.com

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	100	500	0	0	0	600
<b>Check Qty</b>	100	500	0	0	0	600
<b>NG Qty</b>	70	370	0	0	0	440

## Action taken on NG part

<b>Scrap</b>	0
<b>Rework</b>	440
<b>Under Deviation</b>	0

## Containment Action

100% THREADING DIE ANSWER IN THE THREAD TILL THE GROOVE END ,WHICH AVAILABLE BELOW THE THREAD

## 3. Process Flow

## Process Flow Description

STEERING SHAFT PFD:- 10-RECEIPT OF MATERIAL 20-RECEIPT INSPECTION , 30-STORAGE , 40-DMC OPERATION, 50-CNC TURNING 1ST ,60-BUSH PRESSING, 70-HOLE BUSH WELDING, 80-CNC TURNING 2ND , 90-CNC TURNING 3RD, 100-CNC TURNING 4TH

## 4. Process Details

<b>Process / Operation</b>	100-CNC TURNING
<b>Outsource</b>	No
<b>Machine / Cell</b>	CNC TURNING
<b>Machine / Cell No.</b>	CNC

## 5. Problem Analysis

Type	Possible Cause	Fact Verification	Jud
Man	Unskilled operator.inspector	skill matrix	O
Machine	wrong correction in machine eprogram	thraed length 21.5 is mention in the machjine program and drawing requirement 21.5-1.0 mm	O
Method	Limitation of drawing	during verification of the drawing ,it observed that groove dia is more than the thread minor dia	X
Machine	Incomplete operation	Program completion logic is available at machine as part will not de-clamp without complete of opera	O
Machine	wrong offset	offset value locked in 0.005mm	O
Method	inspection frequecy not followed	100% inspection done by TRG	O

## 6. Inspection Method Analysis (Current)

<b>Inspection Method</b>	Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100%

## 7. Root Cause Analysis (Occurance)

<b>Why 1</b>	Matting part mot answering on the thread till the groove end
<b>Why 2</b>	Groove diameter is more than the thread minor diameter
<b>Why 3</b>	Specification given as per the drawing
<b>Why 4</b>	
<b>Why 5</b>	
<b>Root Cause (Occurance)</b>	Groove diameter is more by the thread minor diameter by which matting part not answering till groove end

## Root Cause Analysis (Outflow)

<b>Why 1</b>	Part not detected in the final inspection stage
<b>Why 2</b>	TRG gauge answering till the thread end.
<b>Why 3</b>	
<b>Why 4</b>	

<b>Why 5</b>	
<b>Root Cause (Outflow)</b>	NO

### 8. Countermeasure ( Occurrence , Outflow & System side Actions )

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Occurance	Customer drawing need to revise either for thread length or for the groove depth.	ETL	10/08/2024		Inprocess
Occurance	Thread length raised by the 1mm in the machine program by which minor diameter profile machined in the groove & gauge or matting part answer till the groove end. effective date 25.06.2024	QA	01/08/2024	01/08/2024	Completed

### 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	No
<b>Change Details</b>	No change point
<b>Inspection Method</b>	Gauge
<b>Other Inspection Method</b>	
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100

### 10. Evidance of Countermeasure

<b>Occurance (Before)</b>	Machine program in which thread length was 21.5mm <a href="#">925_Occurance_Before.jpeg</a>
<b>Occurance (After)</b>	Machine program in which thread length is 22.5mm,which is out of the drawing but meeting the customer requirement. <a href="#">925_Occurance_After.jpeg</a>
<b>Outflow (Before)</b>	TRG <a href="#">925_Outflow_Before.jpeg</a>
<b>Outflow (After)</b>	TRG <a href="#">925_Outflow_After.jpeg</a>

### 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	No
<b>Applicable Machine / Model / Plant</b>	NO

### 12. Document Review

<b>Documents</b>	Drawing, ControlPlan
<b>Specify Other Document</b>	Need revise Cust Drg

### 13. Effectiveness Of Action

Reviewed Quantity	
Reason for submission	