Defect Details

NC No.	8000886612
NC Date	12/08/2024
NC Submission Date	
Part No.	F2BZ05712B
Part Name	CAP OIL LOCK - J1D FF (10mm taper)
Supplier Name & Code	101255-MAHAVIR INDUSTRIES
ETL Plant	1117-ETL K-228/9 Suspension
Defect Details	PARALITY NOT OKPARALLISUM FOUND NOT OK.

1. Problem Description

Defect Description	Parallelism Found Not OK
Detection Stage	Receipt
Problem Severity	Fitment
NG Quantity	4
Is Defect Repeatative?	Yes
Defect Sketch / Photo	

Supplier Communication Details

Quality Head Email ID	quality@mahavirind.co.in
Plant Head/CEO Email ID	planthead@mahavirind.co.in
MD Email ID	

2. Stock Details & action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
Total Qty	340	0	0	0	0	340
Check Qty	340	0	0	0	0	340
NG Qty	4	0	0	0	0	4

Action taken on NG part

Scrap	4
Rework	0
Under Deviation	0

Containment Action

All Stages +customer End All suspected Finish Good material Verified

3. Process Flow

Process Flow Description

R/M Inward - R/M Store- Traub parting ?10.5 ID Hole - CNC Taper Turning/ ID Boring - Bottom Side Chamfer- OD Grinding- Rust preventive washing - Final Inspection - Packing- Dispatch.

4. Process Details

Process / Operation	CNC Taper Turning/ ID Boring
Outsource	Yes
Machine / Cell	CNC Section
Machine / Cell No.	CNC-2

5. Problem Analysis

Туре	Possible Cause	Fact Verification	Jud
Method	Not proper arrangement of Defective parts Handling on CNC Machine	Not Available Lock and Key Red box on CNC machine	X
Man	Unskiilled Man power	Skilled operator On CNC machine	0
Material	Hard Material	Correct Grade Material use & hardness ok	0
Machine	CNC Machine Condition Not OK	As PM plan Check sheet Condition found ok but Chuck Jaw Boring Frequency not decide.	Х
Tool	Wrong Tool use For Pilot Drill	Correct Required Tool On CNC Machine	0

6. Inspection Method Analysis (Current)

Inspection Method	Instrument
Other Inspection Method	
Check Point at Final Inspection	Yes
Checking Freq.	100%
Sampling	No
Sample Size	100%

7. Root Cause Analysis (Occurance)

Why 1	PARALITY NOT OKPARALLISUM FOUND NOT OK.
Why 2	CNC chuck jaw boring was not completed on time
Why 3	The operator is not aware of CNC jaw boring
Why 4	The frequency for jaw boring has not been decided
Why 5	
Root Cause (Occurance)	The frequency for jaw boring has not been decided

Root Cause Analysis (Outflow)

Why 1	PARALITY NOT OKPARALLISUM FOUND NOT OK.
Why 2	Defected Part By Mistake Mix By CNC operator
Why 3	Improper arrangement of defective parts stored on the CNC machine.
Why 4	
Why 5	

Root Cause (Outflow) Impro

8. Countermeasure (Occurrence , Outflow & System side Actions)

Туре	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Occurance	Define the frequency of CNC jaw boring and provide training to the operator.	Production Head	14/08/2024	14/08/2024	Completed
Outflow	Arrange the lock and key in the red box on the CNC machine.	Quality head	17/08/2024	17/08/2024	Completed

9. Inspection Method After Customer Complaint

Change In Inspection System	Yes
Change Details	100%
Inspection Method	Instrument
Other Inspection Method	
Check Point at Final Inspection	Yes
Checking Freq.	100%
Sampling	No
Sample Size	100%

10. Evidance of Countermeasure

Occurance (Before)	The frequency for jaw boring has not been decided 1006_Occurance_Before.pptx	
Occurance (After)	Define the frequency of CNC jaw boring and provide training to the operator. 1006_Occurance_After.jpg	
Outflow (Before)	Improper arrangement of defective parts stored on the CNC machine. 1006_Outflow_Before.jpg	
Outflow (After)	Arrange the lock and key in the red box on the CNC machine 1006_Outflow_After.jpg	

11. Horizontal Deployment

Horizontal Deployment Required	Yes	
Applicable Machine / Model / Plant	All Machine and all models	

12. Document Review

Documents	PFMEA, WISOP
Specify Other Document	no

13. Effectiveness Of Action

Reviewed Quantity	Re	view	ed	Quantity
-------------------	----	------	----	----------

Work instruction updated for jaw boring frequency but no revision number updated