

## Defect Details

<b>NC No.</b>	8000889507
<b>NC Date</b>	02/09/2024
<b>NC Submission Date</b>	
<b>Part No.</b>	F2FQ00307B
<b>Part Name</b>	HOLDER HANDLE LOWER P/C (XF-521)
<b>Supplier Name &amp; Code</b>	201092-PRANEEL INDUSTRIES
<b>ETL Plant</b>	1117-ETL K-228/9 Suspension
<b>Defect Details</b>	DENT MARK-DENT DAMAGE, PIN HOLE

## 1. Problem Description

<b>Defect Description</b>	DENT DAMAGE
<b>Detection Stage</b>	Receipt
<b>Problem Severity</b>	Aesthetic
<b>NG Quantity</b>	16
<b>Is Defect Repeatative?</b>	Yes
<b>Defect Sketch / Photo</b>	

## Supplier Communication Details

<b>Quality Head Email ID</b>	quality@praneelgroup.com
<b>Plant Head/CEO Email ID</b>	praneelindustries@rediffmail.com
<b>MD Email ID</b>	anilpatil@praneelgroup.com

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	350	0	0	0	200	550
<b>Check Qty</b>	350	0	0	0	200	550
<b>NG Qty</b>	27	0	0	0	30	57

## Action taken on NG part

<b>Scrap</b>	57
<b>Rework</b>	0
<b>Under Deviation</b>	0

## Containment Action

All material at ETL end and In-house sagrigation done and NG parts rejected at both location.

## 3. Process Flow

**Process Flow Description**

Raw Casting Inward=&gt;CNC Setup=&gt;Powder Coating=&gt;VMC setup=&gt;De-burring=&gt;Final Inspection=&gt;Packing and Dispatch.

**4. Process Details**

<b>Process / Operation</b>	VMC Machining
<b>Outsource</b>	No
<b>Machine / Cell</b>	VMC Machine
<b>Machine / Cell No.</b>	VMC Cell

**5. Problem Analysis**

Type	Possible Cause	Fact Verification	Jud
Machine	Clamping pressure not as per CP.	Verify clamping pressure as per CP and found OK.	O
Tool	Toolings used for part production is not as per standard.	Verify the toolings used for part production and found adequate.	O
Man	Unskilled manpower for inspection.	Verify skill matrix for inspector and found skilled person.	O
Method	Inspection method not as per standard.	Verify inspection method and found inadequate.	X
Material	Material not as per specifications.	Verify material composition and found as per specifications.	O

**6. Inspection Method Analysis (Current)**

<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	Visual Inspection
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	samp.plan

**7. Root Cause Analysis (Occurance)**

<b>Why 1</b>	Pin hole observed on the parts after powder coating.
<b>Why 2</b>	Powder used for the process contains trapped air and moisture.
<b>Why 3</b>	Degreasing bath deep time for surface cleaning is found low for cleaning the parts.
<b>Why 4</b>	
<b>Why 5</b>	
<b>Root Cause (Occurance)</b>	Degreasing bath deep time for surface cleaning is found low for cleaning the parts.

**Root Cause Analysis (Outflow)**

<b>Why 1</b>	Pin hole observed on the parts after powder coating.
<b>Why 2</b>	Skipped from final inspection stage.
<b>Why 3</b>	Final inspector was unable to identify pin hole defect properly.
<b>Why 4</b>	Due to low lux level inspector was unable to identify the pin hole issue.
<b>Why 5</b>	
<b>Root Cause (Outflow)</b>	Due to low lux level inspector was unable to identify the pin hole issue.

## 8. Countermeasure ( Occurrence , Outflow & System side Actions )

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Outflow	New high power LED tube installed at final inspection stage to increase the optimal lux level.	Mr. Yogesh Sonune	12/09/2024	12/09/2024	Completed
Occurance	Degreasing bath deep time for surface cleaning increases from 5-7 min to 7-9 min for cleaning the parts.	Mr.Dhawale	11/09/2024	12/09/2024	Completed

## 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	No
<b>Change Details</b>	---
<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	Visual Inspection
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	100%
<b>Sampling</b>	No
<b>Sample Size</b>	100%

## 10. Evidence of Countermeasure

<b>Occurance (Before)</b>	Before Degree sing bath time 5-7 min available for part cleaning process. <a href="#">1064_Occurance_Before.jpeg</a>
<b>Occurance (After)</b>	After Degree sing bath time 7-9 min done for part cleaning process. <a href="#">1064_Occurance_After.jpeg</a>
<b>Outflow (Before)</b>	Lux level on the final inspection found low for inspection and no awareness about pin hole on the parts. <a href="#">1064_Outflow_Before.pptx</a>
<b>Outflow (After)</b>	Lux level increase on the final inspection for visual inspection also awareness and training given to inspector. <a href="#">1064_Outflow_After.pptx</a>

## 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	Yes
<b>Applicable Machine / Model / Plant</b>	Handle Holder Upper

## 12. Document Review

<b>Documents</b>	WISOP
<b>Specify Other Document</b>	Q-alert, Training rec

## 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	50
<b>Reason for submission</b>	OK

