

Defect Details

NC No.	8000895939
NC Date	17/10/2024
NC Submission Date	
Part No.	F2DZ04603B
Part Name	FORK BOLT J1A & J1D
Supplier Name & Code	100189-SANGKAJ STEEL PVT LTD.
ETL Plant	1117-ETL K-228/9 Suspension
Defect Details	NOT AS PER SPECIFICATION-GROOVE WITH UNDER SIZE

1. Problem Description

Defect Description	Groove width undersize Specification: 4.5 +0.2 Observation: 2.88
Detection Stage	Inprocess
Problem Severity	Fitment
NG Quantity	1
Is Defect Repeatative?	No
Defect Sketch / Photo	

Supplier Communication Details

Quality Head Email ID	qualityassurance@sangkaj.com
Plant Head/CEO Email ID	steel@sangkaj.com
MD Email ID	anirudh.2007@hotmail.com

2. Stock Details & action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
Total Qty	288	0	0	550	300	1138
Check Qty	288	0	0	550	300	1138
NG Qty	0	0	0	0	0	0

Action taken on NG part

Scrap	0
Rework	0
Under Deviation	0

Containment Action

All the Material at Endurance & at sangkaj steel checked and no NG part Found

3. Process Flow

Process Flow Description

RM Inward and inward Inspection-Wire Drawing-Straightening-Bar Parting-CNC 1st- CNC2nd-Milling-Tapping-plating-Final Inspection-Packing & Dispatch

4. Process Details

Process / Operation	CNC turning 2nd
Outsource	Yes
Machine / Cell	CNC Machine
Machine / Cell No.	2

5. Problem Analysis

Type	Possible Cause	Fact Verification	Jud
Tool	Insert Broken	Defective piece observed with groove width undersize by 1.62mm, which occurs only after insert break	X
Man	New operator	Regular and Experienced operator Deployed for Production.	O
Material	Input Material Not OK	Cut Blanks found ok as all the blanks are cut through same bar.	O
Machine	Variation due to machine	Variation due to Machine not Causes dimension undersize by 1.62mm	O
Method	Less Sampling Size	Groove width is checked with width gauge on Sampling basis.	X

6. Inspection Method Analysis (Current)

Inspection Method	Gauge
Other Inspection Method	
Check Point at Final Inspection	Yes
Checking Freq.	Sampling
Sampling	No
Sample Size	10:100

7. Root Cause Analysis (Occurance)

Why 1	Groove Width Undersize Part Found at Customer End
Why 2	Incomplete Operation is done during Grooving.
Why 3	Insert Broken before the Set Tool Life.
Why 4	
Why 5	
Root Cause (Occurance)	Insert Broken before the Set Tool Life.

Root Cause Analysis (Outflow)

Why 1	Groove Width Undersize Part Found at Customer End
Why 2	Defective Parts Skipped from the Final Inspection
Why 3	Part Checked on Sampling basis with slip type width gauge.
Why 4	Less Sampling Size
Why 5	
Root Cause (Outflow)	Less Sampling Size during Final Inspection.

8. Countermeasure (Occurrence , Outflow & System side Actions)

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Occurance	Revalidation of Insert Life is done by varying the Process Parameters. Previous set Life was 800 No's Per Side. By Setting the Process Parameters at extreme limit of their Specification, the new Insert Life set is 700 No's.	Mr. Santosh Raut	22/10/2024	22/10/2024	Completed
Outflow	Inspection method Changed. 100% Inspection of Groove with Slip type Width Gauge is done During the Final Inspection.	Mr. A.A. Joshi	22/10/2024	22/10/2024	Completed

9. Inspection Method After Customer Complaint

Change In Inspection System	Yes
Change Details	100% inspection of Groove with Slip type Width Gauge.
Inspection Method	Gauge
Other Inspection Method	
Check Point at Final Inspection	Yes
Checking Freq.	100%
Sampling	No
Sample Size	100%

10. Evidance of Countermeasure

Occurance (Before)	Tool Life-800 Nos 1157_Occurance_Before.pptx
Occurance (After)	Tool Life -700 Nos 1157_Occurance_After.pptx
Outflow (Before)	Inspection on Sampling Basis 1157_Outflow_Before.pptx
Outflow (After)	100% Inspection with Width gauge 1157_Outflow_After.pptx

11. Horizontal Deployment

Horizontal Deployment Required	Yes
Applicable Machine / Model / Plant	Fork Bolt AABM

12. Document Review

Documents	ControlPlan, InspCheckSheet
Specify Other Document	No Other

13. Effectiveness Of Action

Reviewed Quantity	50
Reason for submission	Interlocking required for tool breakage