

## Defect Details

<b>NC No.</b>	8000896101
<b>NC Date</b>	17/10/2024
<b>NC Submission Date</b>	
<b>Part No.</b>	F2PH01202B
<b>Part Name</b>	valve retainer for K10 Ø18
<b>Supplier Name &amp; Code</b>	100161-PREMIER ENGINEERS
<b>ETL Plant</b>	1117-ETL K-228/9 Suspension
<b>Defect Details</b>	NOT AS PER SPECIFICATION-OD OVERSIZE

## 1. Problem Description

<b>Defect Description</b>	OD oversize Specification - 38.85 ±0.05 Observed - 39.074
<b>Detection Stage</b>	Inprocess
<b>Problem Severity</b>	Fitment
<b>NG Quantity</b>	5
<b>Is Defect Repeatative?</b>	No
<b>Defect Sketch / Photo</b>	

## Supplier Communication Details

<b>Quality Head Email ID</b>	quality.premier@sanghavigroup.co.in
<b>Plant Head/CEO Email ID</b>	prabhune.girish@sanghavigroup.co.in
<b>MD Email ID</b>	sanghavi.rajesh@sanghavigroup.co.in

## 2. Stock Details &amp; action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
<b>Total Qty</b>	1500	0	0	0	0	1500
<b>Check Qty</b>	1500	0	0	0	0	1500
<b>NG Qty</b>	5	0	0	0	0	5

## Action taken on NG part

<b>Scrap</b>	5
<b>Rework</b>	0
<b>Under Deviation</b>	0

## Containment Action

Available parts at Endurance send Segregated with Meting part.

## 3. Process Flow

**Process Flow Description**

Raw material+CNC+Forming and Piercing+CNC

**4. Process Details**

<b>Process / Operation</b>	CNC
<b>Outsource</b>	No
<b>Machine / Cell</b>	CNC 03
<b>Machine / Cell No.</b>	CNC Machine

**5. Problem Analysis**

Type	Possible Cause	Fact Verification	Jud
Method	Improper part Clamping	During CNC part observed improper clamping during CNC operation	X

**6. Inspection Method Analysis (Current)**

<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	Digital VC
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	Sampling
<b>Sampling</b>	No
<b>Sample Size</b>	20/100

**7. Root Cause Analysis (Occurance)**

<b>Why 1</b>	OD oversize
<b>Why 2</b>	Due to part OD ovality
<b>Why 3</b>	Due Part loading during CNC
<b>Why 4</b>	part improper clamping
<b>Why 5</b>	Operator not aware about Part ovality
<b>Root Cause (Occurance)</b>	Improper clamping of part during CNC operation.

**Root Cause Analysis (Outflow)**

<b>Why 1</b>	OD oversize
<b>Why 2</b>	part verification on sampling basis
<b>Why 3</b>	No Inspector awareness for OD oversize
<b>Why 4</b>	Awareness training provided to Inspector
<b>Why 5</b>	
<b>Root Cause (Outflow)</b>	Sampling basis OD Inspection.

**8. Countermeasure ( Occurrence , Outflow & System side Actions )**

Type	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
------	------------------------	----------------	-------------	-------------	--------

Occurance	On CNC part clamping training provided to Operator	Mr.Vilas Kamble	25/10/2024	Completed
Outflow	Sampling quantity increased Double sampling followed.	Mrs.Deshmukh	25/10/2024	Completed

## 9. Inspection Method After Customer Complaint

<b>Change In Inspection System</b>	Yes
<b>Change Details</b>	Double sampling followed
<b>Inspection Method</b>	Other
<b>Other Inspection Method</b>	20/100 part Insp
<b>Check Point at Final Inspection</b>	Yes
<b>Checking Freq.</b>	Sampling
<b>Sampling</b>	No
<b>Sample Size</b>	20/100

## 10. Evidance of Countermeasure

<b>Occurance (Before)</b>	After Set up no verification <a href="#">1166_Occurance_Before.pdf</a>
<b>Occurance (After)</b>	After Set Up verification Started. <a href="#">1166_Occurance_After.pdf</a>
<b>Outflow (Before)</b>	Sampling Basis Inspection <a href="#">1166_Outflow_Before.pdf</a>
<b>Outflow (After)</b>	Sampling frequency Increased <a href="#">1166_Outflow_After.pdf</a>

## 11. Horizontal Deployment

<b>Horizontal Deployment Required</b>	No
<b>Applicable Machine / Model / Plant</b>	CNC MACHine 02

## 12. Document Review

<b>Documents</b>	WISOP
<b>Specify Other Document</b>	One Point Lesson

## 13. Effectiveness Of Action

<b>Reviewed Quantity</b>	50
<b>Reason for submission</b>	5. Problem Analysis - Need to cover all 4M