

XF1F1 LOW HARDNESS

Action Plan

CONDITIONS FOR OCCURRENCE



• Phenomenon: LOW HARDNESS

• **Supplier:** Endurance Technologies Ltd.

Model: XF1F1

• Parts name: Front Fork

Part No.:

Date of Occurrence:06.09.2024

• **Qty NG: 40** Nos

Parts Stock check results

Action

| Area | Total Stock | Checked | Checking Method | NG Qty | Status | |
|--------------------|-------------|---------|--------------------|--------|---|--|
| Dekson Casting Ltd | 50 | 50 | By Hardness Tester | 0 | All available stock qty. verified & found NG | |
| ETL | 40 | 40 | By Hardness Tester | 240 | | |

Trouble content

| NG Part | OK Part |
|---------|---------|
| | |


UNDERSTANDING OF ACTUAL CONDITION AND CONTROL



Process Flow




Possible defect occurrence area.



UNDERSTANDING OF ACTUAL CONDITION



Understanding the actual cause – (Factor analysis)



FACTS VERIFICATION



| SR NO | 4M | PROBABLE CAUSES | FACTS VERIFICATION | Judgment |
|----------|---------|--|---|----------|
| | MAN | Less Awareness | verify Awareness of operator and found Not Ok | 0 |
| 1 | | Unskilled operator & Inspector | Verified skill level of Inspector & fond Ok as per the skill matrix | |
| | | Training not followed for New inspector and operator | Verified training record and work procedure for inadequacy while appointing new inspector and found Ok. | 0 |
| 2 | MACHINE | Fan bearing not ok Quenching tank not clean | Heat Treatment Furnance Fan bearing jam & Also Monthly cleaning tank frequency. | X |
| 2 | METHOD | temp High/low | temp check found ok | 0 |
| 3 | | Die temp variation | Die temp check found ok | 0 |

ROOT CAUSE ESTABLISHMENT

(WHY-WHY ANALYSIS)



Root cause establishment (Why-Why Analysis)

| | WHY – 1 | WHY- 2 | WHY -3 | WHY-4 | Why-5 |
|------------|----------------------------------|--|-----------------------------------|-------------------------------|-------|
| Occurrence | Hardness less than specification | Heat Treatment Furnance Fan suddenly Off &Quenching tank not clean, | Furnance Fan bearing jam | air circulation not proper | |
| Outflow | Hardness less than specification | Not detected in Inspection | Inspection done on sampling basis | - | - |

COUNTERMEASURES



| | Cause | Countermeasure | Tgt. Dt. | Status |
|--------------|---------------------------|---|------------|-----------|
| Supplier End | <occurrence></occurrence> | 1.Fan Bearing changed & its Life monitoring started. 2. Fan check point added in heat Treatment WI. 3. Water tank cleaning frequency changed to weakly. 4. Tank cleaning check point added in heat Treatment WI. | 15.09.2024 | Completed |
| Supplier End | <outflow></outflow> | Checking Hardness in every Lot after Heat Treatment. | 15.09.2024 | Completed |
| ETL End | <outflow></outflow> | Start inspection in every lot. | 15.09.2024 | Completed |

GDC



Shop: GDC

Operation: Pouring

Implementation Date: 15.09.2024

| BEFORE | AFTER |
|----------------------------|----------------------------|
| | |
| - Low Hardness - 85 BHN | - Hardness OK - 105 BHN |

