

ENGINEERING PRODUCTS FOR THE FUTURE



TUBE PRODUCTS OF INDIA SHIRWAL

41.20x36.40-ETL-PIT MARK ANALYSIS



SAMPLE DETAILS



Customer :- ETL

Size :- 41.20x36.20 x557


Reason for analysis :- Pit Mark

➤ **Date of sample received** :- 08th Oct 2024





SAMPLE PHOTOS











Observations:-

1) Pit marks observed to received samples.



MICROSTRUCTURE ANALYSIS



Sample	Micro @Pit-100x	Micro @Pit-500x	Pit location from weld	Remarks
1			Weld line	Flow lines below the defect
				Pit observed away from the weld
				Pit depth 0.071 mm
		-8.00 -8.00		Mechanical damage (Handling defect)
2			Weld line Fi	Flow lines below the defect
				Pit observed away from the weld
				Pit depth 0.268 mm
				Mechanical damage (Handling defect)
3		30 Jul.	Wold line Pii	Flow lines below the defect
				Pit observed away from the weld
				Pit depth 0.016 mm
				Mechanical damage (Handling defect)



OBSERVATIONS



Sample	Defect description	Defect location	Probable cause
1	Flow lines below the defect Pit depth 0.071 mm	Away from the weld	Mechanical damage
2	Flow lines below the defect Pit depth 0.268 mm	Away from the weld	Mechanical damage
3	Flow lines below the defect Pit depth 0.016 mm	Away from the weld	Mechanical damage





Thank you!



Contact

Corporate Office:

Tube Investments of India Ltd.
"Dare House", 234 N S C Bose Road,
Chennai- 600 001, India.

***** +91 44 42177770

4 +91 44 42110404

⊠ info@tii.murugappa.com