Defect Analysis Report

W/O- 967/0 (K19)

Part Name: Plate Clutch

Part Number: C2JT042020



Issue detail: Teeth ID not OK- Fitment Issue

Detail of defect






Fitment issue

Process Flow Chart





Containment Action detail



Component Name	Total checking	Fitment issue
PLATE CLUTCH K19	4000	1
PLATE CLUTCH K19	3800	0
PLATE CLUTCH K19	4000	1
PLATE CLUTCH K19	5700	0
PLATE CLUTCH K19	6000	0
PLATE CLUTCH K19	6000	0
PLATE CLUTCH K19	6000	0

Total Ware house stock and transit stock inspection running as per fitment part

Cause of Generation

Inter plant Material movement in bin



Possibility of material bend during transportation → After getting bend same material getting straight in next straightening operation but ovality will generate at ID and OD

Action plan:- Material will be stack in bin and loose material should not be kept over.



Possibility of material bend during transportation→ Eliminated

Cause of Outflow


50)	OILING	MANUAL	1	VISUAL DEFECTSS	CLEAN WITH RP OIL		PREE OF THICK DUITY OIL HUST BURIL ETC.	VISUAL CHECK	10 PCS	EVERY LOT	EVERY LOT	OPERATOR	OK.	
			1	ROLLER CLEARANCE			FREE OF DIRT, DIRTY OIL ETC.	VISUAL CHECK	5 PC8.	BEFORE SETUP! STARTING OF SHIFT! WHENEVER NECESSARY	PROCESS CONTROL SHEET	OPERATOR		
60	STRAIGHTENING	STRAIGHTENNIS MACHNE	2	LUBRICANT OIL LEVEL	200		AS PER OIL LEVEL INDICATOR	VISUAL CHECK		EVERY WEEK	MACHINE CHEK SHEET	MAINTANANCE	20.00	
			э	ROLLER GAP SETTING		AS PER WORK INSTRUCTION TRIAL METHOD	AS PER WORK INSTRUCTION BY TRIAL METHOD	Digil Gauge		DURING MACHINE SETUP	PROCESS CONTROL SHEET	OPERATOR		
			anorth a	d	PLATNESS (BOTH SIDE)		•	0.07	LEVER TYPE DIAL / GAP GAUGE NO: DA699/07	5 PCS	1st OFF SAMPLE & EVERY 30 MIN. INTERVAL	PROCESS CONTROL SHEET	OPERATOR	
			5 THE	THICKNESS			1.60 ± 0.05	MICROMETER, RANGE: 0 -	5 PCS	1st OFF SAMPLE		OPERATOR	1	
				-	OUTER DIAMETER		_	9 110 - 0.30	25, LC : 0.01 DIGITAL CALIPER, L.C. : 0.01	11000000	THE OFF SAMPLE		OPERATOR	4
				INNER DIAMETER OF SPLINE			⊕ 85.20 + 0.30 / 0.00	DIGITAL CALIFER, L.C. : 0.01	23555	1st OFF SAMPLE		OPERATOR		
			B	VISUAL CHECK	-00		Patern W FREE OF DENT.DAMAGE 8 ANY OTHER SURFACE DEFECT	VISUAL CHECK	8 POS.	1st OFF SAMPLE & EVERY 30 MIN.		DPERATOR		
70	GAP GAUGING	MANUAL.		FLATNESS (BOTH SIDE)		•	0.07	GAP GALIGE NO: DA/893/07	1	EVERY LOT	NO RECORD	OPERATOR	QUARANTINE THE LOT IF N	
			1		VFO SPEED		SG Hz	VISUAL CHECK	EVERY LOT	DURING SETUP & ONCE IN EVERY SHIFT		+		
			2		BELT GRADE (HEAD	0	MAKE-HERMES, TYPE-MERCURIT-RS 598Y, GRIT- 600	VISUAL CHECK	EVERY LOT	DURING SETUP & ONCE IN EVERY SHET				
			3		BELT GRADE (HEAD 2)		MAKE HERMES, TYPE MERCURIT RS 598Y, GRIT, 600	VISUAL CHECK	EVERY LOT	DURING SETUP & ONCE IN EVERY SHIFT				
			4		BELT LIFE		500 PCS (PRODUCT COUNTER- 2600 NOS)	VISUAL CHECK	EVERY LOT	DURING SETUP & ONCE IN EVERY SHET				
			П		SED GRINDING		FLATNESS-0.05 MAX	LEVER TYPE DIAL & HEIGHT	AFTER 100000 PASSES	AFTER 100000 PASSES	PROCESS CONTROL SHEET			

NO control given in control plan for bend component

Cause of Outflow

New type gauge design made and 100 % inspection started in next lot production





Why-Why Analysis- Generation



Why? Component not qualify at corresponding fitment part

Why? Component found oval

Why? Component storage by OD resting

Why? No standard defined for storage of material in bin

Action- OPL made and displayed over machine. Status- Done

Why-Why Analysis- Outflow



Why? Bend component found at customer end

Why? No inspection system defined in Control plan

Action Plan:- New type gauge need to be design and made for detection at final stage >> Status- Under process and will be implement by 8-7-2023

Temporary Action plan → 100 % inspection by mating part started at Warehouse for in transit and warehouse stock and 100% inspection started at IFB end at final stage.



Action Plan



- 1> 100 % ID checking gauge to be made for Ovality checking in component → Under process → T.Date- 7-07-2023
- 2> Component stacking system to be change from rolling to stacking > OPL to be made > Done

Action Plan







Thank you