






 <b>ENDURANCE</b> Complete Solutions Endurance Group		<b>Corrective Action Report (Supplier)</b>				Doc No. : FT-QA- 43 A Rev. No. : 00 Rev. Date : 04.08.2021 Page No. : 01 of 02				
NC No.		Part No. & Rev. No.	520PL043020/B	ETL Division	SUSPENSION					
NC Date	30.05.2024	Part Name	WASHER DF-01	ETL Plant	NARSAPURA					
NC Submission Date		Supplier Name & Code	SAPTAGIRI INDUSTRIES(100165)							
<b>1. Problem Description (To be filled by ETL)</b>										
Defect Description		THICKNESS O/S			Defect Photo / Sketch					
Detection Satge (√)		Problem Severity (√)		NG Qty						
Receipt		Safety								
Inprocess		Fitment								
Customer End	√	Function								
Warranty		Aesthetic								
Repeatative (√)		Yes	No	√						
<b>2. Stock Details &amp; action taken for NG Parts</b>		Location -->	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total		
		Total Qty	4000	0	0	1000	0	5000		
		Check Qty	4000	0	0	1000	0	5000		
		NG Qty	13 nos	0	0	0	0	13		
		Action Taken	Scrap	SRCAP	Rework		Under Deviation			
<b>2. a Containment Action : Re inspect all Pipeline ,material at Saptagiri End.</b>										
<b>3. Process Flow</b>										
<b>4. Process Details</b>		Process / Operation	Press and Plating			Outsource	Yes	√	No	√
		Machine / Cell	Press Shop	Machine / Cell No.	SI/ PS / 05					
<b>5. Problem Analysis (Fish Bone Diagram &amp; Fact Check)</b>										
		#	Possible Cause	Fact Verification	Jud					
			Punch is wear	Not	●					
			Die Punch is rust/ burr	Not	●					
			Dent damage Cavity on Material	No chance all portion of Die Is found OK	●					
			Part to part contact	No contact	●					
			Space between two parts	No metal contact	●					
			Unskill	Skill man	●					
			Not aware	Awareness is less	▲					
<b>6. Inspection Method Analysis (Current) (√)</b>										
Inspection Method	Pokayoke	Gauge	Instrument	Sp. Gauge	Other	Visual				
Check Point at FI	Yes	√	No	Checking Freq.	100%	Sampling	Sample Size			

7. Root Cause Analysis						
Occurrence	Why 1	Why 2	Why 3	Why 4	Why 5	
		Material Thickness os More	Wrong size part	Mix other part		
Root Cause (Occurrence)		Mix other part				
 Endurance Group		<b>Corrective Action Report (Supplier)</b>		Doc No. : FT-QA- 43 A	Rev. No. : 00	
				Rev. Date : 04.08.2021	Page No. : 02 of 02	
Outflow	Why 1	Why 2	Why 3	Why 4	Why 5	
	Material Thickness os More	Inpection method is visual	for visualisation sufficient Awareness required	At a time multi model packed		
Root Cause (Outflow)		At a time multi model packed				
8. Countermeasure ( Occurrence , Outflow & System side Actions ) Both, Long term and short actions to be mentioned						
#	Countermeasure Details			Resp.	Tgt Date	Status
Occurrence	Get separate the tables of Modelwise			Mr. Solankhe	21.06.2024	G
Outflow	At a time only One part Model to be Packed			Mr. Pradip	24.06.2024	G
9. Inspection Method After Customer Complaint (√)						
Change In Inspection System		Yes	No	√	Details	
Inspection Method	Pokayoke		Gauge		Instrument	Sp. Gauge
Check Point at FI	Yes	√	No		Checking Freq.	100%
					Sampling	Sample Size
10. Evidence of Countermeasure						
Occurrence	Before	After		Outflow	Before	After
						
		Get partition,				
11. Horizontal Deployment (√)						
Horizontal Deployment Required		Yes	√	No	Target Date	01.06.2024
Applicable Machine / Model / Plant						
12. Document Review (√)						
Drawing	Control Plan		PM Check Sheet	Pokayoke Check Sheet	If other, specify	
PFMEA	WI / SOP	√	JH Check Sheet	Audit Check Sheet		
Process Flow Chart	Packing Std		Insp Check Sheet			
13. Effectiveness of Action (To be monitored by ETL)						
Date					Remarks	
Qty						
Status						
Verified By						
Dhirajkumar		Mr. Nitin Wagade				
Prepared By (Supplier)		Approved By (Supplier)		Reviewed By (ETL)		
				Approved By (ETL)		