QFR No - 8000862271

Defect Details

NC No.	8000862271	
NC Date	07/02/2024	
NC Submission Date		
Part No.	520HQ00202	
Part Name	ORIFICE VALVE	
Supplier Name & Code	0141-ARVIND AUTOMOTIVE (INDIA) PVT.	
ETL Plant	1118-ETL E-92,93 Suspension	
Defect Details	NOT AS PER SPECIFICATION-WRONG MATERIAL(520HQ00502	

1. Problem Description

Defect Description	DT AS PER SPECIFICATION-WRONG MATERIAL (520HQ00502)	
Detection Stage	Receipt	
Problem Severity	Aesthetic	
NG Quantity	20000	
Is Defect Repeatative?	No	
Defect Sketch / Photo		

Supplier Communication Details

Quality Head Email ID	automotivearvind@yahoo.com	
Plant Head/CEO Email ID	automotivearvind@yahoo.com	
MD Email ID	cheemaarvind@yahoo.in	

2. Stock Details & action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
Total Qty	20000	20000	0	25000	10000	75000
Check Qty	20000	20000	0	25000	10000	75000
NG Qty	20000	0	0	0	0	20000

Action taken on NG part

Scrap	0
Rework	0
Under Deviation	20000

Containment Action

1-SHORT QTY SEND TO LOGISTICS TO MAINTAINED ACTUAL PART NUMBER AND LOT QTY ALSO 2- LOGISTICS PERSON VERIFY THE MATERIAL AS PER INVOICE NO WHICH IS ALREADY MENTION IN TAGS AND NUMBER OF BOXES ALSO

4. Process Details

Process / Operation	PUNCHING
Outsource	No
Machine / Cell	POWER PRESS
Machine / Cell No.	PP 05

5. Problem Analysis

Туре	Possible Cause	Fact Verification	Jud
Man	Unskilled helper	Operator did not aware about Tags and invoice	Х

6. Inspection Method Analysis (Current)

Inspection Method	Other
Other Inspection Method	Visual
Check Point at Final Inspection	Yes
Checking Freq.	100%
Sampling	No
Sample Size	100%

7. Root Cause Analysis (Occurance)

Why 1	Wrong parts dispatch 520HQ00502 instead of 520HQ00202
Why 2	Wrong box pic during dispatch to ETL
Why 3	Loading helper did not check box according to invoice
Why 4	Loading helper did not aware about part number and models also
Why 5	On job training not done
Root Cause (Occurance)	On job training not done

Root Cause Analysis (Outflow)

Why 1	Orfice valve 520HQ00202 NG observed at customer end
Why 2	Only sampling number of box verification done at logistics end
Why 3	box qty is not effetive to detect the problem
Why 4	Pass to customer
Why 5	
Root Cause (Outflow)	Stock details not veified

8. Countermeasure (Occurrence , Outflow & System side Actions)

Туре	Countermeasure Details	Responsibility	Target Date	Actual Date	Status
Occurance	On job training done	Amol	08/02/2024		Completed

9. Inspection Method After Customer Complaint

Change In Inspection System	No
Change Details	Daily stocks details verify share with Arvind & ETL
Inspection Method	Other
Other Inspection Method	Manual
Check Point at Final Inspection	Yes
Checking Freq.	100%
Sampling	No
Sample Size	100%

10. Evidance of Countermeasure

Occurance (Before)	Onjob training not done 674_Occurance_Before.jpeg
Occurance (After)	Onjob training not done 674_Occurance_After.jpeg
Outflow (Before)	Daily stock details not verify 674_Outflow_Before.jpg
Outflow (After)	Daily stocks details verified and shared with Arvind and ETL 674_Outflow_After.jpg

11. Horizontal Deployment

Horizontal Deployment Required	Yes
Applicable Machine / Model / Plant	Daily stock details verified for each models

12. Document Review

Documents	PackingStd
Specify Other Document	PACKING STANDARD

13. Effectiveness Of Action

Reviewed Quantity	20000
Reason for submission	Next lot material observed to be Ok as Per Invoice.