Defect Details

NC No.	8000902377
NC Date	07/12/2024
NC Submission Date	
Part No.	C2CU01300B
Part Name	RUBBER DAMPER
Supplier Name & Code	101220-MEGA RUBBER TECHNOLOGIES PVT L
ETL Plant	1135-ETL 7/10 P Nagar
Defect Details	RUBBER CAP DAMAGED-

1. Problem Description

Defect Description	Crack issue in many qty.
Detection Stage	Receipt
Problem Severity	Function
NG Quantity	621
Is Defect Repeatative?	Yes
Defect Sketch / Photo	vsvk01b0krk2im0l44511b5p.jpg

Supplier Communication Details

Quality Head Email ID	
Plant Head/CEO Email ID	
MD Email ID	

2. Stock Details & action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
Total Qty						
Check Qty						
NG Qty						

Action taken on NG part

Scrap
Rework
Under Deviation

Containment Action	

3. Process Flow

4. Process Details		
Process / Operation		
Outsource Machine / Cell		
Machine / Cell No.		
Duahlar A ! !		
5. Problem Analysis		
Type Possible Cause	Fact Verification	Jud
J. J		
5. Inspection Method A	nalysis (Current)	
Inspection Method		
Other Inspection Method		
Check Point at Final Inspection		
Checking Freq.		
Sampling		
Sample Size		
7 Doot Cours As 1 1 1	(Occurance)	
7. Root Cause Analysis ((Occurance)	
Why 1		
Why 2		
Why 3 Why 4		
Why 5		
Root Cause (Occurance)		
Root Cause Analysis (O	utflow)	
Why 1		
Why 2		
Why 3		
Why 4		
Why 5		
Root Cause (Outflow)		
3. Countermeasure (Oc	ccurrence , Outflow & System side Actions)	

Responsibility

Target Date

Type Countermeasure Details

9. Inspection Method A	fter Customer Complaint
Change In Inspection System	
Change Details	
Inspection Method	
Other Inspection Method	
Check Point at Final Inspection	
Checking Freq.	
Sampling	
Sample Size	
10. Evidance of Counter Occurance (Before) Occurance (After)	measure
Outflow (Before)	
Outflow (After)	
11. Horizontal Deploym Horizontal Deployment Required Applicable Machine / Model / Plant	
12. Document Review	
Documents	
Specify Other Document	
13. Effectiveness Of Acti	on
Reviewed Quantity	
Reason for submission	