

D5, 3rd Floor, ABC Complex, Adalat Road, Opp. Dist. Court, Chh. Sambhajinagar- 431001

## PPE'S INSPECTION CHECKLIST

Contractor: Modern Costruction

Project	:: MHDC SOLAPUR	Contractor: Modern n. Costruction					
Locatio	n: 13, 15 8. 16. Buildi	10		V John	Date: 101.6./2013 Time: 1.1		
nspecto				75			
requer	ncy: Weekly	7 1	and the start with the start condition				
	,			137.	LARPING P		
SL NO	DESCRIPTION	YES	NO	TARGET DATE	REMARKS		
A	HELMET				A breyou vel boil (1)		
1	Fastening belt in order or not.	V			Confidential Control of the Control		
2	Is there any crack on top?	~		ide di	HZIAMICHTIMES, LYTCO		
3	Is there any soil or metal?	/	,		28 12 11 23 14 24 1		
В	SHOES		1		de la company de		
1	Ensure steel toes have	~	1		anothers.		
2	Less for tying.	V					
3	No loose or crack sole.	~	Tu Mu	1/31/10	(รอกุมหากที่อว่ากรรม ค.ก.ก.		
С	HAND GLOVES			1	7		
1	Free from holes.	~	11				
2	Full protections to fingers.	~	0. 40	(KA)	MILEAFON (THE SAFE) WINCEPEDING		
3	No cuts from bottom or top.		NA A		A.P.		
D	SAFETY BELT				10.77 (A) 10 (A)		
1	Hook provision is proper or not	17	~				
2	Fastening device is working or not.						
3	Rope should be in one piece.		<u> </u>				
4	Check wear & tear of D-ring.						



D5, 3rd Floor, ABC Complex, Adalat Road, Opp. Dist. Court, Chh. Sambhajinagar- 431001

5	Check for wear & tear of belt straps.	DHE WH	~	2339	
Eit	DUST MASK		ALL:		The state of the s
1	Ensure dust mask size is adequate to protect.			· Holma	HORALD A SALES ASSESSMENT
2	Fastening strip is in good condition.		~		
F	EAR PLUG				
	Ensure softness	Q11	V		A POTTONIA
2	Tied by thread		~		TIME!
3	No dust or stains		~		an parteil in a stiff grow at the
G	GOGGLES/WELDING SHIELD				100 30 30 30 30 30
1	Free from cracks	V			
2	Dark colour glass				22012
3	Sufficient face coverage from welding spatters.	/			Town to have
			3.		The state of the s
Signatu	re: (PROJECT INCHARGE)	Jul Tue			Savo to Color
			Nation		and the second second of the
ignatu	re:( MECPL SAFETY OFFICER-EHS)	Man Man			