

Standard Operating Procedure (SOP)

- While working in company, before work can commence, properly complete all work permits, safety induction meetings, etc.
- Our motive of company for safety is use three (Safety shoes, Safety Helmet and Mask) and carry three (Hand Gloves, Safety Goggles and Ear Plugs)
- Equipment Inspection will be completed by qualified personnel.
- While working on height , insure life line or arrange life line to tie double harness safety belt.
- Establish scope of work and ensure everyone knows their specific job duties
- While doing welding work the work men should wear full welding apron.
- As before any work please complete all tools and tackles in good condition, no any tear / cutting of wire of any equipment.
- As before doing FRP work in tank area ensure proper air ventilation and use PVC hand gloves for work
- Follow all guidelines regarding work and company policy.
- Before working on site the workmen fully insured by medical insurance.
- Regular safety training provided to workmen.

for, Swagon Engineering Pvt. Ltd.



1