



TRIMASTER METROLOGY LLP

WORK PROCEDURE

S.No	Points of work procedure	Status
1	Please check the masters before service	C
2	Check all the instrument, spares and accessories	C

Status C- Complete P – Pending

